Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMNM33025


SUNDRY	INIVINIVISSU25							
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name							
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well	8. Well Name and No. HUGH LAKE 90							
Name of Operator     DUGAN PRODUCTION COR		9. API Well No. 30-045-29829-00-S1						
3a. Address 709 E MURRAY DRIVE FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505.325.1821		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,	)			11. County or Parish, State			
Sec 33 T27N R12W SWSW 8 36.526897 N Lat, 108.122866				ς.	SAN JUAN COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTHER	R DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE					DF ACTION		
Notice of Intent	☐ Acidize ☐ D		pen	☐ Producti	on (Start/Resume)	Water Shut-Off		
☐ Subsequent Report			raulic Fracturing    Reclan			Well Integrity		
	☐ Casing Repair	- The second of		☐ Recomp	_			
☐ Final Abandonment Notice			and Abandon	☐ Temporarily Abandon				
13. Describe Proposed or Completed Op-	☐ Convert to Injection ☐ Plug E			☐ Water Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Dugan Production Corp. plans to plug and abandon the well as per the following procedure:  1) Set CIBP @ 1184'. Load hole. Pressure test casing to 600 psi. Circulate 6 bbls cement to surface during primary cement job.  2) Spot inside Plug I above BP @ 1184' w/28 sx (33 cu ft) Class B w/2% CaCl2 cement to 870' (15.6#/gal, 1.18 cu ft/sk) - Fruitland, Plug I: 870'-1184'.  3) Spot Plug II below surface casing shoe @ 233' w/22 sx (26 cu ft) Class B cement w/2% CaCl2 to surface (15.6#/gal, 1.18 cu ft/sk) - Surface, Plug II: 0-233'.  4) Fill casing w/cement in case needed. Cut wellhead.  5) Install dry hole marker. Clean location.								
	Electronic Submission #4 For DUGAN PRODUC mmitted to AFMSS for prod	CTION CORP(	DRATION, sent to CK SAVAGE on 08	the Farming 3/09/2018 (18	ton JWS0172SE)			
Name (Printed/Typed) ALIPH RE	Title AGENT,	ENGINEER	RING SUPERVISOR					
Signature (Electronic S	Submission)		Date 06/15/20	)18				
	THIS SPACE FO	R FEDERA	L OR STATE (	OFFICE US	SE			
Approved By JACK SAVAGE		TitlePETROLE	ETROLEUM ENGINEER		Date 08/09/2018			
Conditions of approval, if any, are attache ertify that the applicant holds legal or equal which would entitle the applicant to condu	Office Farmington							
Citle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ke to any department or age	ncy of the United		

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



### Planned P & A Schematic

Hugh Lake # 90 30-045-29829, Basin Fruitland Coal 890 FSL & 905 FWL, NM-33025 S33 T27N R12W, San Juan County



7" 23# casing @ 127'. Cemented with 60 sks Class B. Hole size 8-3/4". 2 bbl Cement circulated to surface.

Spot plug to surface w/ 22 sks Class B Cement (26 cu.ft) (Plug II, Kirtland-Ojo Alamo-Surface, 0-233')

4 ½" 10.5 # casing @ 1412'. Hole size: 6-1/4"

Cement production casing w/ 75 sks 2% Lodense followed by 70 sks Class B. Total Cement volume, 236 cu.ft. Cement circulated to surface.


Set CIBP @ 1184'. Set Inside Plug I with 28 sks (33 cu.ft) @ 870'-1184' w/ Class B cement.(870'-1184') (Plug I, Fruitland )

Fruitland Coal Perforated @ 1234' - 1250'

PBTD @ 1340', TD 1420'

## **Current Wellbore Schematic**

Hugh Lake # 90 30-045-29829, Basin Fruitland Coal 890 FSL & 905 FWL, NM-33025 S33 T27N R12W, San Juan County



7" 23# casing @ 127'. Cemented with 60 sks Class B. Hole size 8-3/4". 2 bbl Cement circulated to surface.

4 1/2" 10.5 # casing @ 1412'. Hole size: 6-1/4"

Cement production casing w/ 75 sks 2% Lodense followed by 70 sks Class B. Total Cement volume, 236 cu.ft. Cement circulated to surface.

Fruitland Coal Perforated @ 1234' - 1250'

PBTD @ 1340', TD 1420'

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Hugh Lake 90

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a) Set Plug 2 (336 0) ft. to cover the Kirtland and Ojo Alamo tops. BLM picks top of Kirtland at 286 ft. BLM picks top of Ojo Alamo at 190 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.