

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



September 12, 2018

Hilcorp Energy Company
Attn: Jodi-Lyn Curtis
1111 Travis Street
Houston, TX 77002-7002

Re: 2017 Bradenhead Test
Well: Beaver Lodge Com #2A, UL C Sec 36 Twn 31N Rge 11W, API # 30-045-23048

Dear Ms. Curtis,

The 2017 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **December 11, 2018**. Initial Surface Casing psi was **355**. Initial Production Casing psi was 110.

Production casing did not drop while bradenhead was open. However, gas analysis shows same gas on surface casing and production casing. Five-minute shut in was **210**.

Hilcorp is directed to find the source of the gas and perform any necessary remediation.

Reference: MPK1733949600 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File