Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary

September 12, 2018

DJR Operating, LLC Attn: Amy Archuleta PO Box 156 Bloomfield, NM 87413 Heather Riley, Division Director Oil Conservation Division



Re: 2018 Bradenhead Test **Well:** Bisti Coal 31 #1, UL G Sec 31 Twn 25N Rge 12W, API # 30-045-28808

Dear Ms. Archuleta,

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **October 12, 2018,** and initiate remedial activity before **December 11, 2018.** The initial Surface Casing psi was 20. The initial Production Casing psi was 20. The five minute Surface Casing shut in pressure was 9. The production casing pressure fell while bradenhead was open indicating there is direct communication between bradenhead and production casing.

Gas analysis has been received. Gas appears to be the same on bradenhead and production casing. Please submit wellbore schematic.

Reference: RBDMS MPK1821436105 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

ouca fuchler

Monica Kuehling Deputy Oil and Gas Inspector District III - Aztec

CC: Well File