

October 8, 2018

Ms. Kate Pickford District Geologist New Mexico Oil Conservation District, District III 1000 Rio Brazos Road Aztec, NM 87410



RE: Form C-219 Exception to No Flare Rule for Nageezi 405H 406H (K03)

Dear Ms. Pickford:

Encana Services Company Ltd. (Encana) submits the attached C-129 Application for Exception to No-Flare Rule 19.15.18.12 for the Nageezi Unit 405H and 406H (KO3). Encana is requesting this exception because the wells at this facility have excess oxygen downhole and cannot meet pipeline specifications. The facility is tied into the gathering system but due to the excess oxygen the gas must be flared until the cause of the issue can be determined and solved. Please feel free to contact me if you have any questions or require additional information at 720-876-3513 or paul.buck@encana.com.

Sincerely,

Paul Buck

Manager, Field Environmental, Western Operations

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No. _______(For Division Use Only)

(For Division Use C

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)			
			NMOCD
Α.	Applicant _Encana Oil and Gas (USA) Inc	e.	OCT 1 2 2018
	whose address is _370 17th Street, Suite 1700	Denver, CO 80202,	DISTRICT III
	hereby requests an exception to Rule 19.15.18.12 From October 14, 2018 until		
	November 30_, 2018, for the following described tank battery (or LACT): Name of Lease _Nageezi 405H (K03)Name of Pool_Nageezi Unit; Mancos_ Location of Battery: Unit Letter _KSection _3Township _23N_Range _9W		
	Number of wells producing into battery _2_		
В.	Based upon oil production of	barrels per day, the estima	ited * volume
	of gas to be flared is14,000MCF; Value\$4,236per day.		
C.	Name and location of nearest gas gathering fa	acility:	
	Enterprise Bisti Compressor Station, Section	on 29 T25N R9W	
D.	Distance _~10 milesEstimated cost of connection _lt is currently connected		
E.	This exception is requested for the following reasons:		
There is excess oxygen down hole in the well. The well is currently shut in due to offset fraccing. The well will comeback on line on October 14, 2018. The O2 is high enough that the gas cannot meet pipeline specifications and the gas must be flared until Encana can determine the cause of and solve the issue.			
OPERATOR I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief. Signature		OIL CONSERVATION DIVISION	
		Approved Until	18
		By Charlettern	=
Printed Name & Title Paul Buck, Manager, Field Environmental		Title UPERVISOR DISTRIC	Т #3
E-mail Address_paul.buck@encana.com		Date 10.13.18	
Date 10/04/2018 Telephone No. 720-876-3513		PROvide GAS ANALY	is on futule Re Que
Gas-Oil ratio test may be required to verify estimated gas volume.			