State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 10/4/18

Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng W/E
30-045-20052- 00-00	HUERFANO UNIT		HILCORP ENERGY COMPANY	G		San Juan	F	0	24	26	Z	10 W

Applicat	tion Type:
	P&A Drilling/Casing Change Location Change
	Recomplete/DHC (For hydraulic fracturing operations review EPA
	lerground injection control Guidance #84; Submit Gas Capture Plan form prior to dding or initiating recompletion operations)
	Other:

Conditions of Approval:

- Notify the OCD 24hrs prior to beginning operations.
- Set cast iron bridge plug (CIBP) inside of cemented casing and at least 500' below the bottom of the proposed perforations. To show adequate formation/cement isolation.
- Perform and submit a cement bond log (CBL) to the OCD for review and approval prior to perforating the formation.
- If needed, submit proposed remediation plan to the OCD for review and approval prior to starting remediation.

NMOCD Approved by Signature

10/25/18 Date Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137

5. Lease Serial No.

Expires: July 31, 2010

SF-079942

Do not use	DRY NOTICES AND REPO this form for proposals to well. Use Form 3160-3 (A	to drill d	or to re-ent er an	au of	6 If Indiana Allottee or Tribe Na Land Management	me			
SU	BMIT IN TRIPLICATE - Other ins		7. If Unit of CA/Agreement, Name and/or No.						
1. Type of Well					Huer	fan	o Unit		
Oil Well	Gas Well Other				8. Well Name and No.				
						no l	Jnit 169		
2. Name of Operator	Hilcorp Energy Compa	iny			9. API Well No. 30-045-20052				
3a. Address			e No. (include area cod	le)	ory Area				
382 Road 3100, Aztec, N	IM 87410		505-599-3400	uerfano PC					
4. Location of Well (Footage, Sec., T., F. Surface Unit O (S	.,M., or Survey Description) WSE) 990' FSL & 1650' FE	EL, Sec.	24, T26N, R10V	V	11. Country or Parish, State San Juan ,	ı	New Mexico		
12. CHECK 1	THE APPROPRIATE BOX(ES)	TO IND	CATE NATURE C	F NO	TICE, REPORT OR OTHER	R DA	λΤΑ		
TYPE OF SUBMISSION			TYPE C	FAC	TION				
X Notice of Intent	Acidize	Deep	en	P	Production (Start/Resume)		Water Shut-Off		
	Alter Casing	Fract	ture Treat	R	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New New	Construction	XR	Recomplete		Other		
	Change Plans	Plug	and Abandon	T	Cemporarily Abandon	_			
Final Abandonment Notice	Convert to Injection	Plug	g Back Water Disposal						
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Dakota with the Pictured Cliffs. Attached is the PC C-102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds. A Closed Loop system will be utilized.									
HOLD C104 FOR DHC 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)									
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Typ	red)							
Cherylene Weston		Title Operati	ons/R	egulatory Technician - Sr	•.				

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

Title

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any



entitle the applicant to conduct operations thereon.

Approved by

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 252709

WELL LOCATION	ACREAGE	DEDICATION	ΡΙ ΔΤ

1. API Number 30-045-20052	2. Pool Code 78840	3. Pool Name HUERFANO PICTURED CLIFFS (GAS)						
4. Property Code	5. Property Name	6. Well No.						
318578	HUERFANO UNIT	169						
7. OGRID No.	8. Operator Name	9. Elevation						
372171	HILCORP ENERGY COMPANY	6564						

10. Surface Location

UL - Lot		Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	0	24	1 2	6N 10	W	990	S	1650	E	SAN JUA
	11. Bottom Hole Location If Different From Surface									
UL - Lot		Section	Township	Range	Lot Idn	Feet From	N/S Lin	e Feet From	m E/W Lin	ne County

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 160.00		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Title: Cherylene Weston, Operations/Regulatory Tech-Sr. Date: May 22, 2018
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: David Kilven Date of Survey: 1/5/1967
Certificate Number: 1760

Huerfano Unit 169

024-026N-010W-0

API: 3004520052

Pictured Cliffs Zone Add

08/28/2018

Proposed Procedure

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set with EOT at 6,545'
- 4. Set a CIBP to isolate the Dakota
- 5. Load the hole
- 6. Pressure test casing to maximum frac pressure
- 7. ND BOP's. NU frac stack and test same to maximum frac pressure
- 8. RDMO Service rig
- 9. MIRU frac spread
- 10. Perforate and frac the Pictured Cliffs from 2,050' to 2,091'. RDMO frac spread
- 11. MIRU Service rig
- 12. Test BOP's
- 13. PU mill & RIH to clean out to Dakota isolation plug
- 14. When water and sand rates are acceptable, flow test the Pictured Cliffs
- 15. Drill out Dakota isolation plug & TOOH
- 16. TIH and land production tubing. Obtain a commingled Dakota flow rate
- 17. ND BOP's, NU production tree
- 18. RDMO service rig & turn well over to production

