Form 3160-5 (August 2007)

Subsequent Report

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED	F	FORM APPROVED					
on Martin Wally Resource Co. My Litters Wash		MB	No.	1	004	-0137	
	200			147			

ON	IB No	. 10	04-	0137
Exp	oires: .	July	31,	2010

Lease	Serial	No.	
		has not	4.76

NM-03493

	SUNL	DRYNO	HCES AN	ID KEPOR	KISON	WELLS
Do	not use	this for	m for pro	posals to	drill or	to re-enter an

6. If Indian, Allottee or Tribe Name Farmington Field Office

abandoned	well. Use Form 3160-3 (A	PD) for such proposals	reau of Land Management	
SU	BMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If Unit of CA/Agreement, Na	me and/or No.
1. Type of Well			Hu	erfano Unit
Oil Well	Gas Well Other		8. Well Name and No.	
			Huerfa	no Unit 125E
2. Name of Operator			9. API Well No.	
	Hilcorp Energy Compa	iny	30-04	45-26277
Ba. Address		3b. Phone No. (include area code)	10. Field and Pool or Explorator	ry Area
382 Road 3100, Aztec, N	IM 87410	505-599-3400	Basin DK	( / Huerfano PC
4. Location of Well (Footage, Sec., T., R	,M., or Survey Description)		11. Country or Parish, State	
Surface Unit L (NV	VSW) 1800' FSL & 830' FV	VL, Sec. 30, T26N, R09W	San Juan ,	New Mexico
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE OF	ACTION	
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off

Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Fracture Treat

New Construction

Plug and Abandon

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle with the existing Dakota. Attached is the PC C-102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A Closed Loop system will be utilized.



Alter Casing

Casing Repair

Change Plans

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Reclamation

Temporarily Abandon

X Recomplete



Notify NMOCD 24 bre

Well Integrity

DISTRICT III HOLD	prior to beginning operations
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Christine Brock	Title Operations/Regulatory Technician - Sr.
Signature Unistine Brock	Date 10/5/18
THIS SPACE FOR FEDI	ERAL OR STATE OFFICE USE
Approved by Javan	Title PE Date 10 /10 /18
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which ventile the applicant to conduct operations thereon.	, , ,

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 258232

## WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-045-26277	78840	HUERFANO PICTURED CLIFFS (GAS)
4. Property Code 318578	5. Property Name HUERFANO UNIT	6. Well No. 125E
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6580


10. Surface Location

TOT CATTLEOU MODELLOTT										
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
L	30	26N	09W		1800	S	830	W		SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A 163	cres .36 SW/4		13. Joint or Infill		14. Consolidation	n Code		15. Order No.	

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



# **Huerfano Unit 125E**

030-026N-009W-L

API: 300452627700

Pictured Cliffs Zone Add

10/04/2018

## **Proposed Procedure**

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set with EOT at 6,634'
- 4. Set a CIBP @ 6,480' to isolate the Dakota. Set CIBP @ 2,200' to isolate the PC
- 5. Load the hole
- 6. Perforate the Pictured Cliffs from 2,062' to 2,083'.
- 7. When water and sand rates are acceptable, flow test the Pictured Cliffs
- 8. Drill out Dakota isolation plug & TOOH
- 9. TIH and land production tubing. Obtain a commingled Dakota-Pictured Cliffs flow rate
- 10. ND BOP's, NU production tree
- 11. RDMO service rig & turn well over to production

Page 1/1

Report Printed: 10/4/2018

www.peloton.com