Susana Martinez Governor

1

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 10/5/18 Well information:

API WELL #	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
30-045-33446-00- 00	p o Pipkin		HILCORP ENERGY COMPANY	G		San Juan	F	G	18	27	N	10	W

Application Type:

P&A		Drilling/Casi	ing Change 🗌	Location Change
Recor	nple	te/DHC (For h	vdraulic fracturing o	operations review EPA

Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)



Conditions of Approval:

- Notify NMOCD 24 Hours prior to commencing activities
- After the Pay add, this well will need a new C-104 and completion paperwork prior to production, as the perforations are outside of the existing Dakota perforations.

Grand the

NMOCD Approved by Signature

<u>10/25/18</u> Date

				RECEIVED				
Form 3160-5 (August 2007)	UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	FORM AP OMB No. Expires: Jul 5. Lease Serial No.	1004-0137 ULI 0 5 2015				
	SUNDRY NOTICES AND REPO not use this form for proposals to adoned well. Use Form 3160-3 (Al	6. If Indian, Allottee or Tribe Nan						
	SUBMIT IN TRIPLICATE - Other instr	uctions on page 2.	7. If Unit of CA/Agreement, Nam	e and/or No.				
1. Type of Well	X Gas Well Other	8. Well Name and No. P O Pipkin 6F						
2. Name of Operator	Hilcorp Energy Compar	9. API Well No. <b>30-045-33446</b>						
3a. Address	3	Bb. Phone No. (include area code)	10. Field and Pool or Exploratory Area					
382 Road 3100, A		505-599-3400	Basin Dakota					
	n, Sec., T.,R.,M., or Survey Description) hit G (SWNE) 2330' FNL & 1740' FE	EL, Sec. 18, T27N, R10W	11. Country or Parish, State <b>San Juan</b> ,	New Mexico				
12. (	CHECK THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	DTICE, REPORT OR OTHER	R DATA				
TYPE OF SUBMIS	SION	TYPE OF A	CTION					
X Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat	Production (Start/Resume) Reclamation Recomplete	Water Shut-Off Well Integrity X Other Payadd				
	Change Plans	Plug and Abandon	Temporarily Abandon	Tayadu				
Final Abandonment N	Notice Convert to Injection	Plug Back	Water Disposal					
	Company plans to add pay to the s schematic. A Closed Loop system		-	ed procedure &				
		otify NMOCD 24 hrs prior to beginning operations	NMOCD	19				
			OCT 1 5 2018					
			_DISTRICT					
14. I hereby certify that the fe	oregoing is true and correct. Name (Printed/Typed	1)						
Christine Brock		Title Operations/	Regulatory Technician - Sr					
Signature	istine Brock	Date 10/5/2018						
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Sawaz	Title	PE	Date 18/18/18				
that the applicant holds legal entitle the applicant to condu		e which would Office	FFO					
	and Title 43 U.S.C. Section 1212, make it a crime statements or representations as to any matter with		y to make to any department or agen	cy of the United States any				
(Instruction on page 2)		NMOCOPY						

## P O Pipkin 6F

T27N-R10W-S18


API: 3004533446

Dakota Payadd

10/05/2018

## **Proposed Procedure**

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set at 6,411'
- 4. Set a CIBP @ 6,410' to isolate the lower Dakota perfs.
- 5. Load the hole
- 6. Perforate and frac the Dakota from 6,120' to 6,410'.
- 7. Option to remove CIBP @ 6,410' or remain in place. Cleanout wellbore
  - a. If the plug is removed, a plug to isolate this formation may be reinstalled at a later date due to water rates
- 8. TIH and land production tubing.
- 9. ND BOP's, NU production tree
- 10. RDMO service rig & turn well over to production



A