Form 3160-5 (August 2007)

UNITED STATES ' DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 RECENEU 13 200

Expires: July 31, 2010

5. Lease Serial No. NMSF079192

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well San Juan 28-6 Unit Oil Well X Gas Well Other 8. Well Name and No. San Juan 28-6 Unit 128 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-20068 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 Blanco Mesaverde / Basin Dakota 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Unit H (SE/NE) 1800'FNL & 1150' FEL, Sec. 17 T28N, R06W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Production (Start/Resume) Water Shut-Off Deepen Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Subsequent Report Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities. BLM'S APPROVAL OR ACCEPTANCE OF THIS prior to beginning ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS SUBMIT CBL TO THE AGENCIES FOR REVIEW AND APPROVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr. Title 11/16/2018 HIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equipable title to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 260041

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-20068	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318710	SAN JUAN 28 6 UNIT	128
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6773

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
Н	17	28N	06W		1800	N	1150	E	RIO ARRIBA
									11.0

11. Bottom Hole Location If Different From Surface

The state of the s									
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00 E/2		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech Sr

Date: 11/16/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

4/3/1967

Certificate Number:

1760



HILCORP ENERGY COMPANY San Juan 28-6 Unit 128 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,888'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 6,300' to isolate the Dakota.
- 4. Load the hole run a CBL from the CIBP to Surface. Evaluate the CBL and squeeze CMT as needed.
- 5. Pressure test the casing.
- 6. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 7. Perforate and frac the Mesa Verde (Top Perforation @ 5,187'; Bottom Perforation @ 6,250').
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 8,041'. TOOH.
- 12. TIH and land production tubing.



L

HILCORP ENERGY COMPANY San Juan 28-6 Unit 128 MESA VERDE RECOMPLETION SUNDRY

