# RECEIVED

.

Form 3160-5 (August 2007)	UNITED DEPARTMENT OI BUREAU OF LANI	THE INTERIOR		FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010				
		Fa	5. Lease Serial No. Farmington Field Office NMSF078089					
	SUNDRY NOTICES AND	REPORTS ON WE	LLS -and Man	6. If Indian, Allottee or Tribe N				
	o not use this form for propo andoned well. Use Form 316							
	SUBMIT IN TRIPLICATE - O	ther instructions on page	2.	7. If Unit of CA/Agreement, N	lame and/or No.			
1. Type of Well Oil Well	X Gas Well	Other		8. Well Name and No. Scott Federal 27-11 23 1				
2. Name of Operator			9. API Well No. <b>30-045-30892</b>					
3a. Address	Hilcorp Energy C	3b. Phone No. (in	clude area code)	10. Field and Pool or Explorate	and the second			
382 Road 3100	, Aztec, NM 87410	505-	599-3400	Basin DK / West Kutz PC				
	ge, Sec., T.,R.,M., or Survey Description) Unit H (SENE) 1645'FNL & 3	60' FEL, Sec. 23, T	23, T27N, R11W 11. Country or Parish, State San Juan , New Mexico					
12.	. CHECK THE APPROPRIATE BO	X(ES) TO INDICATE	NATURE OF NO	OTICE, REPORT OR OTH	ER DATA			
TYPE OF SUBMI	SSION		TYPE OF A	CTION				
X Notice of Intent	Acidize	Deepen		Production (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Trea		Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Constru		Recomplete	Other			
Final Abandonmen	t Notice Convert to Injection	Plug and Aba		Temporarily Abandon Water Disposal				
If the proposal is to de Attach the bond under following completion Testing has been comp determined that the sit Hilcorp Energy the existing Da	Completed Operation: Clearly state all perti- sepen directionally or recomplete horizonta r which the work will be performed or prov- of the involved operations. If the operation pleted. Final Abandonment Notices must be the is ready for final inspection.) <b>A Company plans to recomplet</b> <b>A Dec 2 0 20.3</b> <b>DEC 2 0 20.3</b>	Ily, give subsurface location ide the Bond No. on file with a results in a multiple comp be filed only after all require ete the subject well Attached is the F	ns and measured and ith BLM/BIA. Requi- oletion or recompletion ements, including reco- PC C102, recorn york proceeds. BLM'S AP ACTION I OPERATO AUTHORI	true vertical depths of all pertinent red subsequent reports must be fi on in a new interval, a Form 3160- clamation, have been completed and ed Cliffs formation and nplete procedure & we	nt markers and zones. led within 30 days -4 must be filed once nd the operator has I downhole commingle ellbore schematic. The m will be utilized. TE OF THIS LESSEE AND Y OTHER			
14. I hereby certify that the	e foregoing is true and correct. Name (Prin	ted/Typed)						
Christine Broc	k	Title	Title Operations/Regulatory Technician - Sr.					
Signature UN	vistine Brock	Date	Date 11/27/18					
	THIS SPA	CE FOR FEDERAL	OR STATE OF	FICE USE				
that the applicant holds legated entitle the applicant to conc	and the second	bject lease which would	Title Office	PE PF0	Date 2/17/18			
	01 and Title 43 U.S.C. Section 1212, make at statements or representations as to any m			ly to make to any department or ag	gency of the United States any			
(Instruction on page 2)	a satements of representations as to any n		VADO		<u></u>			

District I

Form C-102 August 1, 2011

Permit 260259

#### Phone:(575) 393-6161 Fax:(575) 393-0720 <u>District II</u> 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

1625 N. French Dr., Hobbs, NM 88240

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

Phone:(505) 334-6178 Fax:(505) 334-6170 <u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

#### WELL LOCATION AND ACREAGE DEDICATION PLAT

2. Pool Code	3. Pool Name
79680	KUTZ PICTURED CLIFFS, WEST (GAS)
5. Property Name	6. Well No.
SCOTT FEDERAL 27 11 23	001
8. Operator Name	9. Elevation
HILCORP ENERGY COMPANY	6133
	79680 5. Property Name SCOTT FEDERAL 27 11 23 8. Operator Name

10. Surface Location														
UL - Lot	Section		Township		Range		Lot Idn	Feet From	N/S Line		Feet From	E/W Line	County	
F		23		27N		11W		1645		Ν	360		Ξ	SAN JUAN

11. Bottom Hole Location If Different From Surface									
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres			13. Joint or Infill		14. Consolidation Code			15. Order No.	
160.00 NE/4									

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Unisture Buck Title: Operation/Regulatory Tech Sr. Date: 11/27/2018					
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.					
Surveyed By: Roy Rush					
Date of Survey: 7/11/2001					
Certificate Number: 8894					

### Scott Federal 27-11 23 #1

#### T27N-R11W-S23

#### API: 3004530892

#### Pictured Cliffs Zone Add

### 11/26/2018

### **Proposed Procedure**

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set with EOT at 6,367'
- 4. Set a CIBP @ ±2,100' to isolate the Dakota
- 5. RDMO Service rig
- 6. MIRU frac spread
- 7. Perforate and frac the Pictured Cliffs from 1,836' to 1,939'. RDMO frac spread
- 8. MIRU Service rig
- 9. Test BOP's
- 10. PU mill & RIH to clean out to Dakota isolation plug
- 11. When water and sand rates are acceptable, flow test the Pictured Cliffs
- 12. Drill out Dakota isolation plug & TOOH
- 13. TIH and land production tubing. Obtain a commingled Dakota-Pictured Cliffs flow rate
- 14. ND BOP's, NU production tree
- 15. RDMO service rig & turn well over to production

