Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

-	-		-	-	-
3				-	3 3
× 1-	1	Sain 1	63	Sharp	dente
				1	
				- 1	

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

NMSF079193 SUNDRY NOTICES AND REPORTS ON WELLSington Field 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter and Mahagement abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well 8. Well Name and No. Other San Juan 28-6 Unit 124 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-08115 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 Blanco Mesaverde/Basin Dakota 11. Country or Parish, State 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Unit K (NESW) 1840'FSL & 1840' FWL, Sec. 22, T28N, R06W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Water Shut-Off Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction X Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities. SUBMIT CBL TO THE AGENCIES FOR REVIEW AND REVISED: Updated schematic with formation tops & proposed MV perforations. APPROVAL BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS 14. I hereby certify that the foregoing is true and correct Tammy Jones Title Operations/Regulatory Technician - Sr. 1/14/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval of any, are attached Approval of this notice does not warrant or certify

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

entitle the applicant to conduct operations thereon

that the applicant holds legal or equitable title to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 259127

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-08115	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 124
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6546


10. Surface Location

UL - Lot		Section		Township		Range		Lot Idn	Feet From		N/S Line		Feet From		E/W Line	T	County	
	K		22		28N		06W			1840		S		1840	1	W		RIO
																	ARRIBA	

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidatio	n Code	15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date:

10/29/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

7/11/1966

Certificate Number:

1760



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 124 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,798'.
- 3. Set a 4-1/2" plug at +/- 7,560' to isolate the Dakota.
- 4. RU Wireline. Run CBL. Record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform cement squeeze work.
- 6. Set a 4-1/2" plug at +/- 6,120'.
- 7. Load the hole and pressure test the casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesa Verde formation (Top Perforation @ 5,046'; Bottom Perforation @ 5,900').
- 10. Isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 13. Clean out to Dakota isolation plug.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 7,833'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



Current Schematic - Version 3

Well Name: SAN JUAN 28-6 UNIT #124

Surface Legal Location VERTICAL 3003908115 022-028N-006W-K BSN DK(PRO GAS) #0068 1303 **NEW MEXICO** KB-Casing Flange Distance (ft) KB-Tubing Hanger Distance (ft) Ground Elevation (ft) KB/RT Elevation (ft) KB-Ground Distance (ft) 6,559.00 13.00 6,546.00

