Subnat 1 Copy To Appropriate District	State of New Me	exico		Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natu	ıral Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	22.522
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-045-	
District III - (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type of Le	rase FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		6. State Oil & Gas Lea	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM			FE	
87505				
	TICES AND REPORTS ON WELLS		7. Lease Name or Uni	t Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR PL ICATION FOR PERMIT" (FORM C-101) FO		BRUINGTO	NI COM C
PROPOSALS.)			8. Well Number	ON COM C
1. Type of Well: Oil Well	Gas Well Other	-se-	8. Well Number	?
2. Name of Operator	HMOCD		9. OGRID Number	
HILCORP ENERGY COMPA	NY	010	3721	171
3. Address of Operator	JAN 03 7	2019	10. Pool name or Wild	dcat
382 Road 3100, Aztec, NM 87			Blanco Mesavero	le/Basin Dakota
4. Well Location	PISTRICT	111		
Unit Letter D	770 feet from the North line	and 495	feet from the West	line
Section 21		nge 11W	NMPM San Juan	County
Section 21	11. Elevation (Show whether DR)			County
	572			
			Alternative and administrative and an administrative and administrative administrative and administrative ad	
12 Check	Appropriate Box to Indicate N	ature of Notice	Report or Other Dat	9
12. Check	appropriate Box to maleute 14	atare of riotice	, report of other but	и
NOTICE OF IN	NTENTION TO:	SUE	SEQUENT REPOR	RT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	RK 🗌 ALT	ERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF	RILLING OPNS. P AI	ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	NT JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
	pleted operations. (Clearly state all persons) SEE BLUE 10.15.7.14 NMAA			
proposed completion or re-	ork). SEE RULE 19.15.7.14 NMAC	. For Multiple Co	ompletions: Attach wellbo	ore diagram of
proposed completion of re-	completion.			
Hilcorp Energy Company requ	ests permission to recomplete the sul	bject well in the M	esaverde and downhole co	ommingle with the
	verde. Attached is the procedure, we			
	. A closed loop system will be used.			
	HOLD COM FOR DIE			
	HOLD C104 FOR DHO Dens to a MIT will be re	sityexceptio		
ATO TIA HO N. L		1		
A 10 TA THE IJARO	ta a MIT will be re	equired.		
Spud Date:	Rig Release Da	ate:		
I hereby certify that the information	above is true and complete to the be	est of my knowled	ge and helief	
Thereby certify that the information	above is true and complete to the bo	est of my knowled;	ge and benef.	
An	M. =			
SIGNATURE PUSULA	TITLE Operat	ions Regulatory Te	echnician Sr. DATE	12/26/2018
	T sperim			
Type or print name Priscilla Sh	orty E-mail address:	pshorty@hilcorp.c	om PHONE:50	05-324-5188
For State Use Only				
	7 Deputy	Oil & Gas Ins District #3	op out	2/1/2
APPROVED BY:	TITLE	DISTRICT #3	DATE_	2/6/19
Conditions of Approval (if any):	\sim 1			

\$

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division

1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 254743

WELL LOCATION AND ACREAGE DEDICATION PLAT

	WELL EGOMINITATE MORE	EAGE DEDICATION EX
1. API Number 30-045-33532	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 319138	5. Property Name BRUINGTON GAS COM C	6. Well No. 001R
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 5722

10. Surface Location

ſ	UL - Lot	Section	Township)	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
1	D	2	1	30N	11W		770	N	495	W	SAN	JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: *Priscilla Shorty*Title: Operations Regulatory Technician - Sr.

Date: 12/26/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

John Vukonich

Date of Survey:

12/1/2005

Certificate Number:

14831



HILCORP ENERGY COMPANY BRUINGTON GAS COM C 1R MESA VERDE RECOMPLETION SUNDRY

API#:

3004533532

JOB PROCEDURES

- 1. MIRU service rig and associated equipment.
- 2. TOOH with existing downhole insert pump and rods.
- 3. NU BOP and test, TOOH with the 2 3/8" tubing set at 6,863'.
- 4. Set a 5-1/2" cast iron bridge plug at +/- 6,480' to Temporarily Abandon the Dakota formation.
- 5. Pressure test casing to frac pressure.
- 6. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 7. Perforate and frac the Mesa Verde in two or three stages. (Top perforation @ 3,800', Bottom perforation @ 4,710')
- 8. Isolate frac stages with a composite bridge plug and set top isolation plug once frac is completed.
- 9. Nipple down frac stack, nipple up BOP and test.
- 10. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 11. Clean out to the top of the Dakota TA CIBP.
- 12. Once water and sand rates are acceptable, TIH and land the production tubing. Get a Mesa Verde flow rate.
- 13. Untill futher notice, the Dakota formation will be TA'd. A future NOI will be sent if the Dakota formation is determined to be commingled with the new Mesa Verde formation for this wellbore.
 - *All formation tops have been reviewed by Hilcorp and agree with what is curently stated on the NMOCD website.
 - **All new perforations added to the wellbore for the MV formation will be verified against the approved NOI perforation intervals from this proposed procedure.



HILCORP ENERGY COMPANY BRUINGTON GAS COM C 1R MESA VERDE RECOMPLETION SUNDRY

