# State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Gabriel Wade, Acting Director Oil Conservation Division



Todd E. Leahy, JD, PhD Deputy Secretary

New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 1/17/19

Well information:

Hilcorp, Whitley #5, API# 30-045-06685

Application Type:  P&A Drilling/Casing Change Location Change
Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)
Other:
Conditions of Approval:
N 10 1 00D 011 1 1 1 1 1 1 1 1

- Notify the OCD 24hrs prior to beginning operations.
- The initial CIBP must be placed no higher than 50' above the existing perforations.
- A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
  - o 24hr notice is required to be provided to the agencies prior to performing the
- After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures.
- From the initial CIBP perform and submit a cement bond log (CBL) to the agencies for review and approval prior to perforating the formation.
- If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.

NMOCD Approved by Signature

2/21/19

Form 3160-5 (August 2007)

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

11 7 3 20 3	FORM APPROVED
	OMB No. 1004-0137
	Expires: July 31, 2010

Farmington	5. Lease Serial No
------------	--------------------

		Farn	nington	b. bease Seriatino.	
		Bureau	of Land	d Management N	IMNM02294
SUN	IDRY NOTICES AND REPO	ORTS ON WELLS		6. If Indian, Allottee or Tribe	Name
Do not use	e this form for proposals t	to drill or to re-enter a	ın		
	well. Use Form 3160-3 (A				
SL	JBMIT IN TRIPLICATE - Other ins	tructions on page 2.		7. If Unit of CA/Agreement,	Name and/or No.
1. Type of Well					
Oil Well	X Gas Well Other			8. Well Name and No.	
	and the second second			WALL TON BUILD SCHOOLSEN IN STREET FOR STATE FOR	Whitley 5
2. Name of Operator		A STATE OF THE STA		9. API Well No.	
•	Hilcorp Energy Compa	ny		30	-045-06685
3a. Address		3b. Phone No. (include area co	ode)	10. Field and Pool or Explora	atory Area
382 Road 3100, Aztec, N	NM 87410	505-599-3400		S. Blan	co PC / Basin DK
4. Location of Well (Footage, Sec., T.,R Surface Unit G (SV	R.,M., or Survey Description)  NNE), 1790' FNL & 1670' F	EL, Sec. 08, T27N, R0	9W	11. Country or Parish, State San Juan	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NO	TICE, REPORT OR OT	HER DATA
TYPE OF SUBMISSION		TYPE	OF AC	TION	
X Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	R	eclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	X R	ecomplete	Other
	Change Plans	Plug and Abandon	T	emporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	W	Vater Disposal	
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent deta	ails, including estimated starting	date of ar	ny proposed work and approxi	imate duration thereof.
	onally or recomplete horizontally, give			1 1	
Attach the hand under which the w	ork will be performed or provide the I	and No on file with DI M/DIA	Daquiro	d subsequent reports must be	filed within 20 days

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Dakota with the Pictured Cliffs. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds. A Closed Loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.



BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

HOLD CTOA FOR DIC

**		HOED OTO	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	T		
Christine Brock	Title	Operations/Regulatory Technician	
Signature Phristine Brock	Date	1/17/19	
THIS SPACE FOR FED	ERAL O	R STATE OFFICE USE	
Approved by		Title Æ	Date 2/6/19
Conditions of approval, if any, the attached Approval of this notice does not warrant or that the applicant holds legal of equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.		Office TEC	171

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 262462

### WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-045-06685	72439	BLANCO P. C. SOUTH (PRORATED GAS)
4. Property Code 318764	5. Property Name WHITLEY	6. Well No. 005
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6303

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
G	8	271	09W		1790	N	1670	E	SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A	cres .00 NE/4	L	13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

#### **OPERATOR CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered

E-Signed By: Illustine As loct Title: Operation/Regulatory Tech Sr

Date: 1/17/2019

### SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

E.L. Poteet

Date of Survey:

10/3/1960

Certificate Number:

3084

# Whitley #5

Section 8-T27N-R9W

API#: 30-045-06685

# **PC** Recompletion Procedure

1/16/2019

# Procedure:

- 1. MIRU Service rig and associated equipment, test BOP.
- 2. TOOH w/ 2 3/8" tubing set at 6649'.
- 3. Set bridge plug at approximately 2475' to isolate existing perforations.
- 4. ND BOP, NU frac stack and test frac stack to frac pressure.
- 5. Perforate and frac the Pictured Cliffs. Estimated interval: 2305'-2375'.
- 6. Cleanout to isolation plug. Flow test PC.
- 7. Cleanout to PBTD.
- 8. TIH and land production tubing. Get a commingled flow rate.
- 9. Release service rig and turn well over to production.

