State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Gabriel Wade, Acting Director Oil Conservation Division



Todd E. Leahy, JD, PhD **Deputy Secretary**

New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 1/17/19

Well information:

| Hilcorp, Jack Frost Gas Com E #1E, AP1# 30-045-25048 |
|--|
| Application Type: P&A Drilling/Casing Change Location Change |
| Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) |
| Other: |
| Conditions of Approval: |
| Notify the OCD 24hrs prior to beginning operations. |
| |

- The initial CIBP must be placed no higher than 50' above the existing perforations.
- A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
 - 24hr notice is required to be provided to the agencies prior to performing the
- After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures.
- From the initial CIBP perform and submit a cement bond log (CBL) to the agencies for review and approval prior to perforating the formation.
- If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.

NMOCD Approved by Signature

2/21/19 Date

•Form 3160-5

UNITED STATES

| AN | 23 | 2011 |
|----------|----|------|
| 6.4.00.5 | 4 | |

FORM APPROVED

| (August 2007) | DEPARTMENT OF THE BUREAU OF LAND MAN | | 20 | | o. 1004-0137 July 31, 2010 |
|--|---|--|-----------------------------------|---|-------------------------------|
| | | Farr | nington Fie | 5. Lease Serial No. | IM03198 |
| SUN | NDRY NOTICES AND REPO | ORTS ON WELLS | of Land M | 6. If Indian, Allottee or Tribe N | |
| | e this form for proposals t well. Use Form 3160-3 (A | | | | |
| | JBMIT IN TRIPLICATE - Other inst | tructions on page 2. | | 7. If Unit of CA/Agreement, Na | ame and/or No. |
| 1. Type of Well Oil Well | X Gas Well Other | | | 8. Well Name and No. | |
| 2. Name of Operator | | | | Jack Fros 9. API Well No. | st Gas Com E 1E |
| 3a. Address | Hilcorp Energy Compa | | | 30-0 | 45-25648 |
| 382 Road 3100, Aztec, I | COLUMN TO SERVICE THE SERVICE | 3b. Phone No. (include ar 505-599-3) | | 10. Field and Pool or Explorato Fulcher Ku | utz PC / Basin DK |
| 4. Location of Well (Footage, Sec., T.,F Surface Unit M (S | R.,M., or Survey Description) SWSW), 930' FSL & 790' FV | VL, Sec. 25, T27N, | R10W | 11. Country or Parish, State San Juan | New Mexico |
| 12. CHECK | THE APPROPRIATE BOX(ES) | TO INDICATE NATU | RE OF NO | TICE, REPORT OR OTHE | ER DATA |
| TYPE OF SUBMISSION | | TY | PE OF AC | TION | |
| X Notice of Intent | Acidize Alter Casing Casing Repair | Deepen Fracture Treat New Construction | R | roduction (Start/Resume) eclamation ecomplete | Water Shut-Off Well Integrity |
| Subsequent Report | Change Plans | Plug and Abandon | | ecomplete emporarily Abandon | Other |
| Final Abandonment Notice 13. Describe Proposed or Completed Op | Convert to Injection | Plug Back | | ater Disposal | |
| the existing Dakota with DHC application will be | r final inspection.) ny plans to recomplete the h the Pictured Cliffs. Attack submitted and approved be performed after surface. | ched is the PC C10 before the work p | 02, recomproceeds. | olete procedure & wel | lbore schematic. The |
| OLD C104 FOR DHC | NMOCD FEB 0 1 2019 DISTRICT III | | ACTION DO OPERATOR AUTHORIZ | ROVAL OR ACCEPTANCI DES NOT RELIEVE THE I R FROM OBTAINING ANY ATION REQUIRED FOR AL AND INDIAN LANDS | LESSEE AND OTHER |
| 14. I hereby certify that the foregoing is | true and correct. Name (Printed/Type | d) | | | |
| Christine Brock | | Title Op | erations/Ro | egulatory Technician | |
| Signature leMist | tire Brock | Date (| 117/1 | 9 | |
| | THIS SPACE FO | R FEDERAL OR S | TATE OFF | ICE USE | |
| Approved by Conditions of approvat, if any, are attack | and Approval of this notice does not u | warrant or certify | Title 5 | Z | Date 1/31/19 |
| that the applicant holds legal or equitable entitle the applicant to conduct operation | e title to those rights in the subject leas | | Office > | FFO | / / / |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources **Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

Form C-102 August 1, 2011

Permit 262460

WELL LOCATION AND ACREAGE DEDICATION PLAT

| 1. API Number | 2. Pool Code | 3. Pool Name | | | | | |
|----------------------------|--|------------------------------------|--|--|--|--|--|
| 30-045-25648 | 77200 | FULCHER KUTZ PICTURED CLIFFS (GAS) | | | | | |
| 4. Property Code 321680 | 5. Property Name JACK FROST GAS COM E | 6. Well No. 001E | | | | | |
| 7. OGRID No. 372171 | 8. Operator Name HILCORP ENERGY COMPANY | 9. Elevation 6550 | | | | | |

10. Surface Location

| UL - Lot | | Section | Townsh | ip | Range | | Lot Idn | Feet From | N/S Line | Feet From | E/W Line | County | |
|----------|---|---------|--------|-----|-------|-----|---------|-----------|----------|-----------|----------|--------|----------|
| | M | 2 | 25 | 27N | | 10W | | 930 | S | 790 | W | | SAN JUAN |

11. Bottom Hole Location If Different From Surface

| UL - Lot | Section | Township | Range | Lot Idn | Feet From | N/S Line | Feet From | E/W Line | County |
|------------------------------------|---------|---------------------|-------|------------------------|-----------|----------|---------------|----------|--------|
| 12. Dedicated Acres 160,00 SW/4 | | 13. Joint or Infill | | 14. Consolidation Code | | | 15. Order No. | | |

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-

| STANDARD ONLY III | AS BELIN AFFROVE | D BY THE DIVISION |
|--|---|---|
| | knowledge and belief, mineral interest in the this well at this locatio interest, or to a volunt by the division. | OPERATOR CERTIFICATION e information contained herein is true and complete to the best of my and that this organization either owns a working interest or unleased land including the proposed bottom hole location(s) or has a right to drill n pursuant to a contract with an owner of such a mineral or working ary pooling agreement or a compulsory pooling order heretofore entered W. Stirle Lauck gulatory Tech Sr. |
| | | SURVEYOR CERTIFICATION e well location shown on this plat was plotted from field notes of actual or under my supervision, and that the same is true and correct to the best Fred B. Kerr |
| Enterprise Control Con | Date of Survey: | 12/18/1982 |
| | Certificate Number: | 3950 |

Jack Frost Gas Com E #1E

Section 25-T27N-R10W

API#: 30-045-25648

PC Recompletion Procedure

1/16/2019

Procedure:

- 1. MIRU Service rig and associated equipment, test BOP.
- 2. TOOH w/ 2 3/8" tubing set at 6879'.
- 3. Set bridge plug at approximately 2498' to isolate existing perforations.
- 4. ND BOP, NU frac stack and test frac stack to frac pressure.
- 5. Perforate and frac the Pictured Cliffs. Estimated interval: 2325'-2398'.
- 6. Cleanout to isolation plug. Flow test PC.
- 7. Cleanout to PBTD.
- 8. TIH and land production tubing. Get a commingled flow rate.
- 9. Release service rig and turn well over to production.



Current Schematic

Well Name: JACK FROST GAS COM E #1E

| | Surface Leg at Location T27N-R10W-S25 | fied Name Basin Dakota | | | State Province New Mexic | | Well Configuration Type Vertical |
|----------------------------------|--|---------------------------|--------------------------------|----------------------|-----------------------------|-------------------|-------------------------------------|
| Ground Eleration (%) 6,550.00 | Original KS-RT Elevation (%) 6,563.00 | | x3-Grand Distance (f) 13.00 | KS-Casing Flange Dis | cance (ft) | kts-Tuting Hanger | Distance (f) |

