State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary **Gabriel Wade**, Acting Director Oil Conservation Division



Todd E. Leahy, JD, PhD Deputy Secretary

NMOCD Approved by Signature

New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 1/16/19 Well information: Hilcorp, Huerfano Unit #108E, API# 30-045-26428
Application Type: P&A Drilling/Casing Change Location Change
Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)
 Other: Conditions of Approval: Notify the OCD 24hrs prior to beginning operations. The initial CIBP must be placed no higher than 50' above the existing perforations. A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC. 24hr notice is required to be provided to the agencies prior to performing the
 MIT. After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures. From the initial CIBP perform and submit a cement bond log (CBL) to the agencies for review and approval prior to perforating the formation. If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.
Brand Dell

2/21/19

Date

UNITED STATES

FORM APPROVED

Form 3160-5	UNITED STAT					APPROVED				
(August 2007)	DEPARTMENT OF THE		IOR Farmin	OMB No. 1004-0137 Express July 31, 2010						
	BUREAU OF LAND MAI	Land	Managerno Zapares.	July 31, 2010						
			20.		J. Deade Bertai 140.	F 078014				
SU	JNDRY NOTICES AND REPO	ORTS O	N WELLS		6. If Indian, Allottee or Tribe N					
	se this form for proposals			ın						
	ed well. Use Form 3160-3 (A									
	SUBMIT IN TRIPLICATE - Other ins	tructions o	on page 2.		7. If Unit of CA/Agreement, Na	ame and/or No.				
1. Type of Well					Hı	ierfano Unit				
Oil Well	X Gas Well Other				8. Well Name and No.					
						no Unit 108E				
2. Name of Operator	Hilaara Enargy Compa				9. API Well No.	AE 20A20				
3a. Address	Hilcorp Energy Compa		No. (include area co	ide)	10. Field and Pool or Explorato	45-26428				
382 Road 3100, Aztec,	. NM 87410	Jo. 1 none	505-599-3400			/ Angel Peak GL				
4. Location of Well (Footage, Sec., T.		L			11. Country or Parish, State					
	(SWSW), 790' FSL & 1090' F	WL, Se	c. 1, T26N, R1	OW	San Juan	New Mexico				
12. CHECK	THE APPROPRIATE BOX(ES)	TO IND	CATE NATURE	OF NO	TICE, REPORT OR OTHE	ER DATA				
TYPE OF SUBMISSION			TYPE	OF AC	CTION					
X Notice of Intent	Acidize	Deep	en		Production (Start/Resume)	Water Shut-Off				
	Alter Casing	Fract	ure Treat	I	Reclamation	Well Integrity				
Subsequent Report	Casing Repair	New	Construction	X	Recomplete	Other				
	Change Plans	Plug	and Abandon		Temporarily Abandon					
Final Abandonment Notice	Convert to Injection Operation: Clearly state all pertinent deta	Plug			Water Disposal					
Attach the bond under which the following completion of the invo Testing has been completed. Fin determined that the site is ready! Hilcorp Energy Comparisation Dakota with tapplication will be sub	etionally or recomplete horizontally, give to work will be performed or provide the Bolved operations. If the operation results and Abandonment Notices must be filed of for final inspection.) any plans to recomplete the che Gallup. Attached is the bmitted and approved before reformed after surface distu	Bond No. o in a multip only after al e subject GL C10 re the w	a file with BLM/BIA le completion or reco l requirements, inclu ct well in the G 2, recomplete ork proceeds.	Required the second sec	ed subsequent reports must be file in a new interval, a Form 3160-4 amation, have been completed an formation and downholder & wellbore scher	ed within 30 days I must be filed once Id the operator has Ple commingle the natic. The DHC				

					OR ACCEPTANCE OF TH					
Server and the second second	piggittan sahara manan na aasamanagaaya jagapik pikindir (saspia tiin.				OBTAINING ANY OTHER					
	HMOCD				REQUIRED FOR OPERAT	TIONS				
			i. F.C.	1 121) INDIAN LANDS					
FEB 1 2 2019										
DIS	TRICT III									
14. I hereby certify that the foregoing	is true and correct. Name (Printed/Type	ed)								
Christine Brock			Title Opera	tions/R	Regulatory Technician					
Signature UNist	ine Brock		Date l //	6/1	19					
	THIS SPACE FO	R FEDE	RAL OR STAT	TE OF	FICE USE					
Approved by			T			/ /				

entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources Oil Conservation Division 1220 S. St Francis Dr.

Form C-102 August 1, 2011

Permit 262336

١	M	FI	1	1	0	C	Δ٦	ПС	M	Δ	N	D	Δ	C	R	F	Δ	G	F	n	F	n	10	1	T	1	A	11	PI	_	17	г
١	e w		_				~		и	Print.	14	_	p-4				P=1					•	и.	n Pri			<i>3</i> 1 7	4 1	_		4 I	4

Santa Fe, NM 87505

1. API Number 30-045-26428	2. Pool Code 2170	3. Pool Name ANGELS PEAK-GALLUP (ASSOCIATED)
4. Property Code	5. Property Name	6. Well No.
318578	HUERFANO UNIT	108E
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6629

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
M	1	26N	10W		790	S	1090	W	SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 319.61 W/2				14. Consolidatio	on Code	15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Lewistive Lewistic Title: Operation/Regulatory Tech Sr. Date: 1/15/2019
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: Fred B. Kerr Date of Survey: 4/10/1985
Certificate Number: 3950

Huerfano Unit 108E

001-026N-010W-M

API: 3004526428

Gallup Recomplete

01/14/2019

Proposed Procedure

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set with EOT at 6,821'
- 4. Set a CIBP @ 6,415' to isolate the Dakota
- 5. Load the hole
- 6. ND BOP's. NU frac stack
- 7. RDMO Service rig
- 8. MIRU frac spread
- 9. Perforate and frac the Gallup from 5,783' to 6,315'. RDMO frac spread
- 10. MIRU Service rig
- 11. Test BOP's
- 12. PU mill & RIH to clean out to Dakota isolation plug
- 13. When water and sand rates are acceptable, flow test the Gallup
- 14. Drill out Dakota isolation plug & TOOH
- 15. TIH and land production tubing. Obtain a commingled Gallup-Dakota flow rate
- 16. ND BOP's, NU production tree
- 17. RDMO service rig & turn well over to production

