## RECEIVED

Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

JAN 29 20

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELL Strmington Field Offite Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit of CA/Agreem	7. If Unit of CA/Agreement, Name and/or No.	
Type of Well			INIVIIVIVI 133462A		
⊠Oil Well	Gas Well Other		8. Well Name and No. NW Lybrook Unit #1	.33Н	
Name of Operator			9. API Well No. 30-045-35623		
a. Address		3b. Phone No. (include area co		ploratory Area	
200 Energy Court Farmington NM 87401		505-636-9743		Lybrook Unit NW HŹ	
Location of Well <i>(Footage, Sec.,</i> IL: 736' FSL & 2531' FEL SEC 3 IL: 1592' FSL & 219' FWL SEC	66 24N 8W		11. Country or Parish, St San Juan, NM	tate	
12. (	CHECK THE APPROPRIATE E	BOX(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OTHER	R DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION		
□Notice of Intent	Acidize	Deepen	Production (Start/Resume)	☐ Water ShutOff	
	☐ Alter Casing	☐ Hydraulic Fracturing	Reclamation	☐ Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	☑Other <u>No Flare</u>	
Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	Temporarily Abandon		
	Convert to Injection	☐Plug Back	☐ Water Disposal		
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed an	lly, give subsurface locations and me M/BIA. Required subsequent repor- interval, a Form 3160-4 must be file id the operator has determined that the	ts must be filed within 30 days followed once testing has been completed. Fine site is ready for final inspection.)	of any proposed work and approximate dura sertinent markers and zones. Attach the Boning completion of the involved operations. I inal Abandonment Notices must be filed on wells:	d under which the work will be perfo. If the operation results in a multiple by after all requirements, including	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed an	Illy, give subsurface locations and me LM/BIA. Required subsequent report interval, a Form 3160-4 must be filled the operator has determined that the eto the nearby Logos France (130-039-31366) [130-039-31367]	ts must be filed within 30 days followed once testing has been completed. Fine site is ready for final inspection.)	ertinent markers and zones. Attach the Boning completion of the involved operations.	d under which the work will be performed in the operation results in a multiple by after all requirements, including	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due leral 2307 7P Com #1H (AP leral 2307 7P Com #2H (AP leral 2307 7P Com #3H (AP	lly, give subsurface locations and me LM/BIA. Required subsequent repor interval, a Form 3160-4 must be filed the operator has determined that the to the nearby Logos Frank 130-039-31366) Pl 30-039-31367) Pl 30-039-31368)	easured and true vertical depths of all p ts must be filed within 30 days follow ed once testing has been completed. F the site is ready for final inspection.)	retrinent markers and zones. Attach the Boning completion of the involved operations. In all Abandonment Notices must be filed on wells:	d under which the work will be perfo.  If the operation results in a multiple by after all requirements, including  RECORD	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due level 2307 7P Com #1H (AP leval 2307 7P Com #2H (AP)	lly, give subsurface locations and me LM/BIA. Required subsequent repor interval, a Form 3160-4 must be filed the operator has determined that the to the nearby Logos Frank 130-039-31366) Pl 30-039-31367) Pl 30-039-31368)	easured and true vertical depths of all p ts must be filed within 30 days follow ed once testing has been completed. F the site is ready for final inspection.)	wells: ACCEPTED FOR  FEB 0 6 2  FARMING TO FEEL By:	d under which the work will be perfo.  If the operation results in a multiple by after all requirements, including  RECORD	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due leral 2307 7P Com #1H (AP leral 2307 7P Com #2H (AP leral 2307 7P Com #3H (AP leral 2307 7P Com #3H (AP	lly, give subsurface locations and me LM/BIA. Required subsequent repor interval, a Form 3160-4 must be filed the operator has determined that the to the nearby Logos Frank 130-039-31366) Pl 30-039-31367) Pl 30-039-31368)	tasured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. F the site is ready for final inspection.)  c activity on the following  inted/Typed)  Title: Permit S	wells: ACCEPTED FOR  FEB 0 6 2  FARMING TO FEEL By:	d under which the work will be perfo.  If the operation results in a multiple by after all requirements, including  RECORD	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due level 2307 7P Com #1H (AP level 2307 7P Com #2H (AP level 2307 7P Com #3H level 2307 7P Com #3H (AP level 2307 7P Com #3H level 23	lly, give subsurface locations and me M/BIA. Required subsequent repor interval, a Form 3160-4 must be file of the operator has determined that the eto the nearby Logos Frank (Pr. 30-039-31366) (Pr. 30-039-31367) (Pr. 30-039-31368) (Pr. 30-039-31368)	tasured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. F the site is ready for final inspection.)  c activity on the following  inted/Typed)  Title: Permit S	retrinent markers and zones. Attach the Boning completion of the involved operations. I inal Abandonment Notices must be filed on wells:  ACCEPTED FOR  FEB 0 6 20  FARMINGTON FILE  By:	d under which the work will be perfo.  If the operation results in a multiple by after all requirements, including  RECORD	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due level 2307 7P Com #1H (AP level 2307 7P Com #2H (AP level 2307 7P Com #3H level 2307 7P Com #3H (AP level 2307 7P Com #3H level 23	lly, give subsurface locations and me M/BIA. Required subsequent repor interval, a Form 3160-4 must be file of the operator has determined that the eto the nearby Logos Frank (Pr. 30-039-31366) (Pr. 30-039-31367) (Pr. 30-039-31368) (Pr. 30-039-31368)	tasured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fine site is ready for final inspection.)  C activity on the following  inted/Typed)  Title: Permit 5	retrinent markers and zones. Attach the Boning completion of the involved operations. I inal Abandonment Notices must be filed on wells:  ACCEPTED FOR  FEB 0 6 20  FARMINGTON FILE  By:	d under which the work will be perfo.  If the operation results in a multiple by after all requirements, including  RECORD	
directionally or recomplete horizontal provide the Bond No. on file with BL completion or recompletion in a new reclamation, have been completed and ring was not necessary due leral 2307 7P Com #1H (AP leral 2307 7P Com #2H (AP leral 2307 7P Com #3H (AP leral 2307 AP leral 2307 A	lly, give subsurface locations and me M/BIA. Required subsequent repor interval, a Form 3160-4 must be file of the operator has determined that the eto the nearby Logos Frank (Pr. 30-039-31366) (Pr. 30-039-31367) (Pr. 30-039-31368) (Pr. 30-039-31368)	tasured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fine site is ready for final inspection.)  C activity on the following  inted/Typed)  Title: Permit 5	retrinent markers and zones. Attach the Boning completion of the involved operations. I inal Abandonment Notices must be filed on wells:  ACCEPTED FOR  FEB 0 6 20  FARMINGTON FILE  By:	d under which the work will be perfo.  If the operation results in a multiple ly after all requirements, including  RECORD  OFFICE	

FEB 0 8 2019 DISTRICT III