Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

3	gon	0	Spare.	50	a	giffetter	to Man
R	-		-	58	ı	Sec.	9 3
10 10	Econoly	1000	Pas	18 15	7	Ross	Person

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

60.6	-	-	-	-
26.7	88		E.s.	Т
674			1.	

BUREAU OF LAND MANAGEMENT

MMUGU		5. Lease Serial No.	.00002704				
FER 1 2 2010 SUNDRY NOTICES AND REPOR	- YCX - 111 TO 11 - XX	NMSF0080379A					
Do not use this form for proposals to	and Management	Management					
abandoned well. Use Form 3160-3 (AF	PD) for such proposals.	The ring of the ri					
SUBMIT IN TRIPLICATE - Other instru	ıctions on page 2.	7. If Unit of CA/Agreement, Nan	7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well							
Oil Well X Gas Well Other		8. Well Name and No.					
2. Name of Operator		9. API Well No.	San Juan 29-6 Unit Com 601 1H				
Hilcorp Energy Compan	у	TOWN TOWN THE PRODUCTION	9-31369				
	b. Phone No. (include area code)		10. Field and Pool or Exploratory Area				
382 Road 3100, Aztec, NM 87410	505-599-3400		Basin Mancos				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	Coo O TOOM DOCK	11. Country or Parish, State	New Meries				
Surface Unit E (SWNW) 2579'FNL & 18' FWI Bottomhole Unit G (SWNE) 2374'FNL & 2379' FE		Rio Arriba ,	New Mexico				
12. CHECK THE APPROPRIATE BOX(ES) T		NOTICE REPORT OR OTHER	R DATA				
TYPE OF SUBMISSION	TYPE OF /						
Notice of Intent Acidize	Deepen	Production (Start/Resume)	Water Shut-Off				
Alter Casing	Fracture Treat	Reclamation	Well Integrity				
X Subsequent Report Casing Repair Change Plans	New Construction	Recomplete	X Other Casing &				
	Plug and Abandon	Temporarily Abandon	Cement Report				
Final Abandonment Notice Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent detail	Plug Back	Water Disposal	1 1 5				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 11/28/2018 Making up coring BHA, core bit & tools. 11/29/18 Space out inner core barrels, pump thru BHA. TIH w/core tools to 6720'. Wash to bttm, no fill. Circ bttms up. Core drill 6860' - 6890'. PUH t/5991'. Spot LCM pill & blow down lines. PUH t/1000', let core equalize. 11/30/18 TOOH L/D core barrels, recover core. TIH w/core tools & BHA. Wash & ream 6750 - 6890'. Core drill @ 6890'. 12/1/18 Core drill to 6988'. Break core, spot LCM. PUH, letting core equalize. 12/2/18 TOOH L/D core barrels, recover core. TIH w/core tools & BHA. Wash & ream 6809 - 6988'. Core drill @ 6988'. 12/3/18 Core drill to 7036'. Break core, spot LCM. PUH, letting core equalize.							
		Title Occupations The Providence Co.					
Tammy Jones	Title Operation	Title Operations/Regulatory Technician - Sr.					
Signature Tammy Smos	Date 1/25	12019					
THIS SPACE FOR	R FEDERAL OR STATE O	OFFICE USE					
Approved by	Title		Date				
Conditions of approval, if any, are attached. Approval of this notice does not we that the applicant holds legal or equitable title to those rights in the subject least	arrant or certify						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any $false, fictitious \ or \ fraudulent \ statements \ or \ representations \ as \ to \ any \ matter \ within \ its \ jurisdiction.$

entitle the applicant to conduct operations thereon.

- 12/4/18 TOOH L/D core barrels, recover core. TIH w/core tools & BHA. Wash & ream 6250 7036'. Core drill @ 7036'.
- 12/5/18 Core drill to 7194'. Break core, spot LCM. PUH, letting core equalize.
- 12/6/18 TOOH L/D core barrels, recover core. TIH w/core tools & BHA. Wash & ream 7122 7194'. Core drill @ 7194'.
- 12/7/18 Core drill to 7311'. Break core, spot LCM. PUH, letting core equalize.
- 12/8/18 TOOH L/D core barrels, recover core. TIH w/core tools & BHA. Wash & ream 7212 7311'. Core drill @ 7311'.
- 12/9/18 Core drill to 7461'. Break core, spot LCM. PUH, letting core equalize. TOOH L/D core barrels, recover core.
- 12/10/18 MU 8-3/4" bit & BHA. TIH to 7375'. Wash & ream 7375-7461'. Drill 7461 7912' TD of pilot hole.
- 12/11/18 Pump sweeps & circ hole clean. TOOH w/8-3/4" bit. RU W/L. Open hole logging Run #1. LD.
- 12/12/18 Notified BLM & NMOCD of pilot hole plug back cmt job.
- 12/13/18 Monitor hole.
- 12/14 & 15/18 TIH w/8-3/4" bit, break circ & wash fill to TD @ 7912'. Circ & condition hole.
- 12/16/18 TOOH w/8-3/4" bit. RU W/L. Attempt open hole logging Run #2, unsuccessful. LD. TIH w/2-7/8" tbg.
- 12/17/18 Tag obstruction @ 6955', unable to wash past. Notified NMOCD, will PU bit & C/O to TD. TOOH w/2-7/8" tbg.
- 12/18/18 TIH w/8-3/4" bit to 6110'. Wash & ream in hole f/6110' to TD @ 7912'. Circ hole clean. TOOH w/bit.
- **12/19/18** TIH w/4-3/4" bladed bit on 2-7/8" & 4-1/2" drill pipe. Wash dwn to 7912'. Circ hole clean. RU cmters for balanced plug. PT lines, good. Pump 325 sx of 12.5 PPG cmt slurry (374 cf 66 bbls = 1.15 yield), displace w/3 bbl spacer, 5 bbl H2O & 31 bbls drlg mud @ 9.4 PPG. PUH.
- **12/20/18** PUH to 6793'. WOC, circ no cmt returns to surface. TIH, tag cmt @ 6807'. Circ & condition. Pump 5 bbls H2O & 37 bbls 12.5 PPG spacer. Pump 385 sx of 15.8 PPG cmt slurry (447 cf 79 bbls = 1.16 yield), displace w/3 bbls H2O & 30 bbls drlg mud @ 9.4 PPG. PUH to 5500'. WOC, reverse circ no returns. TIH, tag TOC @ 6346'.
- 12/21/18 Circ & condition. Pump 5 bbls H2O, 37 bbls 12.5 PPG spacer. Pump 385 sx of 15.8 PPG cmt slurry (447 cf 79 bbls = 1.16 yield), displace w/3 bbls spacer & 27 bbls drlg mud. PUH to 5200'. WOC, circ 15 bbls cmt to surface. TIH, tag TOC @ 5511'. TOOH w/4-1/2" drill pipe & 4-3/4" bladed bit on 2-7/8" DP. Notified BLM & NMOCD of BOP Test.
- **12/22/18** PT BOP & valves, rams 250 3000#, annular 250 1500#, test good. TIH w/8-3/4" bit & BHA on 4-1/2" DP, tag cmt @ 5511'. Drill soft cmt 5511' 5857'.
- 12/23/18 Drill soft cmt 5857' 6111'. Circ hole clean @ 6088'.
- 12/24/18 Drill cmt 6111' 6390', (found harder cmt 6360' 6390'). Circ hole clean. TOOH w/8-3/4" bit & DP.
- 12/25/18 TIH w/4-3/4" blade bit & 2-7/8" cmt strg to 6390'. Circ & condition hole. Pump 2 bbl H2O & 19 bbls tuned spacer. Pump 209 sx of 17 PPG cmt slurry (209 cf 37 bbls = 1.0 yield), displace 1.25 bbl H2O & 68 bbls drlg mud. PUH to 5582'. Reverse out drill string, full returns w/10 bbls spacer & no cmt. Begin hesitate sqz, pump 3.5 bbl of 9.5 PPG mud @ 490#, bled off slow to stabilized @ 175#. WOC.

12/26/18 TIH, tag cmt @ 5931'. Circ pipe clean. TOOH w/4-3/4" blade bit & 2-7/8" cmt strg. TIH w/8-3/4" bit. Break circ & drill cmt stringers f/5819' to 5931'. Drill hard cmt f/5931' - 5960'.

12/27/18 Drlg hard cmt f/5960' - 6380'. Circ hole clean. TOOH w/4-3/4" blade bit & 2-7/8" cmt strg, MU 8-3/4" bit & DD BHA.

12/28/18 TIH w/directional BHA to 6300'. Circ & condition. Tag hard @ 6380'. Attempt to kick off cmt plug, hard cmt f/6380' - 6389' then became soft. Drlg thru soft cmt to 6700'. Plug insufficient to kick off. Circ hole clean. TOOH & L/D directional BHA.

12/29/18 TIH w/4-1/2" drill pipe to 6700'. Circ & cond. RU cmters. Pump 2 bbls H2O & 34 bbls tuned spacer. Pump 247 sx of 17 PPG cmt slurry (247 cf - 44 bbls = 1.0 yield), displace 70 bbls drlg mud. PUH to 6100'. Reverse out drill string, full returns w/27 bbls spacer & no cmt. TOOH w/4-1/2" drill pipe. WOC.

12/30/18 MU 8-3/4" bit & DD BHA. TIH w/directional BHA, tag cmt @ 6129'. Drill cmt to KOP, ratty/soft until 6217' cmt got harder. Begin time drill KOP @ 6344'. Time drill 45' = Avg 3.4'/hr to 6389'.

12/31/18 Continue drilling 8-3/4" curve section f/6389' to 6859'.

1/1/2019 Drlg 8-3/4" curve section f/6859' to 7280'.

1/2/2019 Drlg 8-3/4" curve section f/7280' to 7670'.

1/3/2019 TOOH w/BHA. Lay down directional BHA. Service rig. P/U directional tools & test. TIH w/8.5" BHA directional tools.

1/4/2019 Wash from 7400' to 7689'. Drill 8-1/2" production hole f/7689' to 10500' MD.

1/5/2019 Drill 8-1/2" production hole f/10500' to 11863' MD. Circ hole clean.

1/6/2019 Drill 8-1/2" production hole f/11863' to 11901' MD. Circ & condition. PUH to 6100'. Repair rig.

1/9/2019 Drill 8-1/2" production hole f/11901' to 12040' MD. Circ & condition. PUH to 6100'. Repair rig.

1/14/19 Drill 8-1/2" production hole f/12040' to 14500' MD. Circ & condition.

1/15/19 Drill 8-1/2" production hole f/14500' to TD @ 15081' MD on 1/15/19 @ 12:00. Circ hole clean. PUH to 13150'.

1/16/19 TOOH w/BHA. Lay down directional tools. PU 5-1/2" casing, stage in hole. Notified BLM & NMOCD of cmt job.

1/17/19 Run 332 jts 5-1/2" 20# P-110 BTC casing, set shoe @ 15070' MD, FC @ 15021', Toe Sleeve @ 14972', 14923' & 14874', Mkr Jt @ 11155'. RU cmters, test lines to 5000#.

1/18/19 Pump 10 bbls H2O & 60 bbls tuned spacer. Pump 2294 sx Premium TM Cmt w/0.3% Super CBL, 13.3 PPG slurry (3120 cf - 555 bbls = 1.36 yld). Displace w/332 bbls 2% KCL. Bump plug @ 2000 psi. WOC. ND BOP. NU WH. RD. Rig released.

1/21/19 NU frac stack, PT to 9500#, ok. RU W/L. Run CBL f/7540' to 5000'. RD W/L. TOC @ 6110'. Verbal CBL approval from Brandon Powell, NMOCD & notified BLM.

1/23/19 PT 5-1/2" csg to 1500#/30 mins, test good (chart attached). RU frac crew. U

Completion will be on next report.

CONFIDENTIAL

CONFIDENTIAL

