### State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor Sarah Cottrell Propst Adrienne Sandoval, Division Director Cabinet Secretary Oil Conservation Division Todd E. Leahy, JD, PhD Deputy Secretary New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form. Operator Signature Date: 3/11/2019 Well information: HILCORP ENERGY COMPANY 30-039-21517 Jicarilla B #9 **Application Type:** ☐ Drilling/Casing Change ☐ Location Change P&A Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84: Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other: Conditions of Approval: Notify the OCD 24hrs prior to beginning operations. Hold the C-104 for the DHC. The initial CIBP must be placed no higher than 50' above the existing perforations. Submit the CBL to the agencies for review and approval prior to perforating. A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC. o 24hr notice is required to be provided to the agencies prior to performing the MIT. After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures. If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.

NMOCD Approved by Signature

4/22/19 Date

### RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT MAR 1 2 2019

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

			-leid S. Lease Serial No.				
		Management (	Contract 106				
SUN	IDRY NOTICES AND REP	6. If Indian, Allottee or Trib	be Name				
Do not us	e this form for proposals						
abandoned	well. Use Form 3160-3 (	i. Ji	Jicarilla Apache				
SU	IBMIT IN TRIPLICATE - Other in	nstructions on page 2.	7. If Unit of CA/Agreement	t, Name and/or No.			
1. Type of Well							
Oil Well	X Gas Well Other		8. Well Name and No.	Jicarilla B 9			
2. Name of Operator	Hilaam Francis Cama		Section 201 Authorities (Section 2017)	9. API Well No.			
3a. Address	Hilcorp Energy Comp	3b. Phone No. (include area code		30-039-21517			
382 Road 3100, Aztec, N	JM 87410	505-599-3400		0. Field and Pool or Exploratory Area  Tapacito Pictured Cliffs /Blanco MV  1. Country or Parish, State  Rio Arriba , New Mexico			
4. Location of Well (Footage, Sec., T., I		303-333-3400					
		FWL, Sec. 26, T26N, R04V					
omer (m		112, 000, 20, 12011, 11011	Tuo 7 ii Tibu	, non monoc			
12. CHECK	THE APPROPRIATE BOX(ES	S) TO INDICATE NATURE OF	F NOTICE, REPORT OR OT	HER DATA			
TYPE OF SUBMISSION		FACTION					
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other			
	Change Plans	Plug and Abandon	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent d	letails, including estimated starting d	late of any proposed work and appr	oximate duration thereof.			
		ve subsurface locations and measure					
		e Bond No. on file with BLM/BIA.					
		Its in a multiple completion or recond only after all requirements, including					
determined that the site is ready fo		d only after an requirements, meradi	ing reciamation, have been complete	ed and the operator has			
Hilcorp Energy Compar	ny plans to recomplete th	ne subject well in the Pict	tured Cliffs formation an	id downhole commingle			
the existing Mesaverde	. Attached is the PC C10	2, recomplete procedure	& wellbore schematic.	The DHC application will			
he submitted and appro	yed prior to commingling	a A closed loop system	will be utilized Interim	reclamation will be			

be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.

HOLD CTON FOR DIKC



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Etta Trujillo	Title	Operations/I	Regulatory Technician -	Sr.
Signature EHa Trifullo	Date		3/11/201	9
THIS SPACE FOR FEE	ERAL C	R STATE OF	FICE USE	
Approved by  Dave Mankiewicz		M Title	ATU	Date 4/5 /19
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.	or certify	Office	FFO	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III** 

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### State of New Mexico **Energy, Minerals and Natural** Resources Oil Conservation Division

1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 263963



#### WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-21517	2. Pool Code 85920	3. Pool Name TAPACITO PICTURED CLIFFS (PRO GAS)
4. Property Code 319688	5. Property Name JICARILLA B	6. Well No. 009
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6950

#### 10. Surface Location

Г	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	K	26	26N	04W		1835	S	1675	W	RIO ARRIBA
										1110 7 11

#### 11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 160.00 W/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OTTAINE CITE TIME BELLIT
	I hereby c
	knowledge mineral ini this well a
	interest, or by the divi
	E-Signed
57 22 32 42 77 32 78	Title:
	Date:
	surveys m of my belie
	Surveyed
	Date of Su

#### **OPERATOR CERTIFICATION**

ertify that the information contained herein is true and complete to the best of my and belief, and that this organization either owns a working interest or unleased erest in the land including the proposed bottom hole location(s) or has a right to drill this location pursuant to a contract with an owner of such a mineral or working to a voluntary pooling agreement or a compulsory pooling order heretofore entered

By: Etta Trujillo

Operations/Regulatory Tech Sr

04/09/2019

#### SURVEYOR CERTIFICATION

ertify that the well location shown on this plat was plotted from field notes of actual ade by me or under my supervision, and that the same is true and correct to the best

Зу:

James P. Leese

rvey:

10/11/1977

Certificate Number:

1463



# HILCORP ENERGY COMPANY JICARILLA B 9 PICTURED CLIFFS RECOMPLETION SUNDRY

#### JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-1/16" tubing set at 5,642'.
- 3. Set a 4-1/2" plug at +/- 4,000' to isolate the Mesaverde.
- 4. RU Wireline. Run CBL and record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform squeeze work.
- 6. Load the hole and pressure test the casing.
- 7. N/D BOP, N/U frac stack and pressure test frac stack.
- 8. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,544'; Bottom Perforation @ 3,609').
- 9. Isolate frac stage with a plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out top Pictured Cliffs Isolation plug.
- 12. Clean out to Mesaverde isolation plug.
- 13. Drill out Mesaverde isolation plug and cleanout to PBTD of 5,786'. TOOH.
- 14. TIH and land production tubing. Get a commingled Mesaverde/Pictured Cliffs flow rate.



## HILCORP ENERGY COMPANY JICARILLA B 9 PICTURED CLIFFS RECOMPLETION SUNDRY

