State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary

Adrienne Sandoval, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 2/20/2019

Well information:

HILCORP ENERGY COMPANY 30-039-29376 San Juan 27-4 Unit #102N

Aŗ	pplication Type: P&A Drilling/Casing Change Location Change
	Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)
	Other:
_	

Conditions of Approval:

- Notify the OCD 24hrs prior to beginning operations.
- Hold the C-104 for the DHC.
- The initial CIBP must be placed no higher than 50' above the existing perforations.
- Submit the CBL to the agencies for review and approval prior to perforating.
- A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity
 of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
 - o 24hr notice is required to be provided to the agencies prior to performing the MIT.
- After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures.
- If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.

NMOCD Approved by Signature

4/22/19 Date

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

. *					RECO			
Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG			OMB No. Expires: Ju	PPROVED 1004-0137 25 20 10 10 10 10 10 10 10 10 10 10 10 10 10			
				5. Lease Serial No. NMS	F080675/ 7 A			
Do not use	DRY NOTICES AND REPORT this form for proposals to d well. Use Form 3160-3 (APD)	Irill or to re-enter a		6. If Indian, Allottee or Tribe Name				
	BMIT IN TRIPLICATE - Other instruct	tions on page 2.		7. If Unit of CA/Agreement, Nan	ne and/or No.			
	Gas Well Other				27-4 Unit 102N			
2. Name of Operator	Hilcorp Energy Company			9. API Well No. 30-03	9-29376			
3a. Address	3b.	Phone No. (include area co	de)	10. Field and Pool or Explorator	y Area			
382 Road 3100, Aztec, N 4. Location of Well (Footage, Sec., T.,F		505-599-3400		11. Country or Parish, State	lanco MV/Basin DK			
	ENE) 2390' FNL & 460' FEL,	Sec. 33, T27N, R04	W	Rio Arriba ,	New Mexico			
	THE APPROPRIATE BOX(ES) TO	INDICATE NATURE	OF NO	TICE, REPORT OR OTHER	R DATA			
TYPE OF SUBMISSION		TYPE	OF AC	TION				
X Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	R X R	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon	Water Shut-Off Well Integrity Other			
Final Abandonment Notice 13. Describe Proposed or Completed Op	Convert to Injection peration: Clearly state all pertinent details,	Plug Back including estimated startin		Vater Disposal any proposed work and approxima	ate duration thereof.			
If the proposal is to deepen direction Attach the bond under which the was following completion of the involve	onally or recomplete horizontally, give sub- york will be performed or provide the Bond ed operations. If the operation results in a Abandonment Notices must be filed only	surface locations and meas d No. on file with BLM/BLA a multiple completion or rec	ured and to A. Require ompletion	true vertical depths of all pertinen red subsequent reports must be fil n in a new interval, a Form 3160-4	it markers and zones. ed within 30 days 4 must be filed once			
the existing Mesaverde application will be subn	ny plans to recomplete the su and Dakota. Attached is the nitted and approved prior to o formed after surface disturbin	PC C102, recompl commingling. A clo	ete pro	ocedure & wellbore sch	ematic. The DHC			
		The state of the s	KMOC					
n C1	M FOR DHO			2019				
HOLD		DIST	PICT	111				
14. I hereby certify that the foregoing is	strue and correct. Name (Printed/Typed)							
Etta Trujillo		Title Opera	tions/R	egulatory Technician - Si	r			
Signature Signature	atesto	Date	2/22/2019					
	THIS SPACE FOR F	FEDERAL OR STAT	TE OFF	FICE USE				
Approved by Conditions of approval if any are affective.	Min Leo Co- hed. Approval of this notice does not war		tle	4t-M	Date 3/14/19			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

Office

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 263908

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-29376	85920	TAPACITO PICTURED CLIFFS (PRO GAS)
4. Property Code	5. Property Name	6. Well No.
319210	SAN JUAN 27 4 UNIT	102N
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	7185


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	1
н	33	27N	04W		2390	N	460	E	RIO ARRIBA	ı
1								· ·		Т

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
	12. Dedicated Acres 320.00 E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trufillo

Title:

Operations/Regulatory Tech

Date:

02/21/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Jason C. Edwards

Date of Survey:

7/15/2004

Certificate Number:

15269



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 102N PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-3/8" tubing set at 8,296'.
- 3. Set a 4-1/2" plug at +/- 4,350' to isolate the Mesaverde and Dakota formations.
- 4. RU Wireline- Run CBL and record Top of Cement
- 5. IF NECESSARY (Based on results of the CBL) Preform cement squeeze work.
- 6. Load the hole and pressure test the casing.
- 7. N/D BOP, N/U frac stack and pressure test frac stack.
- 8. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,998; Bottom Perforation @ 4,084).
- 9. Isolate frac stage with a plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 12. Clean out to Mesaverde and Dakota formations isolation plug.
- 13. Drill out Mesaverde and Dakota formations isolation plug and cleanout to PBTD of 8,400'. TOOH.
- 14. TiH and land production tubing. Get a commingled Dakota/Mesaverde/Pictured Cliffs flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 102N PICTURED CLIFFS RECOMPLETION SUNDRY

