Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

APR 08 2019

FORM APPROVED OMB No. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. N0-G-1312-1807

SUNDRY NOTICES AND REPORTS ON WELL'S ton Field Office 6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill of to re-enter an anagement

abandoneu w	ell. Use Form 3160-3 (A				
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit of CA/Agreem NMNM135218A	7. If Unit of CA/Agreement, Name and/or No. NMNM135218A	
1. Type of Well			8. Well Name and No.		
⊠Oil Well	Gas Well Other		W Escavada Unit 302H	I	
2. Name of Operator			9. API Well No. 30-043-21305		
Enduring Resources Iv LLC 3a. Address 200 Energy Court Farmington NM 87402 4. Location of Well (Footage, Sec., T.,R,M., or Survey Description) SHL: 235' FSL & 208' FEL, Sec 17, T22N, R7W BHL: 2269' FSL & 797' FEL, Sec 7 T22N, R7W		3b. Phone No. (include area cod		10. Field and Pool or Exploratory Area Escavada W; Mancos 11. Country or Parish, State Sandoval, NM	
		505-636-9743			
12.	CHECK THE APPROPRIATE I	BOX(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OTHER	R DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION		
□Notice of Intent	Acidize	Deepen	☐Production (Start/Resume)	☐ Water ShutOff	
	☐ Alter Casing	☐ Hydraulic Fracturing	Reclamation	■Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other Covert from ESP to	
	☐Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	GLV	
Final Abandonment Notice	Convert to Injection	□Plug Back	☐Water Disposal		
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a new	tally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be file	easured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fi	of any proposed work and approximate dura ertinent markers and zones. Attach the Bon ing completion of the involved operations.	d under which the work will be perfonned of If the operation results in a multiple	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.)	tally, give subsurface locations and me BLM/BIA. Required subsequent repor	easured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fi	ertinent markers and zones. Attach the Boning completion of the involved operations.	d under which the work will be perfonned of If the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.) /27/19- MIRU	tally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be file and the operator has detennined that the	easured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fi	nertinent markers and zones. Attach the Boning completion of the involved operations. in al Abandonment Notices must be filed on the involved operations.	d under which the work will be performed of the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ne- reclamation, have been completed a	tally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has detennined that the properties of the properties of the Pull ESP.	easured and true vertical depths of all p ts must be filed within 30 days follow ed once testing has been completed. Fi he site	ertinent markers and zones. Attach the Boning completion of the involved operations. inal Abandonment Notices must be filed on	d under which the work will be perfonned of If the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.) /27/19- MIRU /28/19 thru 3/31/19- TOOH. P	hally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fil and the operator has detennined that the Pull ESP. jnts, 2-7/8", 6.5# L-80. Packet	easured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. Fine site	ertinent markers and zones. Attach the Boning completion of the involved operations. In all Abandonment Notices must be filed on MM	d under which the work will be perfonned of the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.) /27/19- MIRU /28/19 thru 3/31/19- TOOH. P	hally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fil and the operator has detennined that the Pull ESP. jnts, 2-7/8", 6.5# L-80. Packet	easured and true vertical depths of all p ts must be filed within 30 days followed once testing has been completed. File site	ertinent markers and zones. Attach the Boning completion of the involved operations. In all Abandonment Notices must be filed on MM	d under which the work will be perfonned of the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.) /27/19- MIRU /28/19 thru 3/31/19- TOOH. P /1/19- Landed @ 5175' w 166 DMO 14. I hereby certify that the foregoint acey Granillo	itally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has detennined that the operator has detennined that the Pull ESP. jnts, 2-7/8", 6.5# L-80. Packeting is true and correct. Name (Pr	er set @ 5171', 5-GLV. Title: Permittin	ertinent markers and zones. Attach the Boning completion of the involved operations. In all Abandonment Notices must be filed on the state of the st	d under which the work will be performed of the operation results in a multiple ly after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with E completion or recompletion in a ner reclamation, have been completed a is ready for final inspection.) /27/19- MIRU /28/19 thru 3/31/19- TOOH. P /1/19- Landed @ 5175' w 166 DMO 14. I hereby certify that the foregoing the completed a service of the completed and the completed a service of the completed and the comp	itally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has detennined that the operator has detennined that the Pull ESP. jnts, 2-7/8", 6.5# L-80. Packeting is true and correct. Name (Pr	er set @ 5171', 5-GLV. Title: Permittir Date: 4/8/19	ertinent markers and zones. Attach the Boning completion of the involved operations. In all Abandonment Notices must be filed on the state of the st	d under which the work will be perfonned of if the operation results in a multiple by after all requirements, including	

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.