x ^(**) ¹ x					
Form 3160-5	UNITED STATES	CONTRACTOR OF A	HHOOD	FORM	APPROVED
(August 2007)	DEPARTMENT OF THE INT		NMOCD		No. 1004-0137
	BUREAU OF LAND MANAC		PR n1 2	Expires 5. Dease Serial No.	s: July 31, 2010
			014		MSF078089
SU	S ON WELLS	TRICT	6. If Indian, Allottee or Tribe Name		
	for such pro		10.00		
	ons on page 2.	005815.	7. If Unit of CA/Agreement, I	Name and/or No	
1. Type of Well	ons on page 2.				
Oil Well X Gas Well Other				8. Well Name and No.	
2. Name of Operator			9. API Well No.		
Hilcorp Energy Company			30-045-30892		
3a. Address 3b. Phone				10. Field and Pool or Exploratory Area	
382 Road 3100, Aztec, NM 87410		505-599-	505-599-3400 Basin DK / West Kutz PC		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit H (SENE) 1645'FNL & 360' FEL, Sec. 2			, R11W San Juan , New Mexico		
12. CHECK	THE APPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NO	TICE, REPORT OR OTH	HER DATA
TYPE OF SUBMISSION	(PE OF SUBMISSION TYPE OF AC			TION	
X Notice of Intent	Acidize	Deepen	Пр	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat		Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	XF	Recomplete	Other
eK	Change Plans	Plug and Abandon		emporarily Abandon	
Final Abandonment Notice	Operation: Clearly state all pertinent details, in	Plug Back		Water Disposal	inste duration thereaf
following completion of the invo Testing has been completed. Fin determined that the site is ready 2/4/19 Pulled plunger & good. Scan tbg. MU bit & 2/5/19 BDW. TOOH w/	e work will be performed or provide the Bond olved operations. If the operation results in a n nal Abandonment Notices must be filed only a for final inspection.) & bumper spring. Tag fill @ 6448'. N & string mill, TIH to 2325'. SIW, SDF bit & string mill. TIH & set 4.5" CIB DOH, LD tbg & setting tool. ND BOF	nultiple completion after all requirements AIRU AWS 840. ED. P @ 2100'. Circ	or recompletion s, including recla BDW. ND th bole clean v	h in a new interval, a Porm 316 amation, have been completed bg, NU BOPE. PT BOPE w/ 45 bbls H2O w/ bioc	0-4 must be filed once and the operator has to 1500# for 10 min, test
	5K tbg head. PT to 1800# for 10 mi f pressure, install string float on bo	-			
	Pictured Cliffs w/ .46" diam holes	, 4spf @ 1858'-	1865' & 184	0'-1845' = 68 shots . SD	DFD.
Continue on page 2					
14. I hereby certify that the foregoin	g is true and correct. Name (Printed/Typed)				
Christine Brock		Title (Title Operations/Regulatory Technician - Sr.		
signature le pristine Report			Date 3/13/19		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by Dave Mankiewicz The AFM 3/28/					
	tached. Approval of this notice does not warr. table title to those rights in the subject lease w ations thereon.		Office	FFO	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

Scott Federal 27 11 23 #1

2/15/19 RU & Run Slkin press recorders & pump breakdown. RIH w/ Slkin press recorders, hang off recorders 50' above top perf's @ 1790'. Load hole w/ H2O, start pumping, PC broke down @ 5.0 bpm-960 psi, pump for 5 mins @ 5.0 bpm from 321 psi to 616 psi. Pump for additional 5 min & pressure stabilized. SIW @ 09:45 - 17:45 hrs, pull press recorders, RD slkin, SIW, SDFD

2/28/19 RU Frac services. Test fluid lines to 4800 psi, tested good. Test N2 pumps/lines to 4800 psi, tested good. **Frac Pictured Cliffs (1840'-1865')** w/ 1000 gals 15% HCL Acid, 46,792 gals of 70Q water gel #20, 125,020 #'s 20/40 AZ sand w/ sandwedge additive, 289,331 scf N2, 24 foam bbls Flush. SISW. RD Release Frac equipment.

3/1/19 RU FB. FBW, conduct flow test.

3/5/19 MIRU BHE 37. RD frac stack. Install tbg hanger w/ 2 way check in place. NU BOPE. PT pipe & blind rams, tested good. PU & TIH w/ mill. Tag up @ 1950' (150' fill). PU tbg swivel & unload csg w/ air. Bring on mist. CO sand fill from 1950'-2100'. Circ the hole clean on bottom. LD swivel. Pull up above PC perfs, SISW, SDFD.

3/6/19 BDW. TI from above PC perfs. Tag PBTD. No fill. Unload csg just off bottom. Est IFL of 1780'. Bring on air/mist. Circ off bottom 1-hr then pull up 30' & natural flow, repeat through the day. Pull up above PC perfs &SISW, SDFD.

3/7/19 TIH w/ tbg, tag for fill (no fill). K/I air/mist. Unload well. LD tag jts. TOOH w/ tbg. LD CO BHA. PU BHA. TIH. Land 58 jts 2-3/8", 4.7# J-55 tbg @ 1878' w/ SN @ 1876'. RDRR @ 12:00 hrs.

This well will be producing as a PC/DK with an approved Test Allowable C-104 & is waiting on RC C-104 approval.

The well will be commingled per DHC-4907-0 when the PC is turned on to production and the DK CIBP is drilled out and a subsequent sundry report will be filed.