State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary Adrienne Sandoval, Division Director Oll Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by PLM on the following 2160 4 or 2160 5 form

to the actions approved by BLM on the following 3160-4 or 3160-5 form. Operator Signature Date: 4/15/2019

Well information:

HILCORP ENERGY COMPANY

30-045-20116 ROELOFS #001

Application Type:

P&A Drilling/Casing Change Location Change

K Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)



Conditions of Approval:

- Notify the OCD 24hrs prior to beginning operations.
- Based on the information provided in the sundry, the bottom of the Mesaverde is located at 5690' and the proposed perforations are 4682'-5770'.
- If the provided information is correct, the perforations extend below the bottom of the proposed formation, and Hilcorp will need to submit a revised Notice of intent (NOI) to include the Mancos formation or resubmit the NOI with revised perforations within the limits of the Mesaverde. If the information is incorrect, Hilcorp will need to submit a revised NOI with the correct information.
- If the provided information is correct, the Downhole commingle (DHC) will also need to be revised to a trimmingle to include the Mancos or it will need to be revised to include the revised perforations.

Kotheric Bala

NMOCD Approved by Signature

<u>5/23/19</u> Date

1220 South St. Francis Drive • Santa Fe, New Mexico 87505 Phone (505) 476-3460 • Fax (505) 476-3462 • www.emnrd.state.nm.us/ocd

Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG			FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No. NMSF078415A			
Do no	SUNDRY NOTICES AND REPORT t use this form for proposals to d ned well. Use Form 3160-3 (APD	Irill or to re-enter	an of La	6. If Indian, Allottee or Tribe N	and the second se		
	SUBMIT IN TRIPLICATE - Other instruct	tions on page 2.		7. If Unit of CA/Agreement, Na	ame and/or No.		
1. Type of Well Oil Well	X Gas Well Other		1	8. Well Name and No. Roelofs 1			
2. Name of Operator	Hilson Energy Company		4	9. API Well No.	45 20146		
3a. Address	Hilcorp Energy Company 3b.	Phone No. (include area	30-045-20116 e No. (include area code) 10. Field and Pool or Exploratory Area				
382 Road 3100, Azt		505-599-340		Blanco Mesaverde / Basin Dakot			
	c., T.,R.,M., or Survey Description) N (SESW) 920' FSL & 1480' FWL,	Sec. 22, T29N, R		11. Country or Parish, State San Juan ,	New Mexico		
12. CHE	CK THE APPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOT	ICE, REPORT OR OTHE	R DATA		
TYPE OF SUBMISSIO)N	TYPE	E OF ACT	ION			
X Notice of Intent	Acidize	Deepen Fracture Treat New Construction	Re	oduction (Start/Resume) cclamation ccomplete	Water Shut-Off Well Integrity Other		
	Change Plans	Plug and Abandon		mporarily Abandon			
Final Abandonment Notic	ted Operation: Clearly state all pertinent details,	Plug Back	-	ater Disposal			
determined that the site is re Hilcorp Energy Cor the existing Dakota will be filed and ap	Final Abandonment Notices must be filed only ady for final inspection.) npany plans to recomplete the su . Attached is the Mesaverde C-10 proved before work proceeds. A face disturbing activities.	bject well in the 02, recomplete pr	Mesavero	de formation and dow & wellbore schematio	whole commingle with c. A DHC application		
			-	California de la california	MOCD		
HOLD CT04 F	OR Density,			MAY	14 2019		
PICCO CITA	exception	a series		DISTR			
14. I hereby certify that the foreg	oing is true and correct. Name (Printed/Typed)						
Cherylene Weston		Title Open	Title Operations/Regulatory Technician - Sr.				
Signature Cherry	erellecton	Date 4					
5	THIS SPACE FOR F	EDERAL OR ST	ATE OFFI	CEUSE			
that the applicant holds legal or e entitle the applicant to conduct op		rant or certify which would	Title C	etr. Eng	Date 5/3/19		
false, fictitious or fraudulent state	Title 43 U.S.C. Section 1212, make it a crime for ments or representations as to any matter within		and willfully	to make to any department or a	gency of the United States any		
(Instruction on page 2)			(

ß

.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 Form C-102 August 1, 2011

Permit 266078

WELL LOCATION AND ACREAGE DEDICATION PLAT

State of New Mexico

Energy, Minerals and Natural

1. API Number	2. Pool Code	3. Pool Name
30-045-20116	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318689	ROELOFS	001
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6424

10. Surface Location										
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
N	23	/ / / /	08W		920	5	5 148	v v	N	SAN JUAN

11. Bottom Hole Location If Different From Surface									
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00 - W/2		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Title: Cherylene Weston, Operations/Regulatory Tech-Sr. Date: 04/12/2019				
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.				
Surveyed By: E. L. POTEET				
Date of Survey: 7/8/1967				
Certificate Number: 3084				



HILCORP ENERGY COMPANY

ROELOFS 1

MESA VERDE RECOMPLETION SUNDRY

API #: 30-045-20116

JOB PROCEDURES

- 1. MIRU Service rig and associated equipment, test BOP. Check Bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM if any anomalous pressures changes occur on the Bradenhead.
- 2. TOOH w/ 2 3/8" tubing set at 7400'.
- 3. Set initial CIBP at 7224' or deeper (no higher than 50' above existing perforations)
- 4. Perform MIT from initial CBP, providing 24 hr notice to BLM and NMOCD. Once completed, review and submit the MIT charted test results to both the NMOCD and BLM If the MIT fails, discuss and gain approval with both the NMOCD and BLM with a plan of action to remediate the wellbore. Perform a 2nd MIT once remediated.
- 5. Run CBL and submit it to NMOCD and BLM.
- 6. Optionally set bridge plug below intended recomplete interval.
- 7. ND BOP, NU frac stack. Pressure test the production casing or frac string and frac stack to maximum frac pressure. The pressure test will not exceed 85% of the internal yield pressure rating of the primary treatment string.
- 8. Perforate and frac the Mesa Verde within 4682'-5770'.
 - a. Note: Based is determined as 500' from top of Point Lookout.
- 9. Optionally set a kill plug above recomplete interval for casing fracs.
- 10. ND the frac stack, NU the BOP and test.
- 11. MU and TIH with a mill. Tag and drill out the top isolation plug and Mesa Verde frac plugs if applicable.
- 12. Clean out the wellbore to the top of the Dakota isolation plug.
- 13. Once water and sand rates are acceptable, drill out the Dakota isolation plug and cleanout to PBTD of 7637'. TOOH.
- 14. TIH and land production tubing. Get a commingled Dakota/MV flow rate.

