Submit 1 Copy To Appropriate District State of New Mexico				Form C-103	
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources			Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-045-23080		
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
District III - (505) 334-6178         1220 South St. Francis Dr.           1000 Rio Brazos Rd., Aztec, NM 87410         Sento Fee NIM 87505			STATE FEE		
<u>District IV</u> (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & G	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM <u>C</u> -101) FOR SUCH DEODOSALS)				7. Lease Name or Unit Agreement Name J. E. DECKER	
PROPOSALS.) 1. Type of Well: Oil Well  Gas Well  Other				8. Well Number 1A	
2. Name of Operator GREAT WESTERN DRILLING C	ame of Operator			9. OGRID Number	
GREAT WESTERN DRILLING COMPANY 3. Address of Operator PO BOX 1659 MIDLAND, TEXAS 79702 4. Well Location				10. Pool name or Wildcat BLANCO MESA VERDE	
4. Well Location					
Unit Letter P990 feet from the South line and 990 feet from the West line					
Section 7 Township 32N Range 11W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
GL 6,607 KB 6,619					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB       CASING/CEMENT JOB					
CLOSED-LOOP SYSTEM			OTHER:		
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>Great Western Drilling Company plans to rig up pulling unit on April 30, 2019 with intentions to investigate communicated Bradenhead pressure by pulling production tubing. PU 2-3/8 work string. Make bit &amp; scraper run to PBTD. POOH. RIH &amp; set RBP 50' above top perf and test liner hanger and casing. POOH w/ setting tool. WSI to check primary seal on slips &amp; secondary seal.</li> </ul>					
Spud Date: 12-12-1978	Rig	Release D	Pate:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Rugh Summing TITLE Production Superdisor DATE 4-30-19					
Type or print name Ralph Skinner J. E-mail address: rskinner@guide PHONE: 575-942-1294 For State Use Only					
SIGNATURE <u>kuch</u> <u>Kunner</u> TITLE <u>Production</u> <u>Superdisor</u> DATE <u>4-30-19</u> Type or print name Ralph Skinner Jr. E-mail address: <u>rskinner@gudc</u> PHONE: <u>575-942-1294</u> <u>For State Use Only</u> APPROVED BY: <u>Utility</u> <u>Deputy Oil &amp; Gas Inspector</u> , <u>DATE 5-10-19</u> Conditions of Approval (if any):					