Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OH GONGERNALTION	DHUGION	30-039-29667
811 S. First St., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	The second state of the se
	CATION FOR PERMIT" (FORM C-101) FO	OR SUCH	San Juan 29-5 Unit
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number 70F
2. Name of Operator	Gas Well Galler		9. OGRID Number
HILCORP ENERGY COMPA	NY		372171
3. Address of Operator			10. Pool name or Wildcat
382 Road 3100, Aztec, NM 874	110		Gobernador PC/Blanco MV/Basin DK
4. Well Location			
Unit Letter P :	1155 feet from the South	line and	1130 feet from the East line
Section 28	Township 29N	Range 05W	NMPM Rio Arriba County
THE PARTY OF THE P	11. Elevation (Show whether DR,		
是在是自然對對於這種的	6679		
12. Check	Appropriate Box to Indicate Na	ature of Notice.	Report or Other Data
12. 6	appropriate Son to marcute 1.		1
	NTENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB L
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM OTHER:	Recomplete	OTHER:	П
			d give pertinent dates, including estimated date
			mpletions: Attach wellbore diagram of
proposed completion or rec		1	
			fs formation and downhole commingle the
			procedure & wellbore schematic. The DHC
application will be submitted	ed and approved prior to commingling	ng. A closed loop s	ystem will be utilized.
			20 to 10 to
			NMOCD
	HOLD C104 FOR DHO		
	UNID CTO4 FOR		JUN 1 2 2019
		NMOCD 24 hrs	2013
	bi ioi.	to Deginning .	DISTRICT 111
	ор	erations	TOTAL III
		雅圖	
Spud Date:	Rig Release Da	te:	
I hereby certify that the information	above is true and complete to the be	st of my knowledge	e and belief.
	and the same and an arrangement to the co	or or my mile midag	
E1100			
SIGNATURE CHECK	TITLE_Operat	ions/Regulatory Te	chnician – SrDATE6/10/2019
T	<i>a</i>		NUO III
Type or print name Etta Trujillo			hilcorp.com PHONE: _(505)324-5161
For State Use Only	111	LORG BIRTS	FOT #3
APPROVED BY: 72/16	TITI & UP ERY	HEDR DIST	DATE 6/17/19
Conditions of Approval (if any):	EV.		DAIL
	/ V		

<u>District I</u>

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 268407

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-29667	77440	GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code	5. Property Name	6. Well No.
318837	SAN JUAN 29 5 UNIT	070F
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6679

10. Surface Location

										_
UL - Lot P	Section 28	Township 29N	Range 05W	Lot Idn	Feet From 1155	N/S Line S	Feet From 1130	E/W Line E	County- RIO ARRIBA	
		1			I .					

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From .	N/S Line	Feet From	E/W Line	County
12. Dedicated A 320	cres .00 E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	.

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Op

Operations/Regulatory Tech Sr

Date:

06/10/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Jason Edwards

Date of Survey:

8/18/2005

Certificate Number:

15269



HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 70F PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 7,954'.
- 3. Set a 4-1/2" plug at +/- 5,405' to isolate the Mesa Verde and Dakota Formations. Note: TOC at 2,748' by CBL.
- 4. Load the hole and perform MIT (Pressure test to 560 psi). Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 5. Set a 4-1/2" plug at +/- 3,800'.
- 6. Load the hole and pressure test the casing to 5,000 psi (64.3% of internal yield pressure for 4.5" 11.6# N-80 casing).
- 7. N/D BOP, N/U frac stack and pressure test frac stack.
- 8. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,625"; Bottom Perforation @ 3,711").
- 9. If needed, isolate frac stage with a plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out any plugs above the Mesa Verde and Dakota Formation isolation plug.
- 12. Clean out to Mesa Verde and Dakota Formation isolation plug.
- 13. Drill out Mesa Verde and Dakota Formation isolation plug and cleanout to PBTD of 8,005'. TOOH.
- 14. TIH and land production tubing. Get a commingled Mesa Verde + Dakota + Pictured Cliffs flow rate.



HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 70F PICTURED CLIFFS RECOMPLETION SUNDRY

