

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

5. Lease Serial No.

NMSF078912

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

382 Road 3100, Aztec, NM 87410

3b. Phone No. (include area code)

505-599-3400

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Lindrith B Unit 113

9. API Well No.

30-039-26766

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit O (SWSE) 330' FSL & 2300' FEL, Sec. 10, T24N, R03W

10. Field and Pool or Exploratory Area

Lindrith Gallup-Dakota, West

11. Country or Parish, State

Rio Arriba, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Rod/Tubing Repair

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

See attached.

NMOC

OCT 13 2018

DISTRICT III

ACCEPTED FOR RECORD

OCT 03 2018

FARMINGTON FIELD OFFICE


By: 

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Etta Trujillo

Title **Operations/Regulatory Technician - Sr.**

Signature



Date

9/26/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOC

2

9/12/2018 – MIRU. LD 1x7/8" rod & pony rod. Multiple attempts to hot oil down tbg/csg.

9/13/2018 – Finish TOO H w/rods. ND B-1. NU BOP stack. Good test. TIH/tag PBT D (7602'), no fill. SIW. SDFN.

9/14/2018 – Spot in new tbg. TIH w/pro BHA. Established circ. Work stuck tbg, no gain. RU hot oil truck pump 40bbls@225deg & 70bbls@230deg, no gain. SIW. SDFN.

9/17/2018 – Attempt to work stuck tbg, no gain. RU WL. Found stretch differential between 1500' & 2500' due to paraffin. Paraffin plug @ 7290'. RIH. Chemical cut tbg @ 7275'. Left 295' of fish in well. RD WL. TOO H w/recovered tbg. TIH w/overshot jars & collars. Latch unto fish & jar, gaining 2'. Leave tbg in 65k tension. SIW. SDFN.

9/18/2018 – Attempt to work stuck tbg, no gain. TIH w/wash pipe to 7245'. Tagged tight spot 23' above fish @ 7268'. Attempt to work over w/tongs, no gain. Prep equip to circ w/air mist. SIW. SDFN.

9/19/2018 – Establish circ w/8BPH mist/1350CFM air. Mill 10' past top of fish to 7278'. Fish depth 7268' to 7566'. SIW. SDFN.

9/20/2018 – TOO H. TIH w/pro BHA. Land @ 7255' (Top of SN @ 7232') w/232 jts, 2-3/8", 4.70#, J-55. RD. ND BOP stack. NU 'B-1. SIW. SDFN.

9/21/2018 – TIH w/rods. Space out, test to 1000#. Good test. RD. Release rig.