BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Office abandoned well. Use Form 3160-3 (APD) for such proposals agement			6. If Indian, Allottee o	6. If Indian, Allottee or Tribe Name	
	m. Use Form 3160-3 (7	APD) for such propos	1		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No. NMNM-132829	
1. Type of Well					
⊠Oil Well □Gas Well □Other			8. Well Name and No. NE CHACO COM #198H		
2. Name of Operator			9. API Well No.		
Enduring Resources IV LLC			30-039-31268 (include area code) 10. Field and Pool or Exploratory Area		
3a. Address 200 Energy Court Farmington NM	87401	3b. Phone No. <i>(include area c</i> 505-6369743	Code) 10. Field and Pool of Exploratory Area CHACO UNIT NE HZ OIL		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1440' FNL & 217' FWL SEC 8 23N 6W BHL: 133' FNL & 503' FEL SEC 12 23N 7W)	11. Country or Parish, RIO ARRIBA, NM	11. Country or Parish, State RIO ARRIBA, NM	
12. 0	CHECK THE APPROPRIATE I	BOX(ES) TO INDICATE NATU	JRE OF NOTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		Т	TYPE OF ACTION		
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water ShutOff	
	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	Convert to Rod	
	Convert to Injection	Plug Back	Water Disposal	Pump	
68				1	
Describe Proposed or Completed Operation: Cle ve subsurface locations and measured and true ve filed within 30 days following completion of th	ertical depths of all pertinent markers and a ne involved operations. If the operation res	zones. Attach the Bond under which the w sults in a multiple completion or recomplet	ork will be perfonned or provide the Bond No. on tion in a new interval, a Form 3160-4 must be file	file with BLM/BIA. Required subsequent reports mu	
Describe Proposed or Completed Operation: I ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.)	ertical depths of all pertinent markers and a ne involved operations. If the operation res	zones. Attach the Bond under which the w sults in a multiple completion or recomplet	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme	
B Describe Proposed or Completed Operation: Cle ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.)	ertical depths of all pertinent markers and a ne involved operations. If the operation res	zones. Attach the Bond under which the w sults in a multiple completion or recomplet	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site	file with BLM/BIA. Required subsequent reports mu d once testing has been completed. Final Abandonme	
B Describe Proposed or Completed Operation: Cleve subsurface locations and measured and true ve to filed within 30 days following completion of the otices must be filed only after all requirements, is ready for final inspection.)	ertical depths of all pertinent markers and a te involved operations. If the operation res including reclamation, have been complet	zones. Attach the Bond under which the w sults in a multiple completion or recomplet	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme	
 B. Describe Proposed or Completed Operation: Cleve subsurface locations and measured and true ve filed within 30 days following completion of thotices must be filed only after all requirements, i is ready for final inspection.) /9/19 - MIRU /10/19 thru 5/14/19- Start RIH, 	ertical depths of all pertinent markers and a te involved operations. If the operation res including reclamation, have been complet , pull tubing and GLV	zones. Attach the Bond under which the w sults in a multiple completion or recomplet	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme	
Describe Proposed or Completed Operation: 1 ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.) /9/19 - MIRU /10/19 thru 5/14/19- Start RIH, /15/19- Land tubing @ 5622'. 1	ertical depths of all pertinent markers and a ne involved operations. If the operation res including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#.	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file : site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
Describe Proposed or Completed Operation: Clove subsurface locations and measured and true verified within 30 days following completion of the otices must be filed only after all requirements, i is ready for final inspection.) (9/19 - MIRU /10/19 thru 5/14/19- Start RIH, /15/19- Land tubing @ 5622'. 1 IH with Rods. 1 1/2 X 26' SPRAY	ertical depths of all pertinent markers and a te involved operations. If the operation res including reclamation, have been complet , pull tubing and GLV 172 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29-3	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site DIS 5- 3/4 4 PER GUIDED RODS 36- 1"	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
 Describe Proposed or Completed Operation: Cleve subsurface locations and measured and true verified within 30 days following completion of the otices must be filed only after all requirements, is ready for final inspection.) /9/19 - MIRU /10/19 thru 5/14/19- Start RIH, /15/19- Land tubing @ 5622'. 1 IH with Rods. 1 1/2 X 26' SPRAY TABILIZER 26K SHEAR TOOL=6" DMO 	ertical depths of all pertinent markers and a te involved operations If the operation res including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29- 2 1/2 X 1 1/4 X 14 RHBC RO	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site DIS 5- 3/4 4 PER GUIDED RODS 36- 1"	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
Describe Proposed or Completed Operation: Clo ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.) ////////////////////////////////////	ertical depths of all pertinent markers and a te involved operations If the operation res including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29- 2 1/2 X 1 1/4 X 14 RHBC RO	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE	ork will be perfonned or provide the Bond No. on ion in a new interval, a Form 3160-4 must be file e site DIS 5- 3/4 4 PER GUIDED RODS 36- 1"	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
Describe Proposed or Completed Operation: Clo ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.) ////////////////////////////////////	ertical depths of all pertinent markers and a te involved operations If the operation res including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29- 2 1/2 X 1 1/4 X 14 RHBC RO	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE	ork will be perfonned or provide the Bond No on ion in a new interval, a Form 3160-4 must be file site DIS 5- 3/4 4 PER GUIDED RODS 36- 1" 3E	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
B Describe Proposed or Completed Operation: Cite ve subsurface locations and measured and true ve filed within 30 days following completion of th otices must be filed only after all requirements, i is ready for final inspection.) ////19 thru 5/14/19- Start RIH, /15/19-Land tubing @ 5622'. 1 EIH with Rods. 1 1/2 X 26' SPRAY TABILIZER 26K SHEAR TOOL=6" EDMO 14. I hereby certify that the foregoin Lacey Granillo	ertical depths of all pertinent markers and a te involved operations If the operation res including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29- 2 1/2 X 1 1/4 X 14 RHBC RO	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE rinted/Typed) Title Permit	ork will be perfonned or provide the Bond No on ion in a new interval, a Form 3160-4 must be file site	UN 1 2 2019	
 Describe Proposed or Completed Operation. Cleve subsurface locations and measured and true verified within 30 days following completion of the otices must be filed only after all requirements, is ready for final inspection.) /9/19 - MIRU /10/19 thru 5/14/19- Start RIH, /15/19- Land tubing @ 5622'. 1 IH with Rods. 1 1/2 X 26' SPRAY TABILIZER 26K SHEAR TOOL=6" DMO 14. I hereby certify that the foregoin 	ertical depths of all pertinent markers and a the involved operations. If the operation resi- including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29-1 2 1/2 X 1 1/4 X 14 RHBC RO rg is true and correct. Name (<i>Pr</i>	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE inted/Typed)	ork will be perfonned or provide the Bond No on ion in a new interval, a Form 3160-4 must be file site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme NMOCD UN 1 2 2019 TRICT III	
Describe Proposed or Completed Operation: Clove subsurface locations and measured and true verified within 30 days following completion of the otices must be filed only after all requirements, i is ready for final inspection.) (9/19 - MIRU (10/19 thru 5/14/19- Start RIH, (15/19- Land tubing @ 5622'. 1 IH with Rods. 1 1/2 X 26' SPRAY IABILIZER 26K SHEAR TOOL=6" DMO 14. I hereby certify that the foregoin Lacey Granillo Signature Signature	ertical depths of all pertinent markers and a the involved operations. If the operation resi- including reclamation, have been complet , pull tubing and GLV L72 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29-1 2 1/2 X 1 1/4 X 14 RHBC RO rg is true and correct. Name (<i>Pr</i>	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE inted/Typed) Title Permit Date 5/20/19	ork will be perfonned or provide the Bond No on ion in a new interval, a Form 3160-4 must be file site	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonme UN 1 2 2019 TRICT III 4 PER GUIDED RODS 4' X 7/8 PUM	
a Describe Proposed or Completed Operation: Clive subsurface locations and measured and true vere filed within 30 days following completion of the otices must be filed only after all requirements, is ready for final inspection.) /9/19 - MIRU /10/19 thru 5/14/19- Start RIH, /15/19- Land tubing @ 5622'. 1 Clive with Rods. 1 1/2 X 26' SPRAY TABILIZER 26K SHEAR TOOL=6" CDMO 14. I hereby certify that the foregoin Lacey Granillo	ertical depths of all pertinent markers and a the involved operations. If the operation resi- including reclamation, have been complet perturbation, have been complet 172 jts, 2-7/8", J55, 6.5#. METAL POLISHED ROD 29-1 2 1/2 X 1 1/4 X 14 RHBC RO reg is true and correct. Name (<i>Pr</i>	zones Attach the Bond under which the w sults in a multiple completion or recomplet ed and the operator has detennined that the 7/8 4 PER GUIDED RODS 155 D PUMP 1 1/4 X 15' DIP TUE inted/Typed) Title Permit Date 5/20/19	ork will be perfonned or provide the Bond No on ion in a new interval, a Form 3160-4 must be file site 5- 3/4 4 PER GUIDED RODS 36- 1" 3E Specialist STATE OFICE USE	file with BLM/BIA Required subsequent reports mu d once testing has been completed. Final Abandonmer UN 1 2 2019 TRICT 111 4 PER GUIDED RODS 4' X 7/8 PUM	

RECEIVED

FORM APPROVED OMB No. 1004-0137

Expires: January 31, 2018

Ł

Form 3160-5

(June 2015)

٤.

. .

UNITED STATES

DEPARTMENT OF THE INTERIOR

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

