nuended

State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary Adrienne Sandoval, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 5/1/2019 Well information:

30-039-06476 JICARILLA 110 #012

SOUTHLAND ROYALTY COMPANY LLC

Application Type:

🖂 P&A 🔄 Drilling/Casing Change 🗌 Location Change

Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)



Conditions of Approval:

- Notify NMOCD 24hrs prior to beginning operations.
- Extend plug #1 to 3090'-2510' BLM Ojo Alamo pick @ 2588'
- Adjust plug #2 to 1218'-1350' to cover the Nacimiento top. BLM Nacimiento pick @ 1268'. OCD Nacimiento pick @ 1300'.

NMOCD Approved by Signature

8/6/19 Date

	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2			OMB Expires: 5. Lease Serial No. JIC110 6. If Indian, Allottee		
=				7. If Unit or CA/Ag		
-	1. Type of Well □ Oil Well 🛛 Gas Well □ Other			8. Well Name and No. JICARILLA 110 12		
-	2. Name of Operator SOUTHLAND ROYALTY COM		ERIC KITTINGER mspartners.com			
	3a. Address 400 W 7TH STREET FORT WORTH, TX 76102		3b. Phone No. (include area cod Ph: 817.334.8302		10. Field and Pool or Exploratory Area SOUTH BLANCO	
-	 Location of Well (Footage, Sec., T., R., M., or Survey Description Sec 17 T26N R5W NESW 1650FSL 1650FWL 36.484263 N Lat, 107.386149 W Lon 			11. County or Parish RIO ARRIBA (
-	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
_	TYPE OF SUBMISSION		ТҮРЕ С	TYPE OF ACTION		
	 ☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice 	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection 	 Deepen Hydraulic Fracturing New Construction Plug and Abandon Plug Back 	 Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal 	 Water Shut-Off Well Integrity Other 	
	 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed determined that the site is ready for final inspection. SRC requests approval to plug and abandon the Jicarilla 110 #12. Attached are the Proposed Procedure, WBDs, Proposed Reclamation Plan, and Noxious Weed Form. 					
	Approved with COA for CBL and plugs to be adjusted based on results					
	JUL 1 0 2019					
<u>*</u>	14. I hereby certify that the foregoing is true and correct. Image: Construct of the state of the stat					
	Signature (Electronic Submission) Da			2019		
-	THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
=	Approved By_JOE KILLINS			EUM ENGINEER	Date 06/27/201	
(Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.		subject lease			
V	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

NMOCDPY

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Jicarilla 110 12 API: 30-039-06476

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. CBL required after setting CIBP from 3090' to surface to confirm TOC. Submit electronic copy of the log for verification to the following addresses: <u>jkillina@blm.gov</u> and <u>Brandon.Powell@state.nm.us</u>. Based on CBL results inside/outside plugs and volumes will be adjusted accordingly. Please review the Genereal Requirements document to ensure volumes meet required excess inside and outside casing.


4. BLM picks formation tops as indicated in the table below for use in determining TOC for all plugs.

TopNacimiento1268Ojo Alamo2588Kirtland2754Fruitland2865Pictured Cliffs3174Lewis Shale3282Chacra4084

P&A PLANNED PROCEDURE

Jicarilla 110 #12

- 1. MIRU.
- 2. Run a casing scraper to 3,110'
- 3. Set CIBP @ 3,090'
- 4. Spot 60 sx Class B Cement on top of plug. (est'd TOC @ 2,600). WOC. Tag TOC.
- 5. Spot balanced cement plug from 1,250' 1,350' with 12 sx Class B cement. WOC. Tag TOC.
- 6. Perforate 3 holes @ 155'.
- 7. Pump 53 sx Class B Cement to fill annulus up through bradenhead and production casing string to surface. If unable to circulate, top off as needed.
- 8. Cut off wellhead below surface casing flange. Install P&A marker.





Jicarilla 110 #12 Rio Arriba County, NM

TD - 3,261'; PBTD - 3,225'

10.5" hole to 103' KB. Surface Csg: 5 jts 8 5/8" 24# J-55 Setting Depth: 103'

Cement 70 Sx Circulated to surface


7.25" hole to 3,261' Production Csg: 97 jts 5.5", 15.5# J-55 Setting Depth: 3,260' 100sx cement TOC Unknown

12/08/1957 3139'-3173' & 3190'-3208' 4 spf Sandfracutred with 24,600 gal water & 30,000# sand. Flushed with 3,400 gal water Dropped 100 rubber balls during treatment

PROPOSED P&A

KB = 6,674' GL = 6,665' API# 30-039-06476

Spud Date: 10/29/1957 Date Completed: 12/24/1957



PLUG 3: Perf 3 holes @ 155' 33 sx cement in casing annulus & 20 sx cement inside 5.5" casing. Bring all cement to surface.

PLUG 2: Balanced Cement Plug from 1,250' – 1,350' w/ 12 sx cmt.

> PLUG 1: Set CIBP @ 3,090' Top w/ 60 sx Cmt. TOC @ 2,600'