## State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary Adrienne Sandoval, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 7/1/2019 Well information:

# 30-045-27124 BETTIN ON BISTI 30 #009

# ENDURING RESOURCES, LLC

Application Type:

P&A 🗌 Drilling/Casing Change 🗌 Location Change

**Recomplete/DHC** (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)



Conditions of Approval:

- Notify NMOCD 24hrs prior to beginning operations.
- Add a Chacra Plug 1635'-1535'.

NMOCD Approved by Signature

9/4/19 Date

(June 2015)	UNITED STATES		1 1 2019	OMI	FORM APPROVED OMB No. 1004-0137	
,	DEPARTMENT OF THE BUREAU OF LAND MAN		1 2010	5. Lease Serial No.	Expires: January 31, 2018 5. Lease Serial No.	
	RY NOTICES AND REP		Reld Office	NMNM68764		
Do not use t	his form for proposals well. Use Form 3160-3 (A	6. If Indian, Allottee or Tr NAVAJO	6. If Indian, Allottee or Tribe Name NAVAJO			
	IT IN TRIPLICATE - Other instr	ructions on page 2		7. If Unit of CA/Agreeme	nt, Name and/or No.	
1. Type of Well       □Oil Well       ☑Gas Well       □Other				8. Well Name and No. BETTIN ON BISTI 30 009		
2. Name of Operator				9. API Well No. 30-045-27124		
Enduring Resources IV LLC3a. Address200 Energy Court Farmington NM 87401505-636-9743			ude area code)			
4. Location of Well (Footage, Sec SHL: 1980' FSL & 660' FEL Se		)		11. Country or Parish, Sta San Juan, NM	te	
12.	CHECK THE APPROPRIATE E	BOX(ES) TO INDICA	TE NATURE OF	NOTICE, REPORT OR OTHER	DATA	
TYPE OF SUBMISSION		Down	TYPE OI	F ACTION		
Notice of Intent	Acidize	Deepen Hydraulic Frac	eturing	Production (Start/Resume)	Water ShutOff	
Subsequent Report	Casing Repair	New Constru	ction	Recomplete	Other Plug and Abando	
Final Abandonment Notice	Change Plans	Plug and Aba	ndon	Temporarily Abandon		
		Plug Back		Water Disposal	ter Disposal	
directionally or recomplete horizon provide the Bond No. on file with completion or recompletion in a ne	tally, give subsurface locations and me BLM/BIA. Required subsequent report w interval, a Form 3160-4 must be file	asured and true vertical of ts must be filed within 30 ed once testing has been	depths of all pertinen days following con	at markers and zones. Attach the Bond npletion of the involved operations. If	under which the work will be perform the operation results in a multiple	
directionally or recomplete horizon provide the Bond No. on file with completion or recompletion in a ne reclamation, hat periodic the is ready for final it rection is under bond is surface restoration	tally, give subsurface locations and me BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be file and the uncentre of the subsequent that the ore. Liability retained until	asured and true vertical c ts must be filed within 30 ed once testing has been he site	depths of all pertinen 0 days following con completed. Final Ab	It markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only CONDITIC Adhere to pre	under which the work will be perform the operation results in a multiple after all requirements, including <b>NS OF APPROVAL</b> viously issued stipulations ant and proposed wellbore dia	
directionally or recomplete horizon provide the Bond No. on file with completion or recompletion in a ne reclamation, has performed as is ready for final it per tool bo under bond is surface restoration	tally, give subsurface locations and me BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be file and the tragging as detennined that the ore. Liability retained until on is completed.	asured and true vertical c ts must be filed within 30 ed once testing has been he site	depths of all pertinen 0 days following con completed. Final Ab	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only CONDITIC Adhere to pre	under which the work will be perform the operation results in a multiple after all requirements, including <b>NS OF APPROVAL</b> viously issued stipulations ant and proposed wellbore dia	
directionally or recomplete horizon provide the Bond No. on file with 1 completion or recompletion in a ne reclamation, ha <b>kepenovolutes</b> is ready for finafittee to a local under bond is surface restoration Enduring Resources IV LLC and reclamation plan.	ntally, give subsurface locations and me BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be file and the ungain gas detennined that the ore. Liability retained until on is completed.	asured and true vertical of ts must be filed within 30 ed once testing has been he site	depths of all pertinen 0 days following con completed. Final Ab	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only <b>CONDITIO</b> Adhere to pre the attached procedure, curre <b>NM</b> ( AUG 1	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations ant and proposed wellbore dia CD 6 2019	
directionally or recomplete horizon provide the Bond No. on file with 1 completion or recompletion in a ne reclamation, ha <b>kepenovolutes</b> is ready for finafittee to a local under bond is surface restoration Enduring Resources IV LLC and reclamation plan.	ntally, give subsurface locations and me BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be file and the ungain gas detennined that the ore. Liability retained until on is completed.	asured and true vertical of ts must be filed within 30 ed once testing has been he site	depths of all pertinen 0 days following con completed. Final Ab	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only <b>CONDITIC</b> Adhere to pre the attached procedure, curre NM AUG 1	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations ant and proposed wellbore dia CD 6 2019	
directionally or recomplete horizon provide the Bond No. on file with 1 completion or recompletion in a ne reclamation, ha <b>kepenovolutes</b> is ready for finafittee to a local under bond is surface restoration Enduring Resources IV LLC and reclamation plan.	ing is true and correct. Name (Pro	asured and true vertical of ts must be filed within 30 ed once testing has been he site n the BETTIN ON BI <i>inted/Typed)</i> Titl Dat	depths of all pertinen 0 days following con completed. Final Ab 1STI 30 009 per t le: Permit Specia de: 7/1/19	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only <b>CONDITIC</b> Adhere to pre the attached procedure, curre <b>NM</b> AUG 1 DISTRIC	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations ant and proposed wellbore dia 0 CD 6 2019	
provide the Bond No. on file with 1 completion or recompletion in a ne reclamation, had percompletes is ready for final it the cive) 1 bo under bond is surface restoration Enduring Resources IV LLC and reclamation plan.	ing is true and correct. Name (Pro	asured and true vertical of ts must be filed within 30 ed once testing has been he site n the BETTIN ON BI <i>inted/Typed)</i> Titl Dat	depths of all pertinen 0 days following con completed. Final Ab 1STI 30 009 per t le: Permit Specia de: 7/1/19	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only <b>CONDITIC</b> Adhere to pre the attached procedure, curre NM AUG 1	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations ant and proposed wellbore dia CD 6 2019	
directionally or recomplete horizon provide the Bond No. on file with I completion or recompletion in a ne reclamation, had performing the under bond is surface restoration Enduring Resources IV LLC and reclamation plan.	ing is true and correct. Name (Pro	asured and true vertical of ts must be filed within 30 ed once testing has been he site n the BETTIN ON BI <i>inted/Typed)</i> Titl Dat	depths of all pertinen 0 days following con completed. Final Ab 1STI 30 009 per t le: Permit Specia de: 7/1/19	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only CONDITIC Adhere to pre the attached procedure, current NM ( AUG 1 alist DISTRIC	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations ant and proposed wellbore dia 0 CD 6 2019	
directionally or recomplete horizon provide the Bond No. on file with 1 completion or recompletion in a ne reclamation, ha <b>k performing leas</b> is ready for final <b>it for toold is</b> <b>surface restoration</b> Enduring Resources IV LLC and reclamation plan.	itally, give subsurface locations and me BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be file and plugging as detennined that the pre. Liability retained until on is completed. C requests to plug and abando ing is true and correct. Name (Pratice Space) E attached. Approval of this notice gal or equitable title to those rights	asured and true vertical of ts must be filed within 30 ed once testing has been one site inted/Typed) EFOR FEDER/	depths of all pertinen 0 days following con completed. Final Ab 1STI 30 009 per t de: Permit Specia te: 7/1/19 AL OR STAT	it markers and zones. Attach the Bond npletion of the involved operations. If andonment Notices must be filed only CONDITIC Adhere to pre the attached procedure, current NM( AUG 1 alist DISTRIC EOFICE USEACCEPT	under which the work will be perform the operation results in a multiple after all requirements, including NS OF APPROVAL viously issued stipulations and and proposed wellbore dia 000 6 2019 1 111 ED FOR RECORD	

Farady-comment bounded in 1963 with Artice Walt Serving Co



#### Enduring Resources Plug & Abandon Procedure May 21, 2019

Bettin on Bisti 30 #9 API: 30-45-27124 Well: Location: 1980' FSL & 660' FEL Field: Bisti lower Gallup Sec,T, R: Sec 30 . T25N. 11W Elevation: GL: 6445' Cnty/State: San Juan, New Mexico 36.3703423,-108.0383835 By: Aztec Well Servicing Lat/Long:

#### Objective:

Permanently plug & abandon the well from 4670' to surface containing 5 cement plugs.

#### Prior to Rig:

- 1. Notify BLM & NMOCD
- 2. Note: verify all cement volumes based on actual slurry to be pumped.
- 3. See attached COA's from BLM & NMOCD.

#### Procedure:

- 1. MIRU well servicing rig and cement equipment.
- 2. LD rods.
- 3. ND WH, NU BOPE, RU rig floor and 2-7/8" handling tools.
- 4. Release TAC, LD production string.
- 5. Tally and PU 2-3/8" workstring with 5-1/2" casing scraper to 4700'.
- 6. TOOH and LD casing scraper.
- 7. TIH with 5-1/2" CR and set @ 4670'.
- 8. Pressure test tubing to 1000psi, roll well, and close pipe rams and pressure test casing to 800psi. (WOC to be determined if test holds).
- 9. Plug #1, 4670'-4455' (Gallup Perfs &Top: 4505') Mix & pump 31 sxs of Class G cement (or equivalent) on top of CR to cover Gallup perfs and top. Pull up and reverse circulate tubing clean.
- 10. TOOH and LD setting tool and TIH open ended.
- 11. Plug #2, 3855'-3755' (Mancos Top: 3805') Mix 18 sxs of Class G cement (or equivalent) and pump a balance plug to cover the Mancos top. Pull up and reverse circulate tubing clean.
- 12. LD tubing to 2727'.
- 13. Plug #3, 2727'-2627' (Mesaverde Top: 2677') Mix 18 sxs of Class G cement (or equivalent) and pump a balance plug to cover the Mesaverde top. Pull up and reverse circulate tubing clean.
- 14. LD tubing to 1283'.
- 15. Plug #4, 1283'-820' (PC, Fruitland, Kirtland, Ojo Alamo Tops: 1233', 1125', 1070', 870') Mix 60 sxs of Class G cement (or equivalent) and pump a balance plug to cover the PC, Fruitland, Kirtland and Ojo Alamo tops. Pull up and reverse circulate tubing clean.



### Enduring Resources Plug & Abandon Procedure May 21, 2019

Well:	Bettin on Bisti 30 #9	API:	30-45-27124
Location:	1980' FSL & 660' FEL	Field:	Bisti lower Gallup
Sec,T, R:	Sec 30 , T25N, 11W	Elevation:	GL: 6445'
Cnty/State:	San Juan, New Mexico	•	
Lat/Long:	36.3703423,-108.0383835	By:	Aztec Well Servicing
Lat/Long:	36.3703423,-108.0383835	Ву:	Aztec Well Servicing

- 16. LD tubing to 319'.
- 17. Plug #5, 319'-0' (Surface Casing Shoe to 0') Mix and pump 45 sxs of Class G cement (or equivalent) until good cement returns to surface.
- 18. ND BOP and cut off wellhead below surface casing flange per regulation. Top off w/cement if needed. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

#### THE-AZTEG-WELL-FAMILY 1951 Not Servicing Co



## **Enduring Resources** Plug & Abandon Procedure


May 21, 2019

Well:	Bettin on Bisti 30 #9	API:	30-45-27124
Location:	1980' FSL & 660' FEL	Field:	Bisti lower Gallup
Sec,T, R:	Sec 30 , T25N, 11W	Elevation:	GL: 6445'
Cnty/State:	San Juan, New Mexico		
Lat/Long:	36.3703423,-108.0383835	By:	Aztec Well Servicing
-			

#### Bettin on Bisti 30 #9


Proposed P&A **Bisti Lower Gallup** SEC 30, T25N, R11W API 30-045-27124 Procedure Date: 5/21/2019

#### Proposed P&A



5-1/2" 15.5# Production Casing set @4995' Stage 1, and 2: 750 sxs, circ to surface.

TD @ 5000'



Bettin on Bisti #9 WBD.xts

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD.

· •

FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Bettin on Bisti 30 009

#### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. If casing fails pressure test, CBL required after setting CR from 4670' to surface to confirm cement. Submit electronic copy of the log for verification to the following addresses: jkillina@blm.gov and Brandon.Powell@state.nm.us . Based on CBL results inside/outside plugs and volumes will be adjusted accordingly. Please review the Genereal Requirements document to ensure volumes meet required excess inside and outside casing.

4. Add an additional plug (720'-445') to cover BLM picks for Kirtland and Ojo Alamo tops at 670' and 495'.