Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31 20

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

 Lease Serial No. 14206032168A

Do not use this form for proposals to abandoned well. Use form 3160-3 (AP	If Indian, Allottee or Tribe Name SHIPROCK	
SUBMIT IN TRIPLICATE - Other ins	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well	8. Well Name and No. NAVAJO 27 1	
2. Name of Operator Contact: XTO ENERGY INC E-Mail: pshorty@f	9. API Well No. 30-045-29955-00-C1	
3a. Address 600 E EXCHANGE FT WORTH, TX 76164	3b. Phone No. (include area code) Ph: 505-324-5188	 Field and Pool or Exploratory Area BASIN FRUITLAND COAL WEST KUTZ GALLUP
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	11. County or Parish, State	
Sec 27 T29N R14W NENE 1255FNL 1120FEL		SAN JUAN COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off☑ Well Integrity□ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy Company requests permission to perform a MIT per the attached procedure and wellbore schematic to extend the TA status. The subject well was TA'd on 9/4/2014.

NMOCD

AUG 28 2019

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Electronic Submission #475956 verified by the BLM Well Information System For XTO ENERGY INC, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 08/27/2019 (19JK0171SE)								
Name (Printed/Typed)	PRISCILLA SHORTY	Title	OPERATIONS REGULATORY TECH					
Signature	(Electronic Submission) THIS SPACE FOR FEDERA	Date	07/31/2019 STATE OFFICE USE					
	THIS OF AGE FOR FEBRUAR		CTATE OF THE COL					
Approved By JOE KILLINS			ETROLEUM ENGINEER	Date 08/27/2019				
certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease icant to conduct operations thereon.	Office	· Farmington					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United								

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





HILCORP ENERGY COMPANY NAVAJO 27 1

MIT SUNDRY

API#:

3004529955

JOB PROCEDURES

- 1. Notify BLM / NMOCD at least 48 hours prior to conducting the MIT.
- 2. Record current wellhead pressures, ND exisiting piping on casing valve
- 3. RU pump truck, pressure test surface equipment and wellhead to 1000 psi
- 4. Load well and pressure test CIBP at 1070' to 650 psi, hold for 30 minutes and chart on a 2 hour chart. Monitor tbg and surface csg pressures
- 5. Bleed off pressure, break out surface piping and RD pump truck. NU exisitng piping.



HILCORP ENERGY COMPANY

NAVAJO 27 1 MIT SUNDRY

