Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NMSF078277

SOMPLY	CHOLS AND IN	-I OILIO OIL A	VLLLO
Do not use this	form for proposal	s to drill or to I	re-enter an
abandoned well.	Use form 3160-3	(APD) for such	proposals.

6. If Indian, Allottee or Tribe Name

abandoned well. Ose form 5100-5 (Al L					
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No. 891000437B			
Type of Well		8. Well Name and No. SAN JUAN 29-5 UNIT 55F			
2. Name of Operator Contact: TAMMY JONES HILCORP ENERGY COMPANY E-Mail: tajones@hilcorp.com (san jua		9. API Well No. 30-039-29335-00-C1			
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505.324.5185	 Field and Pool or Exploratory Area BASIN DAKOTA BLANCO MESAVERDE 			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State				
Sec 18 T29N R5W NWSW 2460FSL 1050FWL 36.725165 N Lat, 107.404179 W Lon		RIO ARRIBA COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					

TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
☑ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity	
	☐ Casing Repair	■ New Construction	■ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon		
BP	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		

Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

This well was returned to production on 9/4/2019 following a Recompletion project. This well is now producing as a Gobernador Pictured Cliffs/Blanco Mesaverde/Basin Dakota tri-mingle under DHC4999.

Please see attached recompletion summary reports, wellbore schematic & production allocation.

NMOCD SEP 1 1 2019 BICTRICT III

			112141	01
14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #482438 verifie For HILCORP ENERGY COMP Committed to AFMSS for processing by J	ANY, s	sent to the Farmington	
Name (Printed/Typed)	TAMMY JONES	Title	REGUALATORY SPECIALIST	
Signature	(Electronic Submission)	Date	09/09/2019	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By ACCEPTED			OE KILLINS ENGINEER	Date 09/09/201
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	⊵ Farmington	



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

5/21/19 Verbal remediation plan approval from Brandon Powell, NMOCD & Jim Lovato, BLM to cmt sqz @ 3538'.

6/26/19 (BH & INT 0#) MIRU. ND WH. NU BOP. PT BOP, test good. Pull tbg hanger & tag fill @ 7933'. TOOH w/2-3/8" tbg. SDON.

6/27/19 (BH & INT 0#) TIH w/3-7/8" csg scraper to 3800'. TOOH w/scraper. TIH w/4-1/2" CIBP set @ 3760'. Circ clean & test csg to 560#/15 mins, good. TOOH. RU W/L. Perf sqz holes @ 3538'. RD W/L. Attempt to circ dwn 4.5" up 7" annulus, no circ. SDON.

6/28/19 (BH & INT 0#) Verbal approval from Brandon Powell, NMOCD & Joe Killins, BLM to cmt sqz @ **3138'**. RU W/L. Perf sqz holes @ 3138'. RD W/L. TIH w/4.5" CR set @ 3200'. Est circ dwn 4.5" & out 7" intermediate. RU cmters. Mix & pump 66 sx (75 cf - 13 bbls) = 1.14 yld cement @ 15.8 PPG. Displace w/15 bbls wtr. Sting out of CR. Reverse circ clean. Set tbg @ 3150'. Pump 15 sx (17 cf - 3 bbls) = 1.14 yld cement plug @ 15.8 PPG. Displace w/11 bbls wtr. PUH to 2500'. Reverse circ clean. Open 7" INT flow back 3/4 bbl to balance plug. RD cmters. SDON.

7/1/19 (BH & INT 0#) TOOH. TIH w/3-7/8" bit, tag cmt @ 3016'. PT csg to 560#/15 mins, good. Swivel dwn & circ. D/O cmt to 3140'. Drop dwn & tag CR @ 3200'. Circ wellbore clean. Perform MIT on csg to 600#, pressure dropped 20# in 3 mins, failed. TOOH w/bit. TIH open ended to 3150'. SDON.

7/2/19 (BH & INT 0#) RU cmters. Mix & pump 18 sx (14.8 cf - 2.6 bbls) = .82 yld Micro seal blend cement plug @ 13 PPG. Displace w/11 bbls wtr. PUH to 2500'. Reverse circ clean. RD cmters. TOOH. Pressure up on 4.5" to 600#. SI well w/600#. SDON.

7/6/19 (BH & INT 0#) TIH w/3-7/8" bit, tag cmt @ 3020'. Swivel dwn & D/O cement to 3142', drop dwn to CR @ 3200'. Perform csg MIT to 600#/30 mins, test good. D/O CR @ 3200', drop dwn & tag cement @ 3240'. D/O cement dwn to 3370'. Circ well clean. PUH. SDON.

7/7/19 (BH & INT 0#) TIH, continue D/O cement plug to 3542'. Drop dwn to CIBP @ 3760'. Circ well clean. PT csg to 560#, pressure dropped to 80# in 1 min. TOOH. RU W/L. Run CBL from 3760' to surface. RD W/L. SDON.

7/8/19 (BH & INT 0#) Verbal approval from Brandon Powell, NMOCD to suicide sqz @ 3370' & 3250'. RU W/L. Perf sqz holes @ 3370'. Pull up. Perf sqz holes @ 3250'. RD W/L. TIH w/tbg open ended to 3548'. RU cmters. Mix & pump 6 sx (7 cf - 1.3 bbls) = 1.15 yld cement @ 15.8 PPG. Displace w/12 bbls wtr. RD cmters. TOOH w/tbg. TIH w/CR, set @ 3260'. RU cmters. Est rate thru sqz perfs. Mix & pump 28 sx (32 cf - 5.8 bbls) = 1.15 yld cement @ 15.8 PPG. Displace w/11 bbls wtr. Sting out of CR. PUH to 2900'. Reverse circ wellbore clean. RD cmters. TOOH. SDON.

Continued on Page 2

7/9/19 (BH & INT 0#) TIH w/3-7/8" bit, tag cement @ 3230'. Swivel dwn & D/O cmt to CR @ 3260'. PT csg to 580#/15 mins, good. Continue to D/O CR & cmt dwn to 3372'. Circ wellbore clean. PUH. PT csg to 580#/15 mins, good. SDON.

7/10/19 (BH & INT 0#) Verbal CBL cmt isolation approval from Brandon Powell, NMOCD & Joe Killins, BLM - needs passing MIT. PT csg to 580#, pressure dropped 80# in 30 mins. TOOH w/bit. RU W/L. Run CBL from 4460' to surface. RD W/L. TIH w/tbg open ended to 3380'. RU cmters. Mix & pump 14 sx (16 cf - 2.9 bbls) 1.15 yld cement @ 15.8 PPG. Displace w/11.5 bbls wtr. RD cmters. PUH to 3150'. Circ wellbore clean. TOOH. Pressure up to 500#. SIW. SDON.

7/11/19 (BH & INT 0#) PT csg to 580#, pressure dropped 13# in 15 mins. TIH w/3-7/8" bit, tag cement @ 3235'. TOOH w/bit. ND BOP. NU frac 7" 5K frac head. PT seal on frac head to 2000#, good. PT 4.5" csg to 580#, pressure dropped 13# in 15 mins. TIH w/3-7/8" bit, tag cement @ 3235'. D/O cmt plug from 3235' to 3380'. PT 4.5" csg to 580#, pressure dropped 20# in 10 mins. TOOH w/bit. TIH w/tbg open ended to 3380'. SDON.

7/12/19 (BH & INT 0#) RU cmters. Pre-flush 5 bbls wtr. Mix & pump 45 sx (34 cf - 6 bbls) .76 yld cement plug @ 13.5 PPG. Displace w/11 bbls wtr. RD cmters. TOOH. Pressure up on cmt plug to 580#. SIW. SDON.

7/15/19 (BH & INT 0#) TIH w/3-7/8" bit, tag cmt @ 3120'. Swivel dwn & D/O cement to 3380'. Circ wellbore clean. **Perform 4.5" csg MIT to 570#/30 mins, passed - witnessed by NMOCD.** Drop dwn tag cmt @ 3460'. Swivel dwn & D/O cmt plug to 3550'. Drop dwn to CIBP @ 3760'. Circ wellbore clean. TOOH w/bit. RU W/L. Perf Pictured Cliffs @ 3594, 3593, 3571, 3570, 3569, 3560, 3559, 3558, 3553, 3552, 3551, 3550, 3538, 3537 (2 SPF) for a total of 28, 0.34" dia holes. RD W/L. SDON.

7/16/19 (BH & INT 0#) TIH w/2-7/8" P110 frac string & pkr, land @ 3503'. ND BOP. NU 10K frac stack. PT csg from pkr to surface 560#/20 mins, good. PT frac string to 9000#/30 mins, good. TIH w/sand line, punch out mag disc on frac string. Pump into PC perfs w/rig pump. SIW. RD. Rig released.

8/26/19 (BH & INT 0#) RU frac crew. Broke down well with water & 500 gal 15% HCL. Foam FRAC'D Pictured Cliffs w/151,540# 20/40 sand & 34,291 gal 20# Inr gel & 1.10 million SCF N2 70 quality. avg rate = 40 BPM, avg PSI = 6870. RD frac crew. RU flowback. Flowback overnight.

8/29/19 (BH & INT 0#) MIRU. ND frac stack. NU BOP & PT, test good. Kill well w/wtr. Rls pkr & TOOH laying down 2-7/8" frac string & pkr. TIH w/3-7/8" bit to 3500'. SDON.

Continued on Page 3

8/30/19 (BH & INT 0#) TIH, tag fill @ 3610'. Est circ & CO to CIBP @ 3760'. Circ well clean. Flow well. D/O CIBP. PUH w/bit to 3500'. SIW. SDON.

8/31/19 (BH & INT 0#) TIH, tag fill @ 7881'. CO to PBTD @ 7941'. TOOH w/3-7/8" bit. TIH w/BHA, tag PBTD @ 7941'. PUH, PT tbg to 500#, test good. Unload well. SDON.

9/3/19 (BH & INT 0#) Land 242 jts 2-3/8" 4.7# J-55 EUE T&C upset tubing @ 7848', SN @ 7846'. ND BOP. NU WH. RD. Rig released.

Well is now producing as Gobernador Pictured Cliffs/Blanco Mesaverde/Basin Dakota tri-mingle under DHC4999.

