Submit One Copy To Appropriate District Office	rict State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.
District II	OIL CONSERVATION DIVISION		30-045-27167
811 S. First St., Artesia, NM 88210 <u>District III</u>	1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE   FEE   □
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B10894-12
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Jake Johnson
1. Type of Well: Oil Well Gas Well Other			8. Well Number 001
2. Name of Operator DJR Operating, LLC	NMOCD		9. OGRID Number 149052
3. Address of Operator	406 <b>1 3 2019</b>		10. Pool name or Wildcat
1 Road 3263 4. Well Location			Bisti Lower Gallup
4. Well Location  Unit Letter L: 1650 feet from the South line and 990 feet from the West line			
Section 32 Township 25N Range 11W NMPM County San Juan			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6442' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	I JOB
OTHER:			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. — Well clear not filled and leveled. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. — Location has not been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. — Location has not been leveled and cleared of trash			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD rules and where pump jack had been			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines			
All other environmental concerns have been addressed as per OCD rules. — and where pump jack had been Marker Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. — Pipe with valve sticking up out of grown on North side of location. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURETITLE Regulatory Specialist DATE 08/12/2019			
TYPE OR PRINT NAME Shaw-Marie Ford E-MAIL: sford@djrllc.com PHONE: (505) 632-3476 Ext. 219  For State Use Only			

APPROVED BY:\_\_\_\_\_ Conditions of Approval (if