Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

Lease Serial No.

NMSF080675

	o (i ii z) i oi oii oii opoonioi	
SUBMIT IN TRIPLICATE - Ot	7. If Unit or CA/Agreement, Name and/or No. 8910010540	
Type of Well Oil Well		8. Well Name and No. SAN JUAN 27-4 UNIT 37
Name of Operator HILCORP ENERGY COMPANY E-Mail: et	9. API Well No. 30-039-06781-00-C1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505-324-5161	10. Field and Pool or Exploratory Area BASIN DAKOTA BS MESA GALLUP
4. Location of Well (Footage, Sec., T., R., M., or Survey De	escription)	11. County or Parish, State
Sec 33 T27N R4W SESW 0990FSL 1550FWL 36.525375 N Lat, 107.259338 W Lon		RIO ARRIBA COUNTY, NM
12 CHECK THE ADDRODDIATE DO	OV(EC) TO INDICATE MATURE OF NOTI	CE DEPORT OF OTHER DATA

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Acidize ☐ Deepen ☐ Prod		☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair ☐ New Construction		Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
BP	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle the existing Gallup/Dakota formations. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.

NOV 1 4 2019

HOLD C104 FOR DIC DISTRICT 111

14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #491643 verifie For HILCORP ENERGY COMP Committed to AFMSS for processing by JO	ANY. S	ent to the Farmington	
Name (Printed/Typed)		Title	OPERATIONS REGULATORY TECH SR	
Signature	(Electronic Submission)	Date	11/08/2019	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
	OFFMAN	TitleF	ETROLEUM ENGINEER	Date 11/14/201

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Office Farmington



District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

<u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 274380

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-06781	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
319210	SAN JUAN 27 4 UNIT	037
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	7131


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
N	33	27N	04W		990	S	1550	w	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00 W/2		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trufillo

Title: Operations/Regulatory Tech Sr

Date: 11/08/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

5/27/1965

Certificate Number:

1760



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 37 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 8,325'.
- 3. Set a 5-1/2" plug at +/- 7,615' to isolate the Gallup.
- 4. Load the hole and perform MIT (Pressure test to 560 psi). Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 5. RU W/L. Run CBL, record TOC.
- 6. Set a 5-1/2" plug at +/- 6,650'.
- 7. Load the hole and pressure test the casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesaverde formation (Top Perforation @ 5,500'; Bottom Perforation @ 6,500').
- 10. If needed, isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out any plugs above the Gallup isolation plug.
- 13. Clean out to Gallup isolation plug.
- 14. Drill out Gallup isolation plug and cleanout to PBTD of 8,324'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Gallup/Mesaverde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 37 MESA VERDE RECOMPLETION SUNDRY

