	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. JIC105		
					6. If Indian, Allottee or Tribe Name JICARILLA APACHE		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well					8. Well Name and No. JICARILLA A 5		
Oil Well Image: Contact: ETTA TRUJILLO 2. Name of Operator Contact: ETTA TRUJILLO					9. API Well No.		
HILCORP ENERGY COMPANY E-Mail: ettrujillo@hilcorp.com 3a. Address 3b. Phone No. (include area code)					30-039-06419-00-S1 10. Field and Pool or Exploratory Area		
382 ROAD 3100 AZTEC, NM 87410	Ph: 505-32			ТАРАСІТО			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 23 T26N R4W NENE 93 36.476718 N Lat, 107.215606			RIO ARRIBA COUNTY, NM				
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
□ Notice of Intent	□ Acidize	Dee	pen	Product	ion (Start/Resume)	□ Water Shut-Off	
	□ Alter Casing	🗖 Hyd	Iraulic Fracturing	Reclam	ation	U Well Integrity	
Subsequent Report	Casing Repair		v Construction	Recomp		□ Other	
□ Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abandon g Back	□ Tempor □ Water I	arily Abandon		
13. Describe Proposed or Completed Op					-	vimate duration thereof	
Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for The subject well was P&A'd o schematic.	d operations. If the operation res bandonment Notices must be file final inspection.	sults in a multip ed only after all	le completion or reco requirements, includ	mpletion in a ing reclamatio	new interval, a Form 316 n, have been completed a	0-4 must be filed once	
			··· ··· ··· ···	MACD	Na Beaux, Jryslan a 1		
	NMOCD						
	JAN 02 2020						
DISTRICT III							
14. I hereby certify that the foregoing i	Electronic Submission #4	NERGY COM	PANY, sent to the	Rio Puerco			
Name (Printed/Typed) ETTA TRUJILLO			Title OPERATIONS REGULATORY TECH SR				
Signature (Electronic	Submission)		Date 01/02/20	020			
	THIS SPACE FO				SE		
Approved By ACCEPT	FD		JOE KILLII TitlePETROLE			D / 01/00/00	
Approved By Conditions of approval, if any, are attach certify that the applicant holds legal or ec						Date 01/02/202	
which would entitle the applicant to cond Title 18 U.S.C. Section 1001 and Title 43	Office Rio Puer		ake to any department or	agency of the United			
States any false, fictitious or fraudulent (Instructions on page 2)	·		0				
** BLM REV	ISED ** BLM REVISED	D ** BLM R	EVISED ** BLN		0 ** BLM REVISEI	D **	
			12			6	

6

API: **30-039-06419** Well Name: Jicarilla A 5 Plugged & Abandoned Notification

Received verbal approval from Joe Killins (BLM), Brandon Powell (NMOCD) and Orson Harrison (JOGA) for the following notification:

12/11/2019 – On the Jicarilla A 5, Hilcorp will pump plug #1 (Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo Tops), as planned. For plug #2 (Nacimiento Top), BLM and NMOCD have two different Nacimiento tops. BLM's Nacimiento top is @ 2239' and NMOCD's Nacimiento Top is @ 2,100'. Therefore, Hilcorp will shoot squeeze perfs @ 2289' and set a CICR @ 2239'. Hilcorp will squeeze 125 sx beneath CICR (100% excess) behind pipe with an estimated TOC @ 2,050' and BOC @ 2289'. Hilcorp will sting out and spot a balance plug from the CICR @ 2239' up to 2,050' (46 sx, 200' excess). BLM & NMOCD gave approval to sting out of the cement retainer and spot a balance plug for adequate Nacimiento cement coverage if Hilcorp locks up at any point during the squeeze job.

Hilcorp Energy Company PO Box 4700

Farmington, NM 87499



Name: Jicarilla A 5 API:30-039-06419

Well Plugging Report

Work Detail

Plug #1 Pictured Cliffs, 5-1/2" CSG Shoe, Fruitland & Ojo Tops 3873'-3000' Mix & Pump 130 SXS, 15.8 PPG, 1.15 Yield, 149.5 CUFT, 26.6 BBL Slurry, Class G Cement, leaving 40 SXS below CR to cover 50' below CSG Shoe & 50' inside 5-1/2" CSG, leaving 90 SXS above CR, DISP W/ 11 BBL H2O.

Plug #2 Nacimiento Top 2239'-1900' Mix & Pump 42 SXS, 15.8 PPG, 1.15 Yield, 48.3 CUFT, 8.6 BBL Slurry, Class G Cement, DISP W/ 6 BBL H2O.

Plug #3 Surface 206'-0' Mix & Pump 80 SXS, 15.8 PPG, 1.15 Yield, 92 CUFT, 16.3 BBL Slurry, Class G Cement, saw good Cement Returns to Pit.

Surface Top Off Mix & Pump 25 SXS, 15.8 PPG, 1.15 Yield, 28.7 CUFT, 5.1 BBL Slurry, Class G Cement.

12/10/2019

Load supplies, travel to LOC. Install Tire Chains on Equip, Road Rig & Equip to LOC. HSM on JSA. Spot Equip, (small LOC) RU Daylight Pulling Unit. Check PSI 2-3/8" TBG-0, 5-1/2" CSG-0, BH-0 PSI, RU Relief Lines, open Well to Pit. ND WH, Function Test & NU BOP, RU Work Floor. PU on Hanger, PU to 50K, had to work TBG free. LD 130 2-3/8" JTS on Pipe Trailer. MU 5-1/2" Watermelon Mill, PU & Tally In Hole to 3776', TOOH, LD Mill. Secure Well & LOC. Travel to Yard.

12/11/2019

Load supplies, travel to LOC. HSM on JSA, service & start Equip. Check PSI TBG-N/A, CSG-0, BH-0 PSI, open Well to Pit. MU 5-1/2" TBG Set CR, TIH to 3776', set CR. Load Well W/ 31 BBL H2O, CIRC 96 BBL total, saw good Returns to Pit, attempt to PSI Test CSG to 600 PSI, no Test, BD 150 PSI in 2 MINS. TOOH, LD Setting Tool. RU A-Plus WL, RIH to 3773', run CBL, POOH, LD Tool, RD WL. MU Setting Tool, TIH to 3773', load well W/ 4-1/2 BBL, S/I CR, check ROI, 1-1/2 BPM @ 100 PSI. LD 25 JTS on Pipe Trailer, TOOH, LD Setting Tool. Secure Well & LOC. Travel to Yard.

12/12/2019

Load supplies, travel to LOC.

HSM on JSA, service & start Equip.

Check PSI TBG-0, CSG-0, BH-0 PSI, open Well to Pit.

TIH, Tag Plug #1 @ 3065', good Tag. Load Well W/ 13-1/2 BBL H2O, attempt to PSI Test CSG to 600 PSI, no Test, LD to next Plug, TOOH.

RU A-Plus WL, TIH to 2289', shoot 3 Holes W/ 3-1/8" Tag Gun, POOH, LD Tool, RD WL.

MU 5-1/2" TBG Set CR, TIH to 2339', set CR, S/O load Well W/ 1/2 BBL, PSI Test CSG to 600 PSI, good Test, S/I check ROI Pump 1/2 BBL to 600 PSI Lockup, no Rate, S/O.

Plug #2 Nacimiento Top 2239'-1900' Mix & Pump 42 SXS, 15.8 PPG, 1.15 Yield, 48.3 CUFT, 8.6 BBL Slurry, Class G Cement, DISP W/ 6 BBL H2O.

LD Work String, LD Setting Tool.

RU A-Plus WL, RIH to 206', shoot 4 Holes W/ 3-1/8" Tag Gun, POOH, LD Tool, check ROI 2 BPM @ 100 PSI, CIRC 21 BBL, saw good Returns to Pit, RD WL. RD Work Floor, ND BOP, NU WH, dig out Cellar.

Plug #3 Surface 206'-0' Mix & Pump 80 SXS, 15.8 PPG, 1.15 Yield, 92 CUFT, 16.3 BBL Slurry, Class G Cement, saw good Cement Returns to Pit.

Perform Hot Work Permit, cut off WH, TOC @ 4' below Surface in 5-1/2" CSG, 30' in 5-1/2" X 9-5/8" Annulus, Install & Weld DH Marker @ LAT 36.476601, LONG - 107.215639.

Surface Top Off Mix & Pump 25 SXS, 15.8 PPG, 1.15 Yield, 28.7 CUFT, 5.1 BBL Slurry, Class G Cement.

RD Daylight Pulling Unit.

Clean & Secure LOC.

Travel to Yard.

On Site Reps:

Name	Association	Notes
Mark Decker	BLM	On Loc
Juan Cardenas	Co. Rep.	On Loc
Rio Rig Crew	Other	On Loc



