Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 20
Lease Serial No.
NMNM62969

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals

6 If Indian Allottee or Tribe Name

5.

abandoned we	o. If Indian, Anottee o	i Titoe Name						
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No. NMNM120525						
Type of Well	ner: COAL BED METHAN			8. Well Name and No. TSAH TAH 3 2				
Name of Operator JUNIPER RESOURCES EXP	Contact: L COMPÆNNáil: adam.mar	TINEZ urces.com		9. API Well No. 30-045-34551-00-S1				
3a. Address 3333 LEE PKWY SUITE 210 DALLAS, TX 75219		o. (include area code) 20-6112		Field and Pool or Exploratory Area BASIN FRUITLAND COAL				
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	1)			11. County or Parish,	State		
Sec 3 T24N R10W SENW 145 36.346426 N Lat, 107.887550				SAN JUAN COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF SUBMISSION				TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Production	on (Start/Resume)	■ Water Shut-Off		
	☐ Alter Casing	□ Нус	Iraulic Fracturing	☐ Reclama	tion	■ Well Integrity		
Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recompl	ete	Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug	g and Abandon		rily Abandon			
	☐ Convert to Injection	☐ Plug	ig Back Water Dis		isposal			
13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. JUNIPER RESOURCES REQUESTS APPROVAL TO TEMPORARILY ABANDON THE WELLBORE UNTIL IMPROVED ECONOMIC CONDITIONS MERIT RETURNING WELL TO PRODUCTION. OPERATIONS REPORT: 7/30/19- MIRU WORKOVER RIG, LD PUMP, RODS, TOOH W/TBG, PU BIT AND SCRAPER RUN TO 1738?, TOOH, PU SETTING TOOL AND CIBP, TIH SET CIBP @1510?, 50? ABOVE TOP PERF, (PERFS 1560'-1725') LOAD CSG WITH WATER AND INHIBITOR, PT TO 500# FOR 15 MIN ? HELD. SDFN. PROVIDE 24 HRS NOTICE: JOE KILLENS (BLM) AND BRANDON POWELL (NMOCD) OF UPCOMING MIT TEST 8/1/19- PERFORM MIT- PT TO 560 PSIG FOR 30 MIN, RECORDED ON 1 HR CHART, TEST PASSED, WITNESSED BY THOMAS VERMERSCH (NMOCD) PERFORM BRADENHEAD TEST, PASSED. SEE ATTACHED PIN CHART OF MIT TEST								
Cor	d by the BLM Well OMPANY, sent to HN HOFFMAN on	the Farming 08/30/2019 (1	ton	NMOCD				
Name (Printed/Typed) ADAM MA	RTINEZ	Title FIELD M	IANAGER					
Signature (Electronic S	ubmission)	Date 08/22/20	119		JAN 24 2020			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
_Approved_By_ACCEPT	JOHN HOF TitlePETROLEU		ER	Date 08/30/2019				
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduction	itable title to those rights in the ct operations thereon.	Office Farmington						
Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



