Form 3160-5 (June 2015)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						JIC40  6. If Indian, Allottee or Tribe Name JICARILLA APACHE			
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No.								
Type of Well     Gen Well     Gen Well     Gen Well	8. Well Name and No. ELK 301H								
☐ Oil Well ☑ Gas Well ☐ Oth  2. Name of Operator	9. API Well No. 30-039-31370-00-X1								
DJR OPĖRATING LLC		10. Field and Pool or Exploratory Area							
3a. Address 1600 BROADWAY SUITE 160 DENVER, CO 80202	Ph: 505.632	(include area code) .3476		OTERO					
4. Location of Well (Footage, Sec., T.		11. County or Parish, State							
Sec 36 T24N R5W NWSW 18 36.265152 N Lat, 107.319038	RIO ARRIBA COUNTY, NM								
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE,	REPORT, OR OT	THER DATA			
TYPE OF SUBMISSION									
Notice of Intent  ■ Notice of Intent	☐ Acidize	□ Deep	en	☐ Product	ion (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hydr	aulic Fracturing	☐ Reclama	ation	■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	□ New	Construction	□ Recomp	olete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	☐ Change Plans ☑ Plug and Abandon ☐			porarily Abandon				
60	☐ Convert to Injection	on Plug Back Water I			Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  DJR?s original intent was to drill the Elk 301H to 7? intermediate casing point prior to suspending the well to allow study of the core and logs. There is strong evidence of wellbore instability in the Kirtland and Fruitland intervals, from about 2000 to 2200-ft.  This instability makes it unlikely that the build curve could be drilled and cased in this well.  DJR?s current plan is to drill the well to the Lower Mancos and run wireline logs. Following that, the well will be plugged and abandoned. Five balanced cement plugs are proposed, as per the attached schematic.  After moving the rig off, a final surface plug will be set with a spudder rig, the well head will be removed, and the 9-5/8? casing stub will be cut off below grade. A dry hole cap and marker will be installed.									
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	502372 verified	by the BLM Wel	I Information	System				
C	For DJR OP committed to AFMSS for pr	PERATING LLC, occessing by JC	sent to the Rio	Puerco 2/07/2020 (20	JK0025SE)				
	RIE FORD			ATORY SPE					
Signature (Electronic S			Date 02/07/20						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									

\_Approved By\_JOE KILLINS \_\_\_\_\_\_ TitlePETROLEUM ENGINEER Date 02/07/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Rio Puerco

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





### PROPOSED P&A

Well Elk #301H Location 921' FWL 1866' FSL S36 T24N RSW
API # 30-039-31370
By C Mallary
Date 2/6/2020

Casing 9-5/8" shoe	<u>Depth</u> 366	Plug #5	Plug #5 From 250	To 550	Height (ft) 300	Volume (bbls) 22.7	Excess 70%	Total Cmt (bbls) 38.5
Formation Ojo Alamo  Formation Pictured Cliffs	Depth 1902 Depth 2355	Plug #4	Plug #4 From 1700	To 2450	Height (ft) 750	Volume (bbls) 55.8	Excess 20%	Total Cmt (bbls) 66.9
<u>Formation</u> Chacra	<u>Depth</u> 3154	Plug #3	Plug #3 From 2900	To 3400	Height (ft) 500	Volume (bbls) 37.2	Excess 20%	Total Cmt (bbls) 44.6
<u>Formation</u> Menefee	<u>Depth</u> 3934	Plug #2	Plug #2 From 3800	To 4300	Height (ft) 500	Volume (bbls) 37.2	Excess 20%	Total Cmt (bbls) 44.6
Formation Gallup A Gallup C	<u>Depth</u> 5591 5746	Plug #1	Plug #1 From 5350	To 6100	Height (ft) 750	Volume (bbis) 55.8	Excess 20%	Total Cmt (bbls) 66.9
Formation Lower Mancos	Depth 6011					Total Cen	nent (bbls)	261.7
TD	6131						a de	

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Elk 301H

### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. BLM picks top of Nacimiento SS at 850. Add plug to ensure coverage 750' to 900'.

## GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following minimum general requirements.
  - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
  - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
  - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
  - 4.1 The cement shall be as specified in the approved plugging plan.
  - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.3 Surface plugs may be no less than 50' in length.
  - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
  - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
  - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
  - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
  - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
  - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
  - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
  - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain  $H_2S$ .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.