Form 3160-5 (June 2015)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

Lease Serial No. NMSF078439

abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No.	
Type of Well  ☐ Gas Well  ☑ Other: UNKNOWN MW		8. Well Name and No. JOHNSTON FEDERAL 22	
2. Name of Operator Contact: PRISCILLA SHORTY HILCORP ENERGY COMPANY E-Mail: pshorty@hilcorp.com		9. API Well No. 30-045-26940-00-S1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505-324-5188	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State	
Sec 33 T31N R9W NWNE 1077FNL 1683FEL 36.858930 N Lat, 107.782230 W Lon		SAN JUAN COUNTY, NM	

#### 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity	
	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
BP	☐ Convert to Injection	☐ Plug Back	■ Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy Company requests permission to perform a MIT on the subject well per the attached procedure and wellbore schematic.

DISTRICT III

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #505047 verified by the BLM Well Information System  For HILCORP ENERGY COMPANY, sent to the Farmington  Committed to AFMSS for processing by JOHN HOFFMAN on 03/02/2020 (20JH0118SE)						
Name (Printed/Typed)	PRISCILLA SHORTY	Title OPERATIONS REGULATORY TECH SR				
Signature	(Electronic Submission)	Date	03/02/2020 STATE OFFICE USE			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
_Approved_By_JOHN_HOFFMAN		TitleP	ETROLEUM ENGINEER	Date 03/02/2020		
certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease icant to conduct operations thereon.	Office	Farmington			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



# Hilcorp Energy JOHNSTON FEDERAL 22 POW Expense - MIT API: 3004526940

Lat 36.85893 N

Long -107.78222 W

### **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify Cathodic turned off. NOTE: Notify the NMOCD at least 24 hours prior to starting the actual MIT test. Test must be witnessed by NMOCD
- 2. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Ops Engineer.
- 3. Load the casing with corrosion inhibited fluid (i.e. packer fluid) if necessary.
- 4. Pressure test the casing in accordance with NMOCD standards with required witness present.
- 5. Notify Operations Engineer and submit test results to HEC Regulatory Technicians as quickly as possible. RDMO.

