



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

June 25, 2003

John Byrom
D J Simons Inc.
PO Box 1469
Farmington NM 87499

RE: L V Hamner B 1B, H 29-29N-09W API 30-045-29980

Dear Mr. Byrom:

The Bradenhead test on the above well indicates a failure. Provide information on where the pressure on the intermediate is originating. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to retest and initiate remedial activity before September 15, 2003.

Reference RBDMS CTP0317564016 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File