In Lieu of Form 3160 (June 1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Tribe Name

(Note: Report results of multiple completion on Well Completion or Recompletion Report

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

 Lease Designation and Serial No. NMSF-078765.

TITLL G MOO GOOT	OOB 6 JUN 9 Indi	mpAllottee	G
------------------	------------------	------------	---

			0011 2 111 11 11
	SUBMIT IN T		7. REGENVEDA, Agreement Designation 070 FARMINGTON NM
1.	Type of Well Oil Well Gas Well X Other	Nun 2008	8. Well Name and No. ROSA UNIT #180B
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	OF COLOR S	9. API Well No. 30-045-33134
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (10. Field and Pool, or Exploratory Area BLANCO MV
4.	Location of Well (Footage, Sec., T., R., M., or 1900' FSL & 845' FWL, NW/4 SW/4 SEC 09	•	11. County or Parish, State SAN JUAN, NM
	CHECK APPROPRIAT	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
	TYPE OF SUBMISSION	ТҮРЕ	OF ACTION
	Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
	X Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off
	Final Abandonment	Casing Repair Altering Casing Other Drilling Completion	Conversion to Injection Dispose Water

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

05-04-2006 MIRU, mix spud mud, PU MM & bit. Drill rate & mouse holes. Spud well @ 0130 hrs, 5/4/06. Drilling 12 1/4" surface hole from 0' to 135'.

<u>05-05-2006</u> Rotary drilling 12 ¼" surface hole from 135' to 340', POOH, stand back DC's in derrick, LD shock sub & bit. RU csg crew, RIH w/ 7 jts, 9 %", 36#, K-55, ST&C csg, total length = 311', set @ 325'. Centralizers on 1st 3 jts, Texas pattern guide shoe on bottom & float insert on top of 1st jt. Circulate csg, RD csg crew. RU cementers, cmt surface csg as follows: 150 sxs (212 cu.ft.) Type III cmt + 2% CaCl2 + .25#/sx Cello Flake + 24.42 bbls FW = 37.72 bbls slurry @ 14.5 ppg (YLD =1.41 / WGPS = 6.84) Displace w/ 21.8 bbls FW, bump plug 100 psi to 350 psi, check float, good cmt job. 21 bbls cmt returns to surface.

<u>05-06-2006</u> Test BOP & choke manifold, all related equipment & lines @ low test 250 psi for 5 mins & high test 1500 psi for 10 mins, test csg @ 1500 psi for 30 mins, all tested good. PU bit & MM, re-drill rat & mouse holes, both filled w/ cmt from surface csg cmt job. PU MM & bit, RIH w/ BHA, tag TOC @ 279'. Drill cmt, insert float, cmt, guide shoe from 279' to 325', CO from 325' to 340'. Drill 8 ¾" hole from 340' to 1200'.

Continued on Back

	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

JUN 1 2 2006







05-07-2006 Rotary drill 8 3/4" hole from 1200' to 2218', bit quit drilling, POOH for bit change.

<u>05-08-2006</u> POOH, change bit, test MM, still in good condition. PU new 8 ¾" bit & 6 ½" shock sub, TIH, tag bridge @ 2118', wash & ream from 2118' to 2218'. Begin rotary drilling 8 ¾" hole from 2218' to 2752'.

05-09-2006

Recap: Rotary drilling 8 3/4" hole from 2752' to 3500'.

<u>05-10-2006</u> Rotary drilling 8 ¾" hole from 3500' to 3625', TD of 8 ¾" section. Circulate hole clean, condition mud & hole. POOH, RU loggers, run open hole logs with Halliburton, loggers depth @ 3629', RD loggers. RIH to 3625', hole is in good condition. Circulate hole clean & condition mud & hole @ 60 sec vis.

05-11-2006 POOH, LD BHA, DC's, shock sub & bit. RU csg crew, RIH w/ 91 jts (3598') 7", 23#, J-55, LT&C csg, land @ 3613' as follows: guide shoe, 1 jt csg, insert float, 90 jts csg, mandrel, landing jt, circulate csg while waiting on cementers. RD csg crew, RU cementers. Cmt 7" as follows: Lead = 520 sxs (1092 cu.ft.) Premium Light cmt + 8% Bentonite + 1% CaCl2 + 4% Phenoseal + ½#/sx Cello Flake + 141.87 bbls FW = 194 bbls slurry @ 12.1 ppg. (Yield = 2.10 / WGPS = 11.46). Tail = 50 sxs (70 cu.ft.) Type III cmt + 1% CaCl2 + ½#/sx Cello Flake + 8.12 bbls FW = 12.48 bbls slurry @ 14.5 ppg. (Yield = 1.40 / WGPS = 6.82). Displace w/ 140 bbls FW. Bump plug from 1070 psi to 1576 psi, hold 1576 psi for 10 mins, csg test good. Release PSI, check float, float held OK. 50 bbls cmt returns to surface, good cmt job. RD & release cementers. WOC, prepare to drill 6 ½" air section of well.

<u>05-12-2006</u> WOC, PU & test air hammer, PU BHA, RIH, tag cmt @ 3532', drill cmt, float, cmt & shoe from 3532' to 3613', CO from 3613' to 3625'. Air hammer drilling 6 ¼" section from 3625' to 4670'.

05-13-2006 Air hammer drilling 6 1/4" section from 4670' to 5875'.

<u>05-14-2006</u> Air hammer drilling 6 ¼" section from 5875' to 6130', blow well clean, circulate with air. TOOH, RU loggers, run logs w/ Halliburton logging, RD loggers, prepare to run 4 ½" liner.

<u>05-15-2006</u> Circulate w/ air, blow well clean. POOH, std back 55 stds DP to run liner on, LD remaining DP, clean out BHA & bit. RU csg crew, run 4 ½" liner, guide shoe, pup shoe jt, insert float, 19 jts csg, pup marker jt, 37 jts csg, hanger, setting tool = 2654.18'. 58 jts 4 ½", 10.5#, J-55, LT&C csg = 2634.28', RD csg crew. Finish running 4 ½" csg liner on DP, TD of well @ 6130', land csg @ 6122' shoe depth = TOL @ 3476' = 137' of overlap into 7" intermeditate csg. Circualte csg with air, RU cementers. Cmt 4 ½" csg as follows: Lead: 50 ssxs (129 cu.ft.) Premium Light HS cmt + 1% FL52 + .2% CD32 + 3#/sx cse + 17.57 bbls FW = 22.9 bbls slurry @ 11.6 ppg. (yield = 2.58 / WGPS = 14.81). Tail: 200 sxs (430 cu.ft.) Premium Light HS cmt + 1% FL52 + .2% CD32 + 3#/sx cse + .25#/sx Cello Flake + 4% Phenoseal + 53.7 bbls FW = 76.5 bbls slurry @ 12.3 ppg. (yield = 2.15 / WGPS = 11.29) Run 10 bbls gel spacer & 10 bbls water spacer @ front. Displace w/ 79.5 bbls FW. Bump plug 650 psi to 1280 psi, plug down @ 1917 hrs, check float, good. 45 bbls cmt returns to surface. Sting out w/ DP, RD & release cementers. POOH, LD remaining DP used to run liner, ND BOP & clean mud pit. Rig released @ 0300 hrs, 05/15/06.