

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89


OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088



WELL API NO.	30-031-20706
Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name SANTA FE PACIFIC RAILROAD
1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER:	8. Well No. 48	
2. Name of Operator ROBERT L. BAYLESS	9. Pool name or Wildcat Miguel Creek Gallup	
3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499		
4. Well Location Unit Letter L : 2310 Feet from the SOUTH Line and 990 Feet from The WEST Line Section 21 Township 16N Range 6W NMPM MCKINLEY County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6443 GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOE <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Robert L. Bayless plugged and abandoned this well 5/13/03. The procedure is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom McCarthy TITLE ENGINEER DATE 6/25/03
TYPE OR PRINT NAME Tom McCarthy TELEPHONE NO. (505) 327-2659

(This space for State Use)
APPROVED BY H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE JUL 31 2003

CONDITIONS OF APPROVAL, IF ANY:

7-31-03

Robert L. Bayless
Plug and Abandon Procedure
SFPRR No. 48

2310' FSL & 990' FWL, Section 21, T16N, R6W
McKinley County, NM

5/12/2003: Rig up JC Well Service. Pressure test tubing with rods and pump in hole. Tested OK. Trip out rods and pump, and used rod count as tally. Tag PBD at 856'. Roll hole with water. Mix and spot 30 sack bottom plug at 856'. Trip out tubing and WOC.

5/13/2003: Tag plug at 720'. Pressure test of casing to 200 PSI was OK. Perforated squeeze holes at 100'. Mix and pump 42 sacks cement. Circulated cement up casing and up backside. Rigged down. Class B cement was used.

Top off cement in both casings. Installed abandonment marker and backfilled pit. Cleaned up location.