Office State of New Mexico	1.01m C-103
Office District I 1625 N French Dr. Hobbs NM 88240	es May 27, 2004
Office District I 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 State of New Mexico Energy Minerals and Natural Resource State of New Mexico Energy Minerals and Natural Resource State of New Mexico Energy Minerals and Natural Resource 1220 South St. Francis Dr. Santa Fe. NM 87505	
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 DISTRICT II DIST	N 30-045-10894
1301 W. Grand Ave., Artesia, NM 88210	3. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 T220 South St. Francis Dr. Santa Fe NM 87505	STATE FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	A. Gross
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	# 1
2. Name of Operator	9. OGRID Number
Synergy Operating, LLC	163458
PO Box 5513	10. Pool name or Wildcat
Farmington, NM 87499 (505-325-5449)	Basin Dakota
	Dushi Dukota
4. Well Location	
Unit Letter K : 1650' feet from the South line and	d1850'feet from theWestline
Section 9 Township 31N Range 13V	V NMPM County: San Juan
11. Elevation (Show whether DR, RKB, RT, G	R, etc.)
Pit or Below-grade Tank Application Or Closure	MANAGEMENT OF THE PROPERTY OF
Pit type Reserve-Lined Depth to Groundwater > 100 Distance from nearest fresh water well	> 1000' Distance from nearest surface water > 1000'
	ls; Construction Material
12. Check Appropriate Box to Indicate Nature of No.	otice, Report or Other Data
	OUDOCOUENT DEDOCT OF
	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL	. WORK 🔲 ALTERING CASING 🗌
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE	. WORK ⊠ ALTERING CASING □ □ CE DRILLING OPNS.□ P AND A □
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE	. WORK 🔲 ALTERING CASING 🗌
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/C	. WORK ⊠ ALTERING CASING □ □ CE DRILLING OPNS.□ P AND A □
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PLUC OR ALTER CASING MULTIPLE COMPL OTHER:	. WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PLANS CASING/COMPLET OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details)	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CEDILLING OPNS. NOT THE PROPERTY OF T
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CEDILLING OPNS. NOT THE PROPERTY OF T
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PLANS CASING/COMPLET OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details)	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A CE DE
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET. 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion.	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET. 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABING.	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL COMMENCE PLANS COMMENCE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET. 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion.	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABING TO PRODUCTION 10-11-2006	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET. 13. Describe proposed or completed operations. (Clearly state all pertinent detay of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABING.	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABING TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SILEMENT JOB CE DRILLING OPNS. P AND A SILEMENT JOB P AND A SILEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABING TO PRODUCTION 10-11-2006	WORK ALTERING CASING CE DRILLING OPNS. P AND A EMENT JOB CE DRILLING OPNS. P AND A SILEMENT JOB CE DRILLING OPNS. P AND A SILEMENT JOB CE DRILLING OPNS. Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABINDATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE.	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB Sils, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABINDATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my known and the properties of the period of the pe	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SILE, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABINDATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE.	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SILE, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABINDATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SING, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET TITLE COMPL PLANS PROPERTY ABANDON CASING/COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMMENCE PULL OR ALTER CASING PULL TO PRODUCTION. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABD DATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per SIGNATURE TITLE Engineeric	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SING, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET TITLE COMPL PLANS PROPERTY ABANDON CASING/COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMMENCE PULL OR ALTER CASING PULL TO PRODUCTION. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABD DATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per SIGNATURE TITLE Engineeric	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SING, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006. Developed and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan. The property of the proposed completion or an (attached) alternative OCD-approved plan.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMPLET TITLE COMPL PLANS PROPERTY ABANDON CASING/COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMMENCE PULL OR ALTER CASING PULL TO PRODUCTION. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABD DATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per SIGNATURE TITLE Engineeric	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SING, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006. Developed and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan. The property of the proposed completion or an (attached) alternative OCD-approved plan.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMMENCE TO THER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABD DATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines , a general performance of print name: Thomas E. Mullins E-mail address: tom.mullins@synerger.	WORK ALTERING CASING DE DRILLING OPNS. PAND A DEMENT JOB DE JOB DEMENT JOB DE JOB D
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/COMMENCE TO THER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. SYNERGY RETURNED THIS WELL TO PRODUCTION, FOLLOWING SWABD DATE RETURNED TO PRODUCTION 10-11-2006 GAS SOLD 10 MCF CURRENT RATE BETWEEN 10 TO 50 MCFD. THE WELL IS NOW ACTIVE. I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines , a general performance of print name: Thomas E. Mullins E-mail address: tom.mullins@synerger.	WORK ALTERING CASING CE DRILLING OPNS. P AND A SEMENT JOB SILE, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion BING IT IN ON OCTOBER 11, 2006. Developed and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan. The property of the proposed completion or an (attached) alternative OCD-approved plan.

H