Form 3160- 5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM A	PPROVE
OMB No	1004- 013

OMB No	1004- 0137
Expires: Ma	arch 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

	Expires: March 31, 2007
Lease Serial No.	
NMSF - 078	3244

If Indian, Allottee, or Tribe Name

aDar.	luoneu wen. Use Form 5100-5 (Ar	D) for such proposals.	n/a_			
SUBMIT IN T	RIPLICATE - Other Instructions	on reverse side	7. If Unit or CA. Agreement Name and/or No.			
1. Type of Well		in the second	n/a			
Oil Well X Gas Well	Other	550 1 F 2007	8. Well Name and No.			
2. Name of Operator		DEC 172007	Shootist Federal 19 - 16			
Noble Energy, Inc.	,	Jurgan of Land Managemen	9. API Well No.			
3a. Address		3b - Rhone No. (include area code)	030 - 045 - 34280			
1625 Broadway, Suite	y, Suite 2200, Denver, CO 80202 303.228.4223		10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		Basin Fruitland Coal			
		11. County or Parish, State				
660 FSL, 660 FEL (SESE), "P", Section 19, T31N - R12W		San Juan County, New Mexico				
12. CHECK APPROI	PRIATE BOX(S) TO INDICATE I	NATURE OF NOTICE, REPOR	T, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Dee	pen Production ( S	tart/ Resume) Water Shut-off			
	Altering Casing Frac	cture Treat Reclamation	Well Integrity			
X Subsequent Report	Casing Repair Nev	v Construction Recomplete	X Other			
Change Plans Pl		g and abandon Temporarily A	bandon Cement and Casing Report			
Final Abandonment Notice	Convert to Injection Plug	g back Water Dispose	l			
13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof.						

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has

PLEASE SEE ATTACHMENT

OIL CONS. DIV.

RCVD DEC 20'07

DIST. 3

Please contact Joe Mazotti with any questions at 303.228.4223

determined that the site is ready for final inspection.)

(Instructions on page 2)

		Need Casing a ceren	Fin	dre
14. I hereby certify that the foregoing is true and correct.  Name (Printed/ Typed)  Joe Mazotti	Title	Regulatory Analyst		
Signature THIS SPACE FO	Date DR FED	12/12/2007  ERAL OR STATE OFFICE USE		AND FOR TAKE
Approved by	Title		Date	DEC 19 2007
Conditions of approval, if any are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subjection.	rant or			FARMINGTON FIELD OFFICE
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make States any false, fictitious or fraudulent statements or representations as to any matter			y to make	any department or agency of the United

## Noble Energy Inc PATINA Development Well OPERATOR -> NOBLE ENERGY, INC. SAN JUAN, CO County, State **PINPOINT** Well Contractor SHOOTIST FEDERAL 19-16 ID Drilling Rig 30-045-34280 **AFE Number** Event: 1 - DRILLING AFE Estimate Operated **Pros Name** SOC WI 0.0000000 **Pros Number** Proposed MD 2,584 SOC RI 0.0000000 Last Casing 9.625 @ 318 Purpose of Expenditure:

DOL: 4 MD:2.538 TVD:2,538 10/30/2007 Tue Rpt # 4 SUMMARY: PICK UP PIPE - MUD UP - CIRCULATE ON BOTTOM. TRIP. RIG UP LOGGERS - SAFETY MEETING - LOG -LOGGERS TD 2,520'. TRIP. LAY DOWN DRILL PIPE. RIG UP CASERS - SAFETY MEETING - RUN CASING. CIRCULATE CASING ON BOTTOM - RIG UP HALLIBURTON. SAFETY MEETING WITH HALLIBURTON - CEMENT - PUMPED 30% OVER CASLEPER LOGS NO CEMENT TO SURFACE - GOT ALL OF CHEMWASH BACK. NIPPLE DOWN - SET SLIPS -CUT OFF CASING - RIG DOWN - RIG RELEASED @ 3:30 AM 10-30-07. MD:2,538 DOL: 3 TVD:2,538 10/29/2007 Mon Rpt # 3 SUMMARY: DRILL FROM 760' TO 1409'. RIG SERVICE. DRILL FROM 1409' TO 2538'. CIRCULATE. RIG SERVICE. TRIP WAIT ON LOGGERS. RIG UP LOGGERS - LOGS STOPPED AT 850'. PICK UP 1 DRILL COLLAR AND PIPE - TAG 817'. WASH THROUGH BRIDGE - HOLE GETTING TIGHT - START MUD UP MD:760 TVD:760 10/28/2007 Sun Rpt # 2 DOL: 2 SUMMARY: DRILL FROM 170' TO 173'. SURVEY @173' - 1 DEG., DRILL FROM 173' TO 328'. CIRCULATE. TRIP. RIG JP CASERS - SAFETY MEETING - RUN CASING. SAFETY MEETING WITH HALLIBURTON - CEMENT. WOC. NIPPLE UP. TEST BOP. TRIP. DRILL PLUG AND CEMENT. CLEAN OUT FLOW LINE. DRILL FROM 328' TO 760' ..... Rpt#1 MD:170 TVD:170 10/27/2007 Sat DOL: 1 SUMMARY: MOVE AND RIG UP. PICK UP KELLY - MIX SPUD MUD. DRILL RAT AND MOUSE HOLE. DRILL SURFACE

Report Lole sizes

Late

Casing detail

Depth of casing

TOC