Bill Richardson

Joanna Prukop Cabinet Secretary Reese Fullerton Deputy Cabinet Secretary Mark Fesmire
Division Director
Oil Conservation Division



October 7, 2008

Sharon Zubrod
Burlington Resources Oil and Gas Company
PO Box 4289
Farmington, NM 87499

Re: Cooper 6, F, 6, 29N, 11W, API # 30-045-20518

Dear Ms. Zubrod:

The 2008 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 9, 2009. Initial Bradenhead psi of 24 was reported with a 5 minute shut in pressure of 9 psi.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement tops, and provide gas analysis from all casing strings.

Reference: RBDMS KGR0828162874 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly Roberts

Deputy Oil and Gas Inspector

District III - Aztec

CC: Well File

