Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

DEC 15 20 13 5. Lease Serial No. NMNM013642 SUNDRY NOTICES AND REPORTS ON WELLS reau of Land Man 6.16 Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter anglon Field Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other Gardner C5 2. Name of Operator Coronado energy E & P Company, LLC 9. API Well No. 30-045-28012 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 1099 18th St , Ste 1900, Denver, CO **Basin Fruitland Coal** 303-291-6400 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) S26, T32N, R9W 1680 FSL & 1010 FWL 11. Country or Parish, State San Juan, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) ☐ Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity ✓ Other Cleanout Well New Construction Casing Repair Recomplete ✓ Subsequent Report /Cavitate Change Plans Plug and Abandon Temporarily Abandon (Amended) Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 10/12/2008 MIRU. Pull rods and pump. Install BOP and test. POOH tbg. 10/13/2008 Clean out fill 3123'-3158'. 10/14/2008 Pooh 7 jts 5.5" liner, left 1 jt 5.5" liner in hole. 10/15/2008 Attempt to Fish. Fish @ 3100' - 3145'. Clean out well/cavitate. Heavy shale. 10/28/2008 Ream tight hole. Cavitate well. Heavy shale. 11/19/2008 Run 4 1/2" 11.6# N-80 liner w 4 aluminum plugs perf. Liner set @ 2804'-3100'. TIH w mill, tag aluminum plugs @ 2814'. Drill and knock off plugs to 2980' 11/20/2008 Tag and drill plugs 2980'-3052'. Drill on plugs 3055'. 11/24/2008 Drill plugs and clean out to 3100'. 11/25/2008 Land 2 3/8" J-55, 4.6# tbg @ 3090'. TIH new pump, 3 sinkers, 12 rods w/ guides, 110 3/4" regular rods & 2 pony rods. 11/26/2008 Return well to production. Release rig. RCVD DEC 30 '08 OIL COMS. DIV. DIST. 3 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Shanelle Deater Title Engineering Tech hanelle 1. Date 12/03/2008 Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by ACCEPTED FOR RECORD Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify DEC 19 2009 that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.