## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

FEB 1 1 2009

|  | Sundry Notices and Reports on Wells   | Bureau of Land Management Farmington Field Office  |   |
|--|---|--|---|
|  |   | 5.   | Lease Number  |
|  |   | ٥.   | NM-01051  |
| ı  | Type of Well  | 6.   | If Indian, All. or  |
|  | GAS   | 0.   | Tribe Name  |
|  | N CO  | 7.   | Unit Agreement Name   |
|  | Name of Operator BURLINGTON   |  |   |
|  | RESCURCES OIL & GAS COMPANY LP  |  | Huerfano Unit   |
|  | HESSISH SES OIL & GAS COMPANT LE  | <del></del> 8.   | Well Name & Number  |
|  | Address & Phone No. of Operator   | <del></del> o.   | Huerfano Unit 255S  |
| •  | Address & Fholie No. of Operator  |  | rideriano Unit 2555   |
|  | P.O. Box 4289, Farmington, NM 87499   | 9.   | API Well No.  |
| _  |   |  | 30-045-34682  |
| •  | Location of Well, Footage, Sec., T, R, M  | 10   | Field and Deal  |
|  | Unit M (SWSW), 230' FSL & 220' FWL, Section 31, T27N, R9W, NMPM Unit M (SWSW), 692' FSL & 704' FWL, Section 31, T27N, R9W, NMPM   | 10.  | Field and Pool<br>Basin Fruitland Coal  |
|  |   | 11.  | County and State<br>San Juan Co., NM  |
|  | X_ Subsequent Report Plugging Non-Routine Fracturing Water Shut off   |  | RCVD FEB 13 '09<br>OIL CONS. DIV  |
|  | Final Abandonment Altering Casing Conversion to Injection   |  |   |
| . <u>.</u>   |   |  |   |
| 9 1<br>30<br>43<br>.ci<br>36<br>au<br>34<br>IH       | Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  /08 MIRU BWWC W/L. Start into well w/3.75" gauge ring, tagged @ 2589'. Run GR/CCl 139'). TOC surface. NUWH, RD BWWC W/L. 1/22/09 PT 4 ½" csg to 4600# 30/min – gr 200' –2316' @ 1SPF = 16 holes, 2320' – 2324' @ 3SPF = 12 holes, 2328' – 2330' @ 3SPF = 32' – 2343' @ 2SPF = 4 holes. Total holes = 46. RD BWWC. 1/23/09 RU Schlumberger to id, pumped 2000 gal 25# X-Linked Pre-Pad followed by 29,752 gal 25# Linear 75% N2 Folion SCF N2. RD Schlumberger. 1/23/09 Begin flowback 1/24/09 Flowback well. 1/26/09 ge ring to 2000'. POOH. RU RIH w/CBP & set @ 2170'. Release W/L. 1/28/09 MIRU AV 10 mill & 2 3/8" tbg to CBP @ 2167'. D/O CBP @ 2167'. PU tbg tag fill @ 2570' C/O to He to PBTD, Blow/flow well. 2/2/09 TIH to PBTD, natural flow well. 2/3/09 Blow/flow well.  | ood test. 6<br>6 holes, 2<br>frac FC.<br>am w/96,<br>09 MIRU<br>WS 448. N<br>PBTD @ 2  | DIST. 3  om 2609' to surface (7" shoe EU BWWC.Perf FC .39" dia 2388' – 2396' @1SPF = 8 ho Acidize w/12 bbls 9% Form 2004 20/40 Brady Sand & W/L trk MU & RIH w w/3.8 ID WH NU BOP. 1/29/09 Pl 2607'. Blow well. 1/30/09                                 |
| ) 1<br>30<br>43<br>ci<br>36<br>14<br>34<br>IH<br>3/  | Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  /08 MIRU BWWC W/L. Start into well w/3.75" gauge ring, tagged @ 2589'. Run GR/CC 139'). TOC surface. NUWH, RD BWWC W/L. 1/22/09 PT 4 ½" csg to 4600# 30/min – go 00' –2316' @1SPF = 16 holes, 2320' – 2324' @ 3SPF = 12 holes, 2328' – 2330' @3SPF = 32' – 2343' @2SPF = 4 holes. Total holes = 46. RD BWWC. 1/23/09 RU Schlumberger to 16, pumped 2000 gal 25# X-Linked Pre-Pad followed by 29,752 gal 25# Linear 75% N2 Fo 165800 SCF N2. RD Schlumberger. 1/23/09 Begin flowback 1/24/09 Flowback well. 1/26/09 gering to 2000'. POOH. RU RIH w/CBP & set @ 2170'. Release W/L. 1/28/09 MIRU AV 16 mill & 2 3/8" tbg to CBP @ 2167'. D/O CBP @ 2167'. PU tbg tag fill @ 2570' C/O to H to PBTD, Blow/flow well. 2/2/09 TIH to PBTD, natural flow well. 2/3/09 Blow/flow well. 8" 4.7# J-55 tbg set @ 2428'. ND BOP, NU WH. RD RR. 15 hereby certify that the foregoing is true and correct.                                      | ood test. For the control of the con | om 2609' to surface (7" shoe EU BWWC.Perf FC .39" dia 2388' – 2396' @1SPF = 8 ho Acidize w/12 bbls 9% Form 200# 20/40 Brady Sand & W/L trk MU & RIH w w/3.8 ID WH NU BOP. 1/29/09 P 2607'. Blow well. 1/30/09 I w/mill. 2/4/09 RIH w/78 jts             |
| 9 1<br>30<br>43<br>43<br>36<br>34<br>1H<br>3/        | Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  /08 MIRU BWWC W/L. Start into well w/3.75" gauge ring, tagged @ 2589'. Run GR/CC 139'). TOC surface. NUWH, RD BWWC W/L. 1/22/09 PT 4 ½" csg to 4600# 30/min – go 00' –2316' @1SPF = 16 holes, 2320' – 2324' @ 3SPF = 12 holes, 2328' – 2330' @3SPF = 32' – 2343' @2SPF = 4 holes. Total holes = 46. RD BWWC. 1/23/09 RU Schlumberger to 16, pumped 2000 gal 25# X-Linked Pre-Pad followed by 29,752 gal 25# Linear 75% N2 Fo 165800 SCF N2. RD Schlumberger. 1/23/09 Begin flowback 1/24/09 Flowback well. 1/26/09 gering to 2000'. POOH. RU RIH w/CBP & set @ 2170'. Release W/L. 1/28/09 MIRU AV 16 mill & 2 3/8" tbg to CBP @ 2167'. D/O CBP @ 2167'. PU tbg tag fill @ 2570' C/O to H to PBTD, Blow/flow well. 2/2/09 TIH to PBTD, natural flow well. 2/3/09 Blow/flow well. 8" 4.7# J-55 tbg set @ 2428". ND BOP, NU WH. RD RR.  | ood test. For the control of the con | om 2609' to surface (7" shoe EU BWWC.Perf FC .39" dia 2388' – 2396' @1SPF = 8 ho Acidize w/12 bbls 9% Form 2000# 20/40 Brady Sand & W/L trk MU & RIH w w/3.8 ID WH NU BOP. 1/29/09 Pl 2607'. Blow well. 1/30/09 I w/mill. 2/4/09 RIH w/78 jts           |
| 9 1<br>30<br>43<br>ci-<br>36<br>au<br>34<br>IH<br>3/ | Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  /08 MIRU BWWC W/L. Start into well w/3.75" gauge ring, tagged @ 2589'. Run GR/CCl 139'). TOC surface. NUWH, RD BWWC W/L. 1/22/09 PT 4 ½" csg to 4600# 30/min – gc 00' –2316' @1SPF = 16 holes, 2320' – 2324' @ 3SPF = 12 holes, 2328' – 2330' @3SPF = 32' – 2343' @2SPF = 4 holes. Total holes = 46. RD BWWC. 1/23/09 RU Schlumberger to id, pumped 2000 gal 25# X-Linked Pre-Pad followed by 29,752 gal 25# Linear 75% N2 Folson SCF N2. RD Schlumberger. 1/23/09 Begin flowback 1/24/09 Flowback well. 1/26/09 gering to 2000'. POOH. RU RIH w/CBP & set @ 2170'. Release W/L. 1/28/09 MIRU AV 10 mill & 2 3/8" tbg to CBP @ 2167'. D/O CBP @ 2167'. PU tbg tag fill @ 2570' C/O to H to PBTD, Blow/flow well. 2/2/09 TIH to PBTD, natural flow well. 2/3/09 Blow/flow well. 3/4" J-55 tbg set @ 2428". ND BOP, NU WH. RD RR.  I hereby certify that the foregoing is true and correct.  Tracey N. Monroe  Title Staff Regulator. | ood test. For the control of the con | om 2609' to surface (7" shoe EU BWWC.Perf FC .39" dia 2388' – 2396' @1SPF = 8 ho Acidize w/12 bbls 9% Form 200# 20/40 Brady Sand & W/L trk MU & RIH w w/3.8 ID WH NU BOP. 1/29/09 P 2607'. Blow well. 1/30/09 I w/mill. 2/4/09 RIH w/78 jts             |
| 30<br>43<br>36<br>34<br>34<br>11<br>3/<br>4.         | Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  /08 MIRU BWWC W/L. Start into well w/3.75" gauge ring, tagged @ 2589'. Run GR/CC 139'). TOC surface. NUWH, RD BWWC W/L. 1/22/09 PT 4 ½" csg to 4600# 30/min – go 00' –2316' @1SPF = 16 holes, 2320' – 2324' @ 3SPF = 12 holes, 2328' – 2330' @3SPF = 32' – 2343' @2SPF = 4 holes. Total holes = 46. RD BWWC. 1/23/09 RU Schlumberger to 16, pumped 2000 gal 25# X-Linked Pre-Pad followed by 29,752 gal 25# Linear 75% N2 Fo 165800 SCF N2. RD Schlumberger. 1/23/09 Begin flowback 1/24/09 Flowback well. 1/26/09 gering to 2000'. POOH. RU RIH w/CBP & set @ 2170'. Release W/L. 1/28/09 MIRU AV 16 mill & 2 3/8" tbg to CBP @ 2167'. D/O CBP @ 2167'. PU tbg tag fill @ 2570' C/O to H to PBTD, Blow/flow well. 2/2/09 TIH to PBTD, natural flow well. 2/3/09 Blow/flow well. 8" 4.7# J-55 tbg set @ 2428'. ND BOP, NU WH. RD RR. 15 hereby certify that the foregoing is true and correct.                                      | ood test. For the control of the con | DIST. 3  om 2609' to surface (7" shoe EU BWWC.Perf FC .39" dia: 2388' – 2396' @1SPF = 8 ho Acidize w/12 bbls 9% Formi 200# 20/40 Brady Sand & W/L trk MU & RIH w w/3.8 ID WH NU BOP. 1/29/09 Pt 2607'. Blow well. 1/30/09 I w/mill. 2/4/09 RIH w/78 jts |

NMOCD

FEB 1 2 2009
FARMSHOTON FIELD OFFICE
BY T. SAVES