UNITED STATES

DEPARTMENT OF THE INTERIOR

		10		N	/[Γ	1
1	!	\S_{i}, I	1	13		1	j

	Gundara Wati and Danan	+ W-11-	* *****	·
	Sundry Notices and Repor	ts on wells	FA 1: 4	7
				ease Number
Type of Well		070 Farming	ica, Ni	F078505 f Indian, All. or
GAS		\	• • •	ribe Name
		Marie America		
Name of Orangham	· · · · · · · · · · · · · · · · · · ·		7. t	Init Agreement Name
Name of Operator	·	AN AN		
RESOURCE	OIL & GAS COMPANY	JAM Onne	3	
			୍ଞ 😿	Well Name & Number
Address & Phone No	<u> </u>			Seymour 8A
PO Box 4289, Farm	nington, NM 87499 (505)	326=9700		API Well No. 80-045-21759
Location of Well,	Footage, Sec., T, R, M		`~ y*	ield and Pool
1500'FsL,900'FeL,	Sec.14, T-31-N, R-9-W, N	MPM COLUMN	E	Blanco MV
				County and State
			2	an Juan Co, NM
	XOther T	Casing Conversion		
10/31/03 MIR 11/03/03 TIH	Ed or Completed Operation OU. TIH & set tbg plug @ OU. tag up @ 5806'. Blow we OU. TIH & Set tbg plug @ OU. TIH & Set	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH.
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	BTD @ 5	943'. TOOH. @ 5619', SN @ 561
10/31/03 MIR 11/03/03 TIH	CU. TIH & set tbg plug @	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg	ACCEPT	943'. TOOH. @ 5619', SN @ 561
10/31/03 MIR 11/03/03 TIH T N	CU. TIH & set tbg plug @	5650'. ND WH, NU BO ll & clean out to P #, J-55 8rd EUE tbg leased.	ACCEPT	943'. TOOH. @ 5619', SN @ 561
10/31/03 MIR 11/03/03 TIH T N	EU. TIH & set tbg plug @ tag up @ 5806'. Blow we PIH w/174 Jts 2 3/8", 4.7 ID BOP, NU WH. RD, Rig Re	5650'. ND WH, NU BO ll & clean out to P #, J-55 8rd EUE tbg leased.	ACCEPT DE	943'. TOOH. @ 5619', SN @ 561
10/31/03 MIR 11/03/03 TIH T N	tify that the foregoing is true and	5650'. ND WH, NU BO ll & clean out to P #, J-55 8rd EUE tbg leased.	ACCEPT DE	ED FOR RECORD C3 1 2003 TON FIELD OFFICE
10/31/03 MIR 11/03/03 TIH T N 14. I hereby cert gned	tify that the foregoing is true and all or State Office use)	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg leased. correct.	ACCEPT DE FARMING BY	ED FOR RECORD C3 1 2003 STON FIELD OFFICE
10/31/03 MIR 11/03/03 TIH T N 14. I hereby cert gned	tify that the foregoing is true and Title al or State Office use) Title	5650'. ND WH, NU BO 11 & clean out to P #, J-55 8rd EUE tbg leased. correct. Regulatory Assistan	ACCEPT DE FARMING BY t_Date	ED FOR RECORD C3 1 2003 STON FIELD OFFICE 12/18/03