


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-29367 OPERATOR Initial Report Final Report

Name of Company Williams Production	Contact Michael K. Lane
Address PO Box 640	Telephone No. 505-634-4219
Facility Name Rosa 383	Facility Type Well Site

Surface Owner USFS	Mineral Owner BLM	Lease No.
---------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter P	Section 29	Township 31 N	Range 04W	Feet from the 1045	North/South Line FSL	Feet from the 1110	East/West Line FEL	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200 bbl	Volume Recovered
Source of Release Drill rig return hose cut hole in pit liner	Date and Hour of Occurrence after 5/30/06 15:00 PM	Date and Hour of Discovery 5/31/06 6:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brennan Powell: NMOCD & JJ Miller: USFS	
By Whom? Myke Lane, WPX	Date and Hour 5/31/06 10:00 AM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.

Return hose on drill rig washed a hole in the pit liner during night tour, allowing drilling returns to drain under liner. Energy dissipation devise moved allowing hose to discharge directly on liner material. Corrective measures include inspection of hose during drilling, securing the energy dissipater, and liner reinforcement where possible. Drill rig being rigged down. Liner will be repaired as needed for completion rig.

Describe Area Affected and Cleanup Action Taken.

Pit will be closed in accordance to approved procedures following completion of well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor:	For: Charlie Perrin
Title: SJB EH&S Specialist	Approval Date: 5/31/06	Expiration Date:
E-mail Address: myke.lane@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/31/06 Phone: (505) 330-3198		

* Attach Additional Sheets If Necessary

u BP 0615137557