


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30-039-29908

OPERATOR

Name of Company Williams Production	Contact Michael K. Lane	
Address PO Box 640	Telephone No. 505-634-4219	
Facility Name Rosa 312A	Facility Type Well Site	
Surface Owner USFS	Mineral Owner BLM	Lease No.

LOCATION OF RELEASE

Unit Letter E	Section 28	Township 31 N	Range 04W	Feet from the 2060	North/South Line FNL	Feet from the 1050	East/West Line FWL	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Drilling fluids w/produced water	Volume of Release >25 bbl	Volume Recovered ~25 bbl
Source of Release Drilling Pit	Date and Hour of Occurrence 8/4/06 ~23:20 PM	Date and Hour of Discovery 8/4/06 ~23:20 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell: NMOCD & John Ridenger: USFS	
By Whom? Roxanne Roberts, WPX	Date and Hour 8/5/06 ~10:30 AM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.

Heavy rains saturated liner anchor and liner pulled away allowing some pit fluids to collect under liner. Immediately removed drilling fluids to level below top of liner, used vac trucks to pull liquids under liner. Liner repaired and change to fresh water for remainder of drilling operations.

Describe Area Affected and Cleanup Action Taken.

Following completion of drilling operations liner to be removed and reinstalled. Soil samples to be taken to determine impact.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor: For: Charlie Perrin	
Title: SJB EH&S Specialist	Approval Date: 8/15/06	Expiration Date:
E-mail Address: myke.lane@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/15/06 Phone: (505) 330-3198		

* Attach Additional Sheets If Necessary

n 890623429218