

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-32414

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Kyle Beebe
Address 1751 HWY 511, Navajo Dam, NM 87401	Telephone No. (505)-486-0060
Facility Name N.E.B.U. 490-A	Facility Type Well location

Surface Owner Federal	Mineral Owner Federal	Lease No. N.E.B.U. 490A
-----------------------	-----------------------	-------------------------

LOCATION OF RELEASE

Unit Letter P	Section 14	Township 31-N	Range 7-W	Feet from the 780'	North/South Line South	Feet from the 660'	East/West Line East	County San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude 36° 53' 40" N Longitude 107° 32' 01" W

NATURE OF RELEASE

Type of Release Diesel Spill	Volume of Release 10 BBLS	Volume Recovered 0 BBLS
Source of Release Day tank	Date and Hour of Occurrence 11/14/07	Date and Hour of Discovery 11/14/07 7:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD NOV 19'07

If a Watercourse was Impacted, Describe Fully.*

**OIL CONS. DIV.
DIST. 3**

Describe Cause of Problem and Remedial Action Taken.*

The diesel generator day tank was disconnected from the generator when it was empty so it could run off the trailer tank on the unit. When the tank was filled it was turned back on before the lines were reconnected and the diesel spilled into the generator and when the pan overflowed it spilled on to the ground. Once discovered cleanup procedures were started.

Describe Area Affected and Cleanup Action Taken.*

The area affected was the well location below the generator and tank. The cleanup was removed and testing of the soil. Contacted Envirotech to test and cleanup. Representative Juli Thompson (505)-793-5392.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerrid Brann</i>		OIL CONSERVATION DIVISION	
Printed Name: Jerrid Brann		Approved by District Supervisor: <i>Brandon Roll</i> For: <i>Charlie Perrin</i>	
Title: Lease Operator		Approval Date: 11/19/07	Expiration Date:
E-mail Address: jerrid.brann@devn.com		Conditions of Approval:	
Date: 11/14/07 Phone: (505)-486-3333		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

n8P0734040949