P.O. B. 1940 Hobbs, N. 88241-1980 District II - (505) 748-1283 811 South First Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 2040 South Pacheco Street

Santa Fe, New Mexico 87505 (505) 827-7131

Form C- 141 Originated 2/13/9

Appropriate District Office in accordance. with Rule 116

District IV · (505) 827-7131			
Release Notification	and Corrective Action	A Secretaria de Companyo de Co	28 280.00 Per 200
	ERATOR	Initial Report	Final Report
Name BC&D OPERATing, Inc.	Contact	Hill	
Address P. O. Box 1680, Hobbs, pm 88.	Telephone No. /	-3912 /50	5-330 3895
Facility Name HOSPAH Sand Unit #13	Facility Type WELL PAD	,	
Surface Owner BCED Dil and Gas Coff Valio	us Individuals	Lease No.	
LOCATION OF RELEASE			
Unit Letter Section Township Range Feet from the North/Seach Lin F 1 7/1N R9W 2600 NORTH	LIPSTI	mckinley,	<i>hm</i>
NATURE OF RELEASE			
Type of Release 29- FRESH WGTER & 1/2 bbl. oil	Volume of Release 29 1/2 666s	Volume Recovere 29 To	as bbls.
Source of Release	Date and Hour of Occurrence	Date and Hour of	Discovery
Was Immediate Notice Given? Yes No Not Required	If YES, To Whom?		
By Whom?	Date and Hour		
Was a Watercourse Reached? Yes No	If YES, Volume Impacting the	Watercourse.	
If a Watercourse was Impacted, Describe Fully.*			vi -
		The the	
Describe Cause of Problem and Remedial Action Taken * FLOW Line Legk - SEE ATTachment		NOV 2001 RECEIVED OIL CON. DRV	SS 35178
Describe Area Affected and Cleanup Action Taken."		9-67. 3	J
SEE ATTachment	- '	Eggt Edul	
Describe General Conditions Prevailing (Temperature, Precipitation, etc.).*			
CLEAR-30° no Rain			
I hereby certify that the information given above is true and complete to the best of my knowledge and belief.	OU. CONSE	RVATION DIVISION	
Printed Name: Donnie Hill	Approved by a coested District Supervisor Demny	Fourt Vecora	, , , , , , , , , , , , , , , , , , ,
Tide: PRESident	Approval Date: 1//20/0	Expiration Date:	, , , , , , , , , , , , , , , , , , ,
Date: 11/19/01 Phone 505-397-3972	, Conditions of Approval: Note 13	Bruce Attached	
Attach Additional Sheets If Necessary	Mustin Report		<u></u>

Martin Reporti MDGF0132454742

CAUSE OF PROBLEM AND REMEDIAL ACTION TAKEN

FLOW LINE LEAK ALLOWING APP. 29 BBLS OF FRESH WATER AND 1/2 BBL OF OIL TO BE SPILLED ON SURFACE. FLOW LINE WAS REPAIRED.

AREA AFFECTED AND CLEANUP ACTION TAKEN

AN AREA OF 30 FEET X 50 FEET WAS AFFECTED BY SPILL VERY LITTLE VEGETATION EXIST IN THE AREA AFFECTED. SOIL IS BEING PICKED UP WITH BACKHOE, CLEAN SOIL IS REPLACING THE SOIL REMOVED AND WILL BE RESEEDED WITH NATIVE GRASS. DUE TO THE WATER BEING FRESH MINIMAL IMPACT IS EXPECTED. SOIL IS BEING PLACED ON WELL PAD IN A 6 INCH LAYER AND WILL BE DISC WITH FERTILIZER UNTIL REMEDIATED.