RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCT 14 2010

	Bureau	ington Field Office of Land Managemen
		Lease Number
	5.	14-20-603-769
1. Type of Well	6.	If Indian, All. or
GAS .	0.	Tribe Name
GNS .	•	NAVAJO
	~	
2. Name of Operator	7.	Unit Agreement Name
2. Name of Operator		
BURLINGTON		
RESOURCES OIL & GAS COMPANY LP		***
	8.	Well Name & Number
3. Address & Phone No. of Operator		GE-ELE-GU-LITHE-E 500S
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
1 0 Box 1207, 1 animington, 1111 0 1175 (300) 320 5700	· ·	ALL WERTO.
A K A CANADA CANADA		30-045-34763
4. Location of Well, Footage, Sec., T, R, M	10.	Field and Dool
Surface: Unit C (NE/NW), 915' FNL & 1775' FWL, Section 7, T26N, R8W, NMPM		Field and Pool BASIN FRUITLAND COAL
Surface. Ont C (14E/1144), 513 FILE & 1773 F WD, Section 7, 12011, Row, 14011 W		
	11.	County and State
		San Juan, NM
Type of Submission Notice of Intent Notice of Intent Recompletion Type of Action Abandonment Recompletion Change of Plans New Construction	<u>x</u>	Other - Spud Report
X Subsequent Report Plugging Non-Routine Fracturin	~	RCVD OCT 28'10
Casing Repair Water Shut off	Б	OTL CONS. DIV.
	•	
Final Abandonment Altering Casing Conversion to Injection	1	DIST. 3
	n	
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations		DIST. 3
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2/2	33'. Cìrc. h	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2: 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2/2 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report.	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2.55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2.55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2/2 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report.	33'. Circ. h 20% Flya	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 22 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct.	33'. Circ. h 20% Flya 2/10. ✓	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J- sh. Dropped plug & displaced
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 22 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct.	33'. Circ. h 20% Flya 2/10. ✓	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J-
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2/2 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct. Signed Marie E. Jaramillo Title: Staff	33'. Circ. h 20% Flya 2/10. ✓	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J- sh. Dropped plug & displaced
Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2:55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct. Signed Marie E. Jaramillo Title: Staff (This space for Federal or State Office use)	33'. Circ. h 20% Flya 2/10. ✓	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J- sh. Dropped plug & displaced
Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2:55 ST&C @ 228'. RU to cmt. Pumped w/8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct. Signed Marie E. Jaramillo Title: Staff (This space for Federal or State Office use)	33'. Circ. h 20% Flya 2/10. ✓	DIST. 3 ole & RIH w/ 7 jts, 7", 20#, J- sh. Dropped plug & displaced
Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 10/12/10 MIRU MOTE 212. Spud w/ 8 3/4" bit @ 08:30hrs on 10/12/10. Drilled ahead to 2: 55 ST&C @ 228'. RU to cmt. Pumped w/ 8bbls FW spacer. Pumped Lead 51sx(82cf-15bbls) w/7bbls FW. Circ. 6bbls cmt to surface. RD cmt. WOC. ND BOPE. RD RR @ 17:00hrs 10/1 PT will be conducted by Drilling Rig. Results will appear on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct. Signed Marie E. Jaramillo Title: Staff (This space for Federal or State Office use)	33'. Circ. h 20% Flya 2/10. ✓	ole & RIH w/ 7 jts, 7", 20#, J-sh. Dropped plug & displaced / Technician Date 10/13/10

ACCEPTED FOR RECORD

OCT 2 5 2010

FARMINGTON FIELD OFFICE BY TL Solvers