

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479	
Facility Name: Schwerdtfeger B 3	Facility Type: Natural Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. NM 013685

LOCATION OF RELEASE

Unit Letter M	Section 27	Township T31N	Range R9W	Feet from the 1120	North/South Line South	Feet from the 810	East/West Line West	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------------

Latitude 36.86503 Longitude 107.77414

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 91 Mcf	Volume Recovered: none
Source of Release: partially open ball valve on compressor skid	Date and Hour of Occurrence: 6:00 PM, 6/13/10	Date and Hour of Discovery: 8:30 AM, 6/14/10
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <div style="text-align: right;">RCVD JUN 21 '10 OIL CONS. DIV. DIST. 3</div>		
Describe Cause of Problem and Remedial Action Taken.* A ball valve on the compressor blow down line was found to be in the partially open position and leaking gas. The valve handle was either kicked or bumped by a cow, which opened the valve. The valve was closed and the handle was removed to prevent this from happening again.		
Describe Area Affected and Cleanup Action Taken.* The natural gas lost through the ball valve dissipated into the air surrounding the compressor. No clean up action was possible.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Jeffrey H. Peace</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeffrey H. Peace	Approved by District Supervisor: <i>Branch Fall</i> For: CP	
Title: HSE Advisor	Approval Date: 9/22/10	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 17, 2010	Phone: 326-9479	

* Attach Additional Sheets If Necessary

nBP1026535861